

DISTRICT CONSERVATION AGENT'S REPORT

TO:

State Corporation Commission
Conservation Division
211 North Broadway
Wichita, Kansas

FILE NO. _____

LOCATION NW-NE

SEC. 28 TWP. 29 RGE. 43W

Dry Hole X Abandoned Oil Well _____ Abandoned Gas Well _____

I have this date completed supervision of plugging of:

Well No. 1 Lease Stewart "E" Unit

Operator Cordewon-Richard Oil Co. Address Box 142 Kismet Band Kansas

Field _____ County Stanton

Total Depth 5554 Feet.

Plugging Contractor Mutrag Dalgico

Plugging Contractor's License No. DB

Address Phalins, Texas.

(Describe Briefly the manner in which the well was plugged)

8 1/2" 1594' C.W.C. shot 35' 4" cement at 4950'

Mud to 35' set Plug cement to face of collar

Cement Pumped by Galpura Cementing Co

M. L. Rivers
District Conservation Agent

Date 3-2-57

Allen McCreider
DEI.

PLUGGING
FILE SEC. 28 T. 29 R. 43W
BOOK PAGE 144 LINE 40

RECEIVED
STATE CORPORATION COMMISSION
MAR 4 - 1957
CONSERVATION DIVISION
Wichita, Kansas

Allen M. Sieder

Mr Jack Mc Ginnis who is in charge of this well for the Co. Called me 2-26-57 about plugging this well. I suggested the cement of any formation at the bottom of the hole if they had any showing of oil or Gas. Then fill the hole to 600' set a Plug and 35' of cement, heavy mud to 35' set Plug and cement to base of cellar. He is now up here and Milder stood me when I told him when he pulled his drill pipe. to stand back 600' then shoot a Plug and Run 35' of cement through the drill pipe. I told him we merely gave permission and suggestions as to how to Plug Wells. And I was accepting the plugging of this well under those circumstances. As they did not set a fresh water Plug we assumed no responsibility.

Rives

P.S. Mr Mc Ginnis said they tested the surface hole for water while drilling and found no water sand only at 590' feet it was dry. And under the circumstances I see no reason that this well should ever give any trouble.

M. L. Rives

The reason for suggesting this amount of cement is. Halperton charge for 60' of whatever used or not when they furnish the cement.