

KANSAS  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION AGENT'S REPORT

RECEIVED  
STATE CORPORATION COMMISSION  
FEB 26 1962  
CONSERVATION DIVISION  
Wichita, Kansas

TO:  
J. P. Roberts  
Assistant Director  
500 Insurance Building  
212 North Market  
Wichita 2, Kansas

File No. \_\_\_\_\_ County: Haskell

Location: SE NW Sec. 33 Twp. 29 Rge. 34 (E) \_\_\_\_\_ (W)

Name of Field: \_\_\_\_\_ Total Depth: 5306

I have this date completed supervision of plugging of:

Lease Name: Kirkpatrick Well No. 6

Operator's Full Name: United Producing Co

Complete Address: Drewes 30, Liberal Kan

Plugging Contractor: Toland & Reeves Pipe Fitting Co

Address: Oklahoma City Okla License No. 346

Oil Well  Gas Well \_\_\_\_\_ Input Well \_\_\_\_\_ SWD Well \_\_\_\_\_ D & A \_\_\_\_\_

Other well as hereafter indicated: \_\_\_\_\_

Was any delay in plugging operations caused by Conservation Division Agent?

Yes \_\_\_\_\_ No

If yes how long? \_\_\_\_\_ Reason: \_\_\_\_\_

Operation Completed: Hour 4pm Day 14 Month 2 Year 1962

The above well was plugged as follows:

1832' of 8 1/2" pipe casing 35 sack cement pumped  
on bottom to 4000'. Hole filled to 685' with heavy  
mud. 35 sack cement spotted from 685' to 600'.  
Hole mudded to 35'. Cement spotted from 35'  
to base of collar - Cementing by Halliburton  
Cementing Co.

Signed: [Signature]  
Conservation Division Agent

Reviewed: [Signature]  
Field Supervisor

Remarks:

INVOICED  
DATE 3/5/62  
INV. NO. 4599-11

WELL LOG BUREAU—KANSAS GEOLOGICAL SOCIETY  
508 East Murdock, Wichita, Kansas


COPY

Company- UNITED PRODUCING CO.  
Farm- Kirkpatrick No. 6

SEC. 33 T. 29 R. 34W  
C SE NW

Total Depth. 5505'  
Comm. 4-12-61 Comp. 4-22-61  
Shot or Treated.  
Contractor. R. W. Rine  
Issued. 8-5-61

County Haskell  
KANSAS



Elevation. 2989' DF

Production. Dry

Figures Indicate Bottom of Formations.

COMPLETE DRILLERS LOG NOT AVAILABLE:

TOPS: ELECTRIC  
Lansing 4104  
Kansas City "A" 4550  
Marmaton Pay 4751  
Morrow 5214  
Chester Sand 5414  
Merimac 5418

DST #1 5335-54 Misrun

DST #2 5341-5412 op 4 min, packer failed  
rec. 2160' GCM

Rotary Total Depth 5505