	· ·	497 NUMBER 48 (VIII 21) 62/mm.63/61616
To: STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING SECTI 200 COLORADO DERBY BUILDING WICHITA, KANSAS 67202		API NUMBER 15- 191-,20,527-000 C SW NW, SEC. 7 , 7 33 s, R 1 W/3 3300 feet from Section line
TECHNICIAN'S PLUGGING REPORT		
Operator License # 4549		Lease NameCornelson Weil gA-1
Operator: Anadarko Petroleum Corp.		- :
	P.O. Box 351	
		Well Total Depth 4375 fee
	Liberal, KS 67905	
		Surface Casing: Size 8 5/8 feet 391
		Input Well D&A
		
Plugging	Contractor Sargent Casing Pul	ling License Number 6547
Address	Liberal, KS	· · · · · · · · · · · · · · · · · · ·
		Month: Year:19
Plugging	proposal received fromD	oug
		ng (phone)
were:		
4½ 43		Cmt plug to 4000'
Perf 42	37-42. 50	O' Cmt plug to 330' 007 2 3 1989
•	40	O' Cmt plug to O' Wichia, Kanegs
	· · · · · · · · · · · · · · · · · · ·	WIGHTS, Kanegs
	Plugaina Pr	oposal Received by Steve Van Geison
		(TECHNICIAN)
Plugging	Operations attended by Agent?:	All Part X None
Operation	s Completed: Hour: 13:30 Day	r: 8 Month: 10 Year:19 89
	UGGING REPORT The perfs we pluc	ged by pumping 20 sx of cmt & 1 sx of hulls to
ACTUAL PL		75
	· -	
4000'.	The 4½" casing was recovered fr	
4000'.	The 4½" casing was recovered fr	com 2425'. The $4\frac{1}{2}$ " was pulled to 480' where 50 sx casing to 40' and circ to surface with 10 sx of
4000'.	The 4½" casing was recovered frwas spotted in place. The 4½" g	com 2425'. The $4\frac{1}{2}$ " was pulled to 480' where 50 sx casing to 40' and circ to surface with 10 sx of
4000'.	The 4½" casing was recovered frwas spotted in place. The 4½" g	com 2425'. The $4\frac{1}{2}$ " was pulled to 480' where 50 sx casing to 40' and circ to surface with 10 sx of
of cmt cmt. The	The 4½" casing was recovered fr was spotted in place. The 4½" c e 4½" remaining the hole was re	rom 2425'. The 4½" was pulled to 480' where 50 sx casing to 40' and circ to surface with 10 sx of ecovered & layed out.
4000'. of cmt cmt. The	The 4½" casing was recovered from was spotted in place. The 4½" control of the hole was recommon cmt. Bought from lumber y	rom 2425'. The $4\frac{1}{2}$ " was pulled to 480' where 50 sx casing to 40' and circ to surface with 10 sx of ecovered & layed out.
of cmt cmt. The	The 4½" casing was recovered from was spotted in place. The 4½" control of the hole was recommon cmt. Bought from lumber y	casing to 40' and circ to surface with 10 sx of ecovered & layed out.
of cmt cmt. The	The 4½" casing was recovered from the 4½" casing was spotted in place. The 4½" casing the hole was recovered from lumber you can be additional description	rom 2425'. The 4½" was pulled to 480' where 50 sx casing to 40' and circ to surface with 10 sx of ecovered & layed out. Vard in Wellington. Is necessary, use BACK of this form.)
4000'. of cmt cmt. The	The 4½" casing was recovered from spotted in place. The 4½" of the 4½" remaining the hole was recommon cmt. Bought from lumber of the additional description construction observe this plugging.	rom 2425'. The 4½" was pulled to 480' where 50 sx casing to 40' and circ to surface with 10 sx of ecovered & layed out. Vard in Wellington. Is necessary, use BACK of this form.)