	API Well	Number: <u>15-12</u>	21-026	5-00	<u> </u>			
Kansas Corporation Commission	Spot: <u>NE</u>				<u>16</u> S	Rng 21 VE/W		
	5040			Feet	from 🗌	N/ S Line of Section		
District Plugging Report	1837			Feet		E / W Line of Section		
		38.621809 Tarr II	Long: <u>_95.0</u>	34749		ate: <u>12/2/14</u> 8/8/13		
				Total V		11#: 12-6 (T-12Ce)		
	County: N				ertical De	<u> </u>		
Operator License No: 101		String	Size	Depth	Pulled	Comments		
Op Name: STATE OF KANSAS		VE - Drive Pipe	10,000	<u>15</u>	0	EST.		
Address 1: 266 N. Main St. Stc. 220 Address 2:		Tubing ! R - Packer	2.000	700	540	EST.		
Address 2:City: WICHITA	<u> FKI</u>	C - Facker	1.000	540	<u>540</u>			
State: KS Zip Code: 67202 - 1513		-						
	<u> </u>					 .		
Well Type: OG - Oil & Gas (OIL)		Docket No.:	-			10/20/14 //		
Plug Co License No.: 33749		Co. Name: KEPL	<u>EY WELL SER</u>	VICE, LL	<u>C</u>			
Proposal Revel from: Milhe Keptey	Com	pany Name: KWS			<u> </u>	Phone: (620) 431-8945		
Plugging Proposal Received By: Frank C	in fagle		Witness T	ype: <u>CO</u>	MP - Com	plete 100%		
Date/Time Plugging Completed: 10/20/14	V	C Agent: <u>Frank Guil</u>	foyle					
Actual Plugging Report:			Perfs:	Top	Botton	n Thru		
Move equipment to location. Run 1" and pull loose. Pull 10 joints of 1" out again. Work on it and got loose. Pull of	Run 1" and tap b	ack. Screw into	1"					
1" back to 540 ft inside 2". Run 1" to 200 ft outside 2" and hit mud. Wash 1" to								
510 ft outside 2". Pump Portland cement to surface inside and outside 2". Pull pipe and top off well. Pump total of 210 sacks of cement. Well plugged.						<u> </u>		
pipe and top off well. Pump total of 2	TO sacks of cemen	. well plugged	•			<u> </u>		
					-	- · · · · · · · · · · · · · · · · · · ·		
	·							
Contract # 39389. Control # 20	0140052-010. Reg	ular section. GF	S'ed by FG	in NAI	O 83. Ca	ategory II.		
Plugged Thru: TBG - Tubing				ged Due to	Complia	nce Issue: Yes No		
District: 03	C WICHITA	Frank	Die	Burt				
	N 05 2015	•			Porm: District Plugging Report –			

RECEIVED