	end to the second of the secon	12-8-87 15-047-70659-8000
io:	¹ 061045	API NUMBER 15-Drill completion date 5/19/80
	PORATION COMMISSION ION DIVISION - PLUGGING SECTION	SE NE SW , SEC. 8 , T 26 S, R 16 W/E
_ • •	ADO DERBY BUILDING KANSAS 67202	1650 feet from S section line
	N'S PLUGGING REPORT	2970 feet from E section line
	License # 5992	Loase NameWelsch Well # 2
•	Patton Oil Company	County Edwards 145.11
Name&	• • • • • • • • • • • • • • • • • • • •	•
	672 West 4th Street Hoisington, KS 67544	· · · · · · · · · · · · · · · · · · ·
	norsingeon, Rb 07344	Conductor Pipe: Size feet
		•
Abandoned	Oll Well X Gas Well	Input Well D&A
Other wel	í as hereinafter indicated	
Plugging	Contractor Kelso Casing Pulling	, Inc. 6050
	P.O. Box 347, Chase, KS 67524	
		8 Month: 12 Year: 19 87
	proposal received from Bill Full	
	name, Kerso Casing Fulling, Inc.	(phone) 316-938-2457
	5½" at 4462' PBTD 4467' Open ho	
		le from 4462-4467' x cement on top of sand through bailer,
lst plug	g sand back to 4410 and dump 5 s	x cement on top of sand through bailer,
lst plug	g sand back to 4410 and dump 5 s	x cement on top of sand through bailer,
1st plug	g sand back to 4410' and dump 5 s	x cement on top of sand through bailer,
1st plug	g sand back to 4410' and dump 5 s g pump 4 sx hulls, 10 sx gel, 50 lug and pump 120 sx cement.	x cement on top of sand through bailer, sx cement, 10 sx gel, 1 sx hulls, release 8 5/8' posal Received by Richard Lacey
1st plug 2nd plug wiper p	g sand back to 4410' and dump 5 s g pump 4 sx hulls, 10 sx gel, 50 lug and pump 120 sx cement. Plugging Pro	x cement on top of sand through bailer, sx cement, 10 sx gel, 1 sx hulls, release 8 5/8' posal Received by Richard Lacey (TECHNICIAN)
1st plug 2nd plug wiper p	g sand back to 4410' and dump 5 s g pump 4 sx hulls, 10 sx gel, 50 lug and pump 120 sx cement. Plugging Pro	x cement on top of sand through bailer, sx cement, 10 sx gel, 1 sx hulls, release 8 5/8' posal Received by Richard Lacey
lst plug 2nd plug wiper pl	g sand back to 4410' and dump 5 s g pump 4 sx hulls, 10 sx gel, 50 lug and pump 120 sx cement. Plugging Pro Operations attended by Agent?:	x cement on top of sand through bailer, sx cement, 10 sx gel, 1 sx hulls, release 8 5/8' posal Received by Richard Lacey (TECHNICIAN)
1st plus 2nd plus wiper p	g sand back to 4410' and dump 5 s g pump 4 sx hulls, 10 sx gel, 50 lug and pump 120 sx cement. Plugging Pro Operations attended by Agent?: as Completed: Hour: 1:20 p.mbay:	x cement on top of sand through bailer, sx cement, 10 sx gel, 1 sx hulls, release 8 5/8' posal Received by Richard Lacey (TECHNICIAN) All X Part None 8 Month: 12 Year:19 87
1st plus 2nd plus wiper p Plugging Operation	g sand back to 4410' and dump 5 s g pump 4 sx hulls, 10 sx gel, 50 lug and pump 120 sx cement. Plugging Pro Operations attended by Agent?: as Completed: Hour: 1:20 p.mbay:	x cement on top of sand through bailer, sx cement, 10 sx gel, 1 sx hulls, release 8 5/8' posal Received by Richard Lacey (TECHNICIAN) All X Part None 8 Month: 12 Year:19 87
1st plus 2nd plus wiper p Plugging Operation ACTUAL PL through	g sand back to 4410' and dump 5 s g pump 4 sx hulls, 10 sx gel, 50 lug and pump 120 sx cement. Plugging Pro Operations attended by Agent?: as Completed: Hour: 1:20 p.mbay: UGGING REPORT 1st plug sanded b bailer,	x cement on top of sand through bailer, sx cement, 10 sx gel, 1 sx hulls, release 8 5/8' posal Received by Richard Lacey (TECHNICIAN) All X Part None 8 Month: 12 Year:19 87
2nd plus 2nd plus wiper p Plugging Operation ACTUAL PL through	g sand back to 4410' and dump 5 s g pump 4 sx hulls, 10 sx gel, 50 lug and pump 120 sx cement. Plugging Pro Operations attended by Agent?: as Completed: Hour: 1:20 p.mbay: UGGING REPORT 1st plug sanded b bailer,	x cement on top of sand through bailer, sx cement, 10 sx gel, 1 sx hulls, release 8 5/8' posal Received by Richard Lacey (TECHNICIAN) All X Part None 8 Month: 12 Year:19 87 ack to 4410' and dumped 5 sx cement on top of sand top o
1st plus 2nd plus wiper p Plugging Operation ACTUAL PL through 2nd plus	g sand back to 4410' and dump 5 s g pump 4 sx hulls, 10 sx gel, 50 lug and pump 120 sx cement. Plugging Pro Operations attended by Agent?: as Completed: Hour: 1:20 p.mbay: UGGING REPORT 1st plug sanded b bailer, g pumped 4 sx hulls, 10 sx gel, 5	x cement on top of sand through bailer, sx cement, 10 sx gel, 1 sx hulls, release 8 5/8' posal Received by Richard Lacey (TECHNICIAN) Al! X Part None 8 Month: 12 Year:19 87 ack to 4410' and dumped 5 sx cement on top of sand contact of the sa
1st plus 2nd plus wiper p Plugging Operation ACTUAL PL through 2nd plus 8 5/8" v	g sand back to 4410' and dump 5 s g pump 4 sx hulls, 10 sx gel, 50 lug and pump 120 sx cement. Plugging Pro Operations attended by Agent?: as Completed: Hour: 1:20 p.mDay: UGGING REPORT 1st plug sanded b bailer, g pumped 4 sx hulls, 10 sx gel, 5 wiper plug and pumped 120 sx ceme	x cement on top of sand through bailer, sx cement, 10 sx gel, 1 sx hulls, release 8 5/8' posal Received by Richard Lacey (TECHNICIAN) All X Part None 8 Month: 12 Year:19 87 ack to 4410' and dumped 5 sx cement on top of sand to 4410' and dumped 5 sx cement
1st plus 2nd plus wiper p Plugging Operation ACTUAL PL through 2nd plus 8 5/8" v	g sand back to 4410' and dump 5 s g pump 4 sx hulls, 10 sx gel, 50 lug and pump 120 sx cement. Plugging Pro Operations attended by Agent?: as Compteted: Hour: 1:20 p.mbay: UGGING REPORT 1st plug sanded b bailer, g pumped 4 sx hulls, 10 sx gel, 5 wiper plug and pumped 120 sx ceme pressure 400 psi and shut in 200	x cement on top of sand through bailer, sx cement, 10 sx gel, 1 sx hulls, release 8 5/8' posal Received by Richard Lacey (TECHNICIAN) Ali x Part None 8
2nd plus 2nd plus wiper p Plugging Operation ACTUAL PL through 2nd plus 8 5/8" v	g sand back to 4410' and dump 5 s g pump 4 sx hulls, 10 sx gel, 50 lug and pump 120 sx cement. Plugging Pro Operations attended by Agent?: as Completed: Hour: 1:20 p.mDay: UGGING REPORT 1st plug sanded b bailer, g pumped 4 sx hulls, 10 sx gel, 5 wiper plug and pumped 120 sx ceme pressure 400 psi and shut in 200	x cement on top of sand through bailer, sx cement, 10 sx gel, 1 sx hulls, release 8 5/8' posal Received by Richard Lacey (TECHNICIAN) All X Part None 8 Month: 12 Year: 19 87 ack to 4410' and dumped 5 sx cement on top of sand to 4410' and dumped 5 sx cement on top of sand top o
Ist plus 2nd plus wiper p Plugging Operation ACTUAL PL through 2nd plus 8 5/8" v	g sand back to 4410' and dump 5 s g pump 4 sx hulls, 10 sx gel, 50 lug and pump 120 sx cement. Plugging Pro Operations attended by Agent?: as Compteted: Hour: 1:20 p.mbay: UGGING REPORT 1st plug sanded b bailer, g pumped 4 sx hulls, 10 sx gel, 5 wiper plug and pumped 120 sx ceme pressure 400 psi and shut in 200 Used 60/40 Pozmix 6% gel by Alli (If additional description I	x cement on top of sand through bailer, sx cement, 10 sx gel, 1 sx hulls, release 8 5/8' posal Received by Richard Lacey (TECHNICIAN) All X Part None 8 Month: 12 Year:19 87 ack to 4410' and dumped 5 sx cement on top of sa O sx cement, 10 sx gel, 1 sx hulls, released ont. RECEIVED STATE CONTENTATION COMMISSION psi.
2nd plus 2nd plus wiper p Plugging Operation ACTUAL PL through 2nd plus 8 5/8" v	g sand back to 4410' and dump 5 s g pump 4 sx hulls, 10 sx gel, 50 lug and pump 120 sx cement. Plugging Pro Operations attended by Agent?: as Completed: Hour: 1:20 p.mDay: UGGING REPORT 1st plug sanded b bailer, g pumped 4 sx hulls, 10 sx gel, 5 wiper plug and pumped 120 sx ceme pressure 400 psi and shut in 200	x cement on top of sand through bailer, sx cement, 10 sx gel, 1 sx hulls, release 8 5/8' posal Received by Richard Lacey (TECHNICIAN) All X Part None 8 Month: 12 Year:19 87 ack to 4410' and dumped 5 sx cement on top of sa O sx cement, 10 sx gel, 1 sx hulls, released ont. RECEIVED STATE CONTENTATION COMMISSION psi. ed. Recovered 2410' of 5½' casing. BACK of this CCOMPENTATION DUMSION

FORM CP-2/3 Rev.01-84