KCC OIL/GAS REGULATORY OFFICES									
Inspection Date	11/10/2015	District:	3	lne	er:	, 52	275		
•		✓ New Situation		☐ Lease Inspection					
✓ Response to Request				☐ Complaint					
☐ Follow-up				☑ Field Report					
Operator License	<b>No:</b> 6293	API:		٠		Q3 ·	Q2:	Q1:	
Operator Name:	Continental	Exploration, Inc.	SEC	29 <b>TWP</b>	17	RGE	22 R	GEDIR E	
Address: 10801	Mastin, Suite	920				FS	SL:		
City: Overland							EL:		
_	ip Code: 6		e Haye	S	0	Well N			
Phone contact: Reason for Invest	913-491-	-17,17			Col	unty:	Mi		
	_	to check the status	of the H	laves D3 15	_121_	27216 a	nd E-2 1	5_121_	
27214 wells.	a legal stall	to check the status	Or the r	layes be 10	141	27210 U	101 21	0 121	
5 11									
<u>Problem:</u>									
							•		
					,			•	
Porcons contacts	d.								
Persons contacte William Moore III 8		•							
	10-223-4014	•							
<u>Findings:</u>									
		2015. I did not find / metal detector in t				e wells a	it the sui	rface nor	
did i get a clear rea	iding with my	y metal detector in t	ne local	ions of the v	vens.				
		•							
Actions / Recomm		Follow-up R	<u>-</u>	_	<u>Dea</u>	<u>dline Da</u>	<u>ite:</u>		
It appears that the	wells were n	ever drilled or were	plugged	d.					
				•					
			•						
						BL.	4-1- <b>T</b> - !		^
DPDM9	M KCS	[] <b>T</b>	. =-			•	<u>to's Tak</u>	<u>cen:</u>	0
	✓ KGS	☐ TA DB Re	•	_		or Herma	<u>an</u>		
T1 DBF	IVI District F	iles 🗍 Courthou	ise Pr	osition: F	·CRS				