100 100			API NUMBER 15-047-20,482-0000 C NE NE, SEC. 18 , T 25 S, R 16 W/E	
Technician's Plugging Report 100				
Operator: License 8 5427 Operator: D:R. Lauck Oil Company, Inc. Named Address 221 S. Broadway, Suite 400 Wichita, KS 67202 Conductor Pipe: Size Surface Casing: Size8 5/8 teet 328 Abandoned Oil Weil x Gas Weil input Weil SND Weil Obba Other weil as hereinafter Indicated Plugging Contractor Kelso Casing Pulling Address P.O. Box 347, Chase, KS 67524 Company to ping at: Hour: 12:45 p.m. Day: 18 Month: 12 Year:19 87 Plugging proposel received from Ron Hoover (company name) Kelso Casing Pulling (phone) 316-938-2457 vere: 5½" at 4425' PETD 4436' Perfs at 4353-70' 1st plug sand back to 4300' and dump 5 sx cement on top of sand through bailer, 2nd plug pump 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, release 8 5/8" wiper plug and pump 125 sx cement. Plugging Proposel Received by Paul Luthi (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 1:30 p.mDay: 18 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT 1st plug sanded back to 4300' and dumped 5 sx cement on top of sand through bailer, 2nd plug pumped 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, release 8 5/8" ACTUAL PLUGGING REPORT 1st plug sanded back to 4300' and dumped 5 sx cement on top of sand through bailer, 2nd plug and pumped 125 sx cement. Maximum pressure 300 psi and shut in 100 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied, Recovered 2300' of 5½" casing the form.) Note of this form.) Note of this form.) Note of this form.) Note of this form.)				
Name6 Address 221 S. Broadway, Suite 400 Well Total Depth 4436 feet Wichita, KS 67202 Conductor Pipe: Size feet	Operator	License # 5427		
Name4 Address 221 S. Broadway, Suite 400 Well Total Depth 4436 feet Surface Casing: Size 65/8 feet 328	Operator:	DCR. Lauck Oil Company, Inc.		
Wichita, KS 67202 Conductor Pipe: Size feet Surface Casing: Size 5/8 feet 328 Abandoned Oli Heil x Gas Well Input Well SWD Well D&A Other well as hereinafter Indicated Plugging Contractor Kelso Casing Pulling License Number 6050 Address P.O. Box 347, Chase, KS 67524 Company to plug at: Hour: 12:45 p.m.Day: 18 Nonth: 12 Year:19 87 Plugging proposel received from Ron Hoover (company name) Kelso Casing Pulling (phone) 316-938-2457 were: 5% at 4425' PETD 4436' Perfs at 4353-70' 1st plug sand back to 4300' and dump 5 sx cement on top of sand through bailer, 2nd plug pump 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, release 8 5/8" wiper plug and pump 125 sx cement. Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 1:30 p.mbey: 18 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT 1st plug sanded back to 4300' and dumped 5 sx cement on top of sand through bailer. 2nd plug pumped 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5 wiper plug and pumped 125 sx cement. Maximum pressure 300 psi and shut in 100 psi. Remarks: Usad 60/40 Pozmix 6% gel by Allied. Recovered 2300' of 5% casaum. Maximum pressure 300 psi and shut in 100 psi.		221 S. Broadway, Suite 400		
Surface Casing: Size8 5/8 test 328 Abandoned Oil Well x Gas Well Input Well SWD Well D&A Other well as hereinafter Indicated Plugging Contractor Kelso Casing Pulling License Number 6050 Address P.O. Box 347, Chase, KS 67524 Company to plug at: Hour: 12:45 p.m.Day: 18 Month: 12 Year:19 87 Plugging proposel received from Ron Hoover (company name) Kelso Casing Pulling (phone) 316-938-2457 vere: 5½" at 4425' PBTD 4436' Perfs at 4353-70' 1st plug sand back to 4300' and dump 5 sx cement on top of sand through bailer, 2nd plug pump 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, release 8 5/8" wiper plug and pump 125 sx cement. Plugging Operations attended by Agent7: All X Pert None Operations Completed: Hour: 1:30 p.mDay: 18 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT 1st plug sanded back to 4300' and dumped 5 sx cement on top of sand through bailer, 2nd plug pumped 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, release 8 5 wiper plug and pumped 125 sx cement. Maximum pressure 300 psi and shut in 100 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied, Recovered 2300' of 5½" casaling. Maximum pressure 300 psi and shut in 100 psi.				
Abendoned Oll Well X Gas Well Input Well SMD Well D&A Other well as hereinafter Indicated Plugging Contractor Kelso Casing Pulling License Number 6050 Address P.O. Box 347, Chase, KS 67524 Company to plug at: Hour: 12:45 p.m.Day: 18 Month: 12 Year:19 87 Plugging proposal received from Ron Hoover (company name) Kelso Casing Pulling (phone) 316-938-2457 were: 5½" at 4425" PETD 4436" Perfs at 4353-70" Ist plug sand back to 4300" and dump 5 sx cement on top of sand through bailer, 2nd plug pump 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, release 8 5/8" wiper plug and pump 125 sx cement. Plugging Operations attended by Agent7: All X Part None Operations Completed: Hour: 1:30 p.mDay: 18 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT 1st plug sanded back to 4300" and dumped 5 sx cement on top of sand through bailer, 2nd plug pumped 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5 wiper plug and pumped 125 sx cement. Maximum pressure 300 psi and shut in 100 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 2300" of 5½" casing and Clif additional description is necessary, use 8ACK of this form.) Note of the state o				
Plugging Contractor Kelso Casing Pulling Address P.O. Box 347, Chase, KS 67524 Company to plug at: Hour: 12:45 p.m.Day: 18 Month: 12 Year:19 87 Plugging proposal received from Ron Hoover (company name) Kelso Casing Pulling (phone) 316-938-2457 vere: 5½" at 4425' PBTD 4436' Perfs at 4353-70' 1st plug sand back to 4300' and dump 5 sx cement on top of sand through bailer, 2nd plug pump 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, release 8 5/8" wiper plug and pump 125 sx cement. Plugging Operations attended by Agent7: All X Part None Operations Completed: Hour: 1:30 p.mDay: 18 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT 1st plug sanded back to 4300' and dumped 5 sx cement on top of sand through bailer, 2nd plug pumped 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, release 8 5 swiper plug and pumped 125 sx cement. Maximum pressure 300 psi and shut in 100 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 2300' of 54" casimum. (If additional description is necessary, use BACK of this form.)	Abandoned	Oli Well X Gas Well		
Address P.O. Box 347, Chase, KS 67524 Company to plug at: Hour: 12:45 p.m.Day: 18 Month: 12 Year:19 87 Plugging proposal received from Ron Hoover (company name) Kelso Casing Pulling (phone)316-938-2457 were: 5½" at 4425' PBTD 4436' Perfs at 4353-70' 1st plug sand back to 4300' and dump 5 sx cement on top of sand through bailer, 2nd plug pump 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, release 8 5/8" wiper plug and pump 125 sx cement. Plugging Proposal Received by Paul Luthi (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 1:30 p.mDay: 18 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT 1st plug sanded back to 4300' and dumped 5 sx cement on top of sand through bailer, 2nd plug pumped 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5 wiper plug and pumped 125 sx cement. Maximum pressure 300 psi and shut in 100 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 2300' of 5½" caskang. (If additional description is necessary, use BACK of this form.)				
Company to plug at: Hour: 12:45 pim.Day: 18 Month: 12 Year:19 87 Plugging proposal received from Ron Hoover (company name) Kelso Casing Pulling (phone)316-938-2457 were: 5½" at 4425' PBTD 4436' Perfs at 4353-70' 1st plug sand back to 4300' and dump 5 sx cement on top of sand through bailer, 2nd plug pump 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, release 8 5/8" wiper plug and pump 125 sx cement. Plugging Proposal Received by Paul Luthi (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 1:30 p.mOay: 18 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT 1st plug sanded back to 4300' and dumped 5 sx cement on top of sand through bailer, 2nd plug pumped 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5 wiper plug and pumped 125 sx cement. Maximum pressure 300 psi and shut in 100 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 2300' of 5½" caskang. (If additional description is necessary, use BACK of this form.) Note of the state of this form.)	Plugging	Contractor Kelso Casing Pulling	License Number 6050	
Piugging proposal received from Ron Hoover (compeny name) Kelso Casing Pulling (phone)316-938-2457 were: 5½" at 4425' PBTD 4436' Perfs at 4353-70' 1st plug sand back to 4300' and dump 5 sx cement on top of sand through bailer, 2nd plug pump 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, release 8 5/8" wiper plug and pump 125 sx cement. Plugging Proposal Received by Paul Luthi (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 1:30 p.mDay: 18 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT 1st plug sanded back to 4300' and dumped 5 sx cement on top of sand through bailer, 2nd plug pumped 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5 wiper plug and pumped 125 sx cement. Maximum pressure 300 psi and shut in 100 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied, Recovered 2300' of 5½" casand. (11 additional description is necessary, use 8ACK of this form.) None Operations Completed: Hour: 1:30 p.mDay: 18 Month: 10 sx gel, 1 sx hulls, released 8 5 Wiper plug and pumped 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5 Wiper plug and pumped 125 sx cement.	Address	P.O. Box 347, Chase, KS 67524		
(compeny name) Kelso Casing Pulling (phone) 316-938-2457 were: 5½" at 4425' PBTD 4436' Perfs at 4353-70' 1st plug sand back to 4300' and dump 5 sx cement on top of sand through bailer, 2nd plug pump 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, release 8 5/8" wiper plug and pump 125 sx cement. Plugging Proposal Received by Paul Luthi (TECHNICIAN) Plugging Operations attended by Agent?: Ali X Part None Operations Completed: Hour: 1:30 p.mooy: 18 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT 1st plug sanded back to 4300' and dumped 5 sx cement on top of sand through bailer. 2nd plug pumped 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5 wiper plug and pumped 125 sx cement. Maximum pressure 300 psi and shut in 100 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 2300' of 5½" casing. (if additional description is necessary, use BACK of this form.)	Company to plug at: Hour: 12:45 p.m.Day: 18 Month: 12 Year:19 87			
Ist plug sand back to 4300' and dump 5 sx cement on top of sand through bailer, 2nd plug pump 3 sx hills, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, release 8 5/8" wiper plug and pump 125 sx cement. Plugging Proposal Received by Paul Luthi (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 1:30 p.mDey: 18 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT 1st plug sanded back to 4300' and dumped 5 sx cement on top of sand through bailer, 2nd plug pumped 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5 wiper plug and pumped 125 sx cement. Maximum pressure 300 psi and shut in 100 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 2300' of 5½" casange. (If additional description is necessary, use BACK of this form.)	Plugglng	proposal received from Ron Hoover		
Ist plug sand back to 4300' and dump 5 sx cement on top of sand through bailer, 2nd plug pump 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, release 8 5/8" wiper plug and pump 125 sx cement. Plugging Proposal Received by Paul Luthi (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 1:30 p.mDay: 18 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT 1st plug sanded back to 4300' and dumped 5 sx cement on top of sand through bailer, 2nd plug pumped 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5 wiper plug and pumped 125 sx cement. Maximum pressure 300 psi and shut in 100 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 2300' of 5½" casanilo. (If additional description is necessary, use BACK of this form.) All Allied	(company name) Kelso Casing Pulling (phone) 316-938-2457			
2nd plug pump 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, release 8 5/8" wiper plug and pump 125 sx cement. Plugging Proposal Received by Paul Luthi (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 1:30 p.mDay: 18 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT 1st plug sanded back to 4300' and dumped 5 sx cement on top of sand through bailer, 2nd plug pumped 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5 wiper plug and pumped 125 sx cement. Maximum pressure 300 psi and shut in 100 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 2300' of 5½" casango. (If additional description is necessary, use BACK of this form.) N W 10/100 through observe this plugging.	were:	5½" at 4425' PBTD 4436' Perfs at 4	4353-70'	
Plugging Proposal Received by Paul Luthi (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 1:30 p.mDay: 18 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT 1st plug sanded back to 4300' and dumped 5 sx cement on top of sand through bailer, 2nd plug pumped 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5 wiper plug and pumped 125 sx cement. Maximum pressure 300 psi and shut in 100 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 2300' of 5½" casange. (If additional description is necessary, use BACK of this form.) NOIO/ARREMAND observe this plugging.	1st plug	sand back to 4300' and dump 5 sx ce	ement on top of sand through bailer,	
Plugging Proposal Received by Paul Luthi (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 1:30 p.mDay: 18 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT 1st plug sanded back to 4300' and dumped 5 sx cement on top of sand through bailer, 2nd plug pumped 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5 wiper plug and pumped 125 sx cement. Maximum pressure 300 psi and shut in 100 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 2300' of 5½" casange. (If additional description is necessary, use BACK of this form.) N Wi O/MIXEMENT observe this plugging.	2nd plug	pump 3 sx hulls, 10 sx gel. 50 sx o	rement. 10 sx gel. 1 sx hulls, release 8 5/8"	
Plugging Proposal Received by Paul Luthi (TECHNICIAN) Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 1:30 p.mDay: 18 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT 1st plug sanded back to 4300' and dumped 5 sx cement on top of sand through bailer, 2nd plug pumped 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5 wiper plug and pumped 125 sx cement. Maximum pressure 300 psi and shut in 100 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 2300' of 5½" casange. (If additional description is necessary, use BACK of this form.)		•		
Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 1:30 p.mDay: 18 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT 1st plug sanded back to 4300' and dumped 5 sx cement on top of sand through bailer, 2nd plug pumped 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5 wiper plug and pumped 125 sx cement. Maximum pressure 300 psi and shut in 100 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 2300' of 5½" casange. (If additional description is necessary, use BACK of this form.)				
Plugging Operations attended by Agent?: All X Part None Operations Completed: Hour: 1:30 p.mDay: 18 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT 1st plug sanded back to 4300' and dumped 5 sx cement on top of sand through bailer, 2nd plug pumped 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5 wiper plug and pumped 125 sx cement. Maximum pressure 300 psi and shut in 100 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 2300' of 5½" casange. (If additional description is necessary, use BACK of this form.) NOO ACCURATE Observe this plugging.		Plugging Propos	sal Received by Paul Luthi	
Operations Completed: Hour: 1:30 p.mDay: 18 Month: 12 Year:19 87 ACTUAL PLUGGING REPORT 1st plug sanded back to 4300' and dumped 5 sx cement on top of sand through bailer, 2nd plug pumped 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5 wiper plug and pumped 125 sx cement. Maximum pressure 300 psi and shut in 100 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 2300' of 5½" casiming. (If additional description is necessary, use BACK of this form.) N WIO Exercise 300 psi and shut plugging.				
ACTUAL PLUGGING REPORT 1st plug sanded back to 4300' and dumped 5 sx cement on top of sand through bailer, 2nd plug pumped 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5 wiper plug and pumped 125 sx cement. Maximum pressure 300 psi and shut in 100 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 2300' of 5½" casingo. (If additional description is necessary, use BACK of this form.) Note that the state of this plugging.	Plugging	Operations attended by Agent?: Al	None	
2nd plug pumped 3 sx hulls, 10 sx gel. 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5 wiper plug and pumped 125 sx cement. Maximum pressure 300 psi and shut in 100 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 2300' of 5½" casing (If additional description is necessary, use BACK of this form.) New York and observe this plugging.				
2nd plug pumped 3 sx hulls, 10 sx gel, 50 sx cement, 10 sx gel, 1 sx hulls, released 8 5 wiper plug and pumped 125 sx cement. Maximum pressure 300 psi and shut in 100 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 2300' of 5½" casingo. (If additional description is necessary, use BACK of this form.)	ACTUAL PL	LUGGING REPORT 1st plug sanded back	to 4300' and dumped 5 sx cement on top of	
Maximum pressure 300 psi and shut in 100 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 2300' of 5½" casingo. (If additional description is necessary, use BACK of this form.)	sand thro	ough bailer,	0	
Maximum pressure 300 psi and shut in 100 psi. Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 2300' of 5½" casango. (If additional description is necessary, use BACK of this form.) NOTE: The state of the	2nd plug	pumped 3 sx hulls, 10 sx gel. 50 sx	k cement, 10 sx gel, 1 sx hulls, released 8 5/8	
Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 2300' of 5½" casingo. (If additional description is necessary, use BACK of this form.) NOTE Of the serve this plugging.	wiper plu	ig and pumped 125 sx cement.	On the Contract of the Contrac	
Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 2300' of 5½" casingo. (If additional description is necessary, use BACK of this form.) NOTE Of the serve this plugging.			CON TO SA COM	
Remarks: Used 60/40 Pozmix 6% gel by Allied. Recovered 2300' of 5½" casingo. (If additional description is necessary, use BACK of this form.) (NIO/ HEXAGOD observe this plugging.	Maximum p	pressure 300 psi and shut in 100 ps	i. Wichigario 190 Milioson N	
N (Vi O) HEHAMAN observe this plugging.	Remarks:	Used 60/40 Pozmix 6% gel by Allied	1. Recovered 2300' of 5½" casango	
		til additional description is i	necessary, use BACK of this form.)	
			De la fitte	
Signed au a sulle (TECHNICIAN)	E	6-82	Signed and a lattle	