## STATE OF KANSAS STATE CORPORATION COMMISSION

# 15-083-10271-0000 Form CP-4

Give All Information Completely Make Required Affidavit Mail or Deliver Report to: Conservation Division State Corporation Commission

## WELL PLUGGING RECORD

212 No. Market Wichita, Kansas	HODGEMAN		County.				
NORTH	Location as "NE	E/CNW%SW%" (	or footage from MDANV	i lines . L S	t st		
	Lease Owner		CIF AND		·	. Well No	2
	Office Address_		llaire. De	enver. CO		. WEIL INO	
	Character of W						
	Date well comp			J	une_3		_19 <u>.63</u>
	Application for	]			<b>-</b> 28		_19 <u>.<b>75</b></u>
		Freedom Property			<u>-30</u>		_19_75
		Plugging commenced 2-1					_19 <u>.<b>75</b></u>
		Plugging completed 2-15  Reason for abandonment of well or producing formation State Regula					_19.75
	Reason for aban	Require		tormation SEA	te kegulai	LIONS.	
0	If a producing	•	-	t production			19
	Was permission						
Locate well correctly on above Section Plat	menced?	Yes					
ne of Conservation Agent who su	pervised plugging of this	swell Clare	nce F. The	omas		1.70	
lucing formation MISSISS	sippian D	Depth to top_4	/20 Bottom	4/50	Total Depth of	Well 478	9 Fe
w depth and thickness of all wate	er, oil and gas formation	ıs.					
IL, CAS OR WATER RECOF	RDS				(	CASING RE	CORD
	CONTENT	FROM	то	SIZE	PUT IN	PULLED	GUT
FORMATION	GUNTEN	0	242	8 5/8	242	0	001
		0	4788	5/1/2	4788	348	
						-	
			1			ļ	
	_		<del> </del>	-			· · · · · · · · · · · · · · · · · · ·
Dumped 50 of Dumped 4 sack	ement or other plugs we set.  f sand across poks of cement.	ere used, state the erferation Shot pipe	s. Plug sat 348'.	same and depth back total Pulled 10	depth is	4700' f 5 1/2''	feet
Dumped 4 sack casing. Disp	ement or other plugs we set.  f sand across pe	erferation Shot pipe h 50 sacks	s. Plug sat 348'.	same and depth back total Pulled 10	depth is	4700' f 5 1/2''	feet
Dumped 4 sack casing. Disp	ement or other plugs we set.  f sand across poks of cement. Splaced hole with	erferation Shot pipe h 50 sacks	s. Plug sat 348'.	same and depth back total Pulled 10	depth is	4700' f 5 1/2''	feet
Dumped 4 sack casing. Disp	ement or other plugs we set.  f sand across poks of cement. Splaced hole with	erferation Shot pipe h 50 sacks	s. Plug sat 348'.	same and depth back total Pulled 10	depth is	4700' f 5 1/2''	feet
Dumped 50 of Dumped 4 sack	ement or other plugs we set.  f sand across poks of cement. Splaced hole with	erferation Shot pipe h 50 sacks	s. Plug sat 348'.	same and depth back total Pulled 10	depth is	4700' f 5 1/2''	feet
Dumped 4 sack casing. Disp	ement or other plugs we set.  f sand across poks of cement. Splaced hole with	erferation Shot pipe h 50 sacks	s. Plug sat 348'.	same and depth back total Pulled 10	depth is	4700' f 5 1/2''	feet
Dumped 50 of Dumped 4 sack	ement or other plugs we set.  f sand across poks of cement. Splaced hole with	erferation Shot pipe h 50 sacks	s. Plug sat 348'.	same and depth back total Pulled 10	depth is	4700' f 5 1/2''	feet
Dumped 50 of Dumped 4 sack	ement or other plugs we set.  f sand across poks of cement. Splaced hole with	erferation Shot pipe h 50 sacks	s. Plug sat 348'.	same and depth back total Pulled 10	depth is	4700' f 5 1/2''	feet
Dumped 50 of Dumped 4 sack	ement or other plugs we set.  f sand across poks of cement. Splaced hole with	erferation Shot pipe h 50 sacks	s. Plug sat 348'.	same and depth back total Pulled 10	depth is joints of gel,	4700' f 5 1/2'' 35 sack	feet
Dumped 50 of Dumped 4 sack	ement or other plugs we set.  f sand across poks of cement. Splaced hole with	erferation Shot pipe h 50 sacks	s. Plug sat 348'.	same and depth back total Pulled 10	depth is	4700' f 5 1/2'' 35 sack	feet
Dumped 50 of Dumped 4 sack	ement or other plugs we set.  f sand across poks of cement. Splaced hole with	erferation Shot pipe h 50 sacks	s. Plug sat 348'.	same and depth back total Pulled 10 t, 10 sack	depth is joints of gel,	4700' f 5 1/2'' 35 sack	feet
Dumped 50 of Dumped 4 sack	ement or other plugs we set.  f sand across poks of cement. Splaced hole with	erferation Shot pipe h 50 sacks	s. Plug sat 348'.	same and depth back total Pulled 10 t, 10 sack  STATE CORI	depth is joints of s of gel,  CEIVED  ORATION COM	4700' f 5 1/2'' 35 sack	feet
Dumped 50 of Dumped 4 sack	ement or other plugs we set.  f sand across poks of cement. Splaced hole with	erferation Shot pipe h 50 sacks	s. Plug sat 348'.	same and depth back total Pulled 10 t, 10 sack  STATE CORI	depth is joints of s of gel,  CEIVED  ORATION COM	4700' f 5 1/2'' 35 sack	feet
Dumped 4 sack casing. Disp	ement or other plugs we set.  f sand across poks of cement. Splaced hole with	erferation Shot pipe h 50 sacks	s. Plug sat 348'.	same and depth back total Pulled 10 t, 10 sack  STATE CORI	depth is joints of gel,	4700' f 5 1/2'' 35 sack	feet
Dumped 4 sack casing. Disp	f sand across pooks of cement. Splaced hole with rface. Well P&	erferation Shot pipe h 50 sacks A.	s. Plug lat 348', of cemen	same and depth back total Pulled 10 t, 10 sack  STATE CORP	depth is joints of s of gel,  CEIVED  ORATION COM	4700' f 5 1/2'' 35 sack	feet
Dumped 50 of Dumped 4 sack casing. Disp cement to sur	f sand across poks of cement. Splaced hole with rface. Well P&	erferation Shot pipe h 50 sacks A.	s. Plug lat 348', of cemen	same and depth back total Pulled 10 t, 10 sack  STATE CORP	depth is joints of s of gel,  CEIVED  ORATION COM	4700' f 5 1/2'' 35 sack	feet
Dumped 50 of Dumped 4 sack casing. Disp cement to sur	f sand across poks of cement. Splaced hole with rface. Well P&	erferation Shot pipe h 50 sacks A.	s. Plug lat 348', of cemen	same and depth back total Pulled 10 t, 10 sack  STATE CORP	depth is joints of s of gel,  CEIVED  ORATION COM	4700' f 5 1/2'' 35 sack	feet
Dumped 50 of Dumped 4 sack casing. Disp cement to sur	f sand across poks of cement. Splaced hole with rface. Well P&	erferation Shot pipe h 50 sacks A.	s. Plug sat 348'. of cemen	same and depth back total Pulled 10 t, 10 sack  STATE CORP	depth is joints of s of gel,  CEIVED  ORATION COM	4700' f 5 1/2'' 35 sack	feet
Dumped 50 of Dumped 4 sack casing. Disp cement to sur	rles Crowe Dril O. Box 706 Hays	erferation Shot pipe h 50 sacks A.  I description is need ling Co. , Kansas	s. Plug sat 348'. of cemen	STATE CORI	depth is joints of s of gel,  CEIVET ORATION COM  ATION DIVISION, Kansas	4700' f 5 1/2'' 35 sack	feet
Dumped 50 of Dumped 4 sack casing. Disp cement to sur	rles Crowe Dril O. Box 706 Hays	erferation Shot pipe h 50 sacks A.  Idescription is necelling Co. , Kansas	s. Plug sat 348'. of cemen ssary, use BACK of 57601	same and depth back total Pulled 10 t, 10 sack  STATE CORI	depth is joints of s of gel,  CEIVET PORATION COM  ATION DIVISION. Kansas	4700' F 5 1/2'' 35 sack  MISSION  F 5 1/2''  F 5 1/2'' F	s of
Dumped 50 of  Dumped 50 of  Dumped 4 sack casing. Disp cement to sur	rles Crowe Dril 0. Box 706 Hays	erferation Shot pipe h 50 sacks A.  Idescription is necelling Co. , Kansas	s. Plug sat 348'. of cemen ssary, use BACK of 67601  Denver employee of or	STATE CORN  CONSERV  Vich  of this sheet)	depth is joints of s of gel,  CEIVET ORATION COM  ATION DIVISION. Kansas	4700' F 5 1/2'' 35 sack  MISSION  F 5 1/2''  MISSION  F 5 1/2''  Of the above	s of
ntroducing it into the hole. If confect for each plug  Dumped 50 of Dumped 4 sack casing. Displayed to sure cement to sure cem	rles Crowe Dril 0. Box 706 Hays  , says: That I have kn	erferation Shot pipe h 50 sacks A.  I description is need ling Co. , Kansas	s. Plug sat 348', of cemen sat 348', of cemen sat 348'.  Seary, use BACK of 67601  Denver employee of or facts, statemen	STATE CORN  CONSERV  Vich  of this sheet)	depth is joints of s of gel,  CEIVET ORATION COM  ATION DIVISION. Kansas	4700' F 5 1/2'' 35 sack  MISSION  F 5 1/2''  MISSION  F 5 1/2''  Of the above	s of
Dumped 50 of Dumped 4 sack casing. Disp cement to sur  The of Plugging Contractor Chailerss P. Colorado D. A. Coppede Chemical Coppede Colorado D. A. Coppede Colorado D. Colorado D. Colorado D. Coppede Coppede Coppede Coppede Copped	rles Crowe Dril O. Box 706 Hays  , says: That I have kn hat the same are true an	erferation Shot pipe h 50 sacks A.  Idescription is necelling Co. , Kansas  UNTY OF  (nowledge of the ad correct. So	s. Plug sat 348', of cemen sat 348', of cemen sat 348'.  Seary, use BACK of 67601  Denver employee of or facts, statemen	STATE CORN  CONSERV  Vich  of this sheet)	depth is joints of s of gel,  CEIVET ORATION COM  ATION DIVISION. Kansas	4700' F 5 1/2'' 35 sack  MISSION  F 5 1/2''  MISSION  F 5 1/2''  Of the above	s of
ntroducing it into the hole. If confect for each plug  Dumped 50 of Dumped 4 sack casing. Displayed comment to sure comment to sure comment to sure comments. P. Colorado D. A. Coppedo I, being first duly sworn on oath ve-described well as filed and the confect of the confect	rles Crowe Dril O. Box 706 Hays  , says: That I have kn hat the same are true an	erferation Shot pipe h 50 sacks A.  I description is need ling Co. , Kansas	s. Plug sat 348', of cemen sat 348', of cemen sat 348'.  Seary, use BACK of 67601  Denver employee of or facts, statemen	STATE CORN  CONSERV  Vich  of this sheet)	depth is joints of s of gel,  CEIVET ORATION COM  ATION DIVISION. Kansas	4700' F 5 1/2'' 35 sack  MISSION  F 5 1/2''  MISSION  F 5 1/2''  Of the above	s of
Dumped 50 of Dumped 4 sack casing. Disp cement to sur  the of Plugging Contractor Char livess P. (  Colorado D. A. Coppedo I, being first duly sworn on oath ve-described well as filed and the	rles Crowe Dril O. Box 706 Hays  , says: That I have kn hat the same are true an	erferation Shot pipe h 50 sacks A.  Idescription is necelling Co. , Kansas  UNTY OF  (nowledge of the ad correct. So	s. Plug sat 348', of cemen sat 348', of cemen sat 348'.  Seary, use BACK of 67601  Denver employee of or facts, statemen	STATE CORP  CONSERV  Victor  of this sheet)	depth is joints of s of gel,  CEIVED  ORATION COM  ATION DIVISIONAL Kansas  ss.  herein contain	4700' F 5 1/2'' 35 sack  MISSION  F 5 1/2''  MISSION  F 5 1/2''  Of the above	s of
Dumped 50 of Dumped 4 sack casing. Disp cement to sur  ne of Plugging Contractor Char lives P. (  TE OF Colorado D. A. Coppede l, being first duly sworn on oath ve-described well as filed and the	f sand across poks of cement.  f sand across poks of cement.  placed hole with rface. Well PEA  rles Crowe Dril  O. Box 706 Hays , COU  ge h, says: That I have know that the same are true and	erferation Shot pipe h 50 sacks A.  Idescription is necelling Co. , Kansas  UNTY OF  (nowledge of the ad correct. So	s. Plug sat 348', of cemen sat 348', of cemen sat 348'.  Seary, use BACK of 67601  Denver employee of or facts, statemen	STATE CORP  CONSERV  Victor  of this sheet)	depth is joints of s of gel,  CEIVET ORATION COM  ATION DIVISION. Kansas	4700' F 5 1/2'' 35 sack  MISSION  F 5 1/2''  MISSION  F 5 1/2''  Of the above	s of
Dumped 50 of Dumped 4 sack casing. Disp cement to sur  The of Plugging Contractor Process  The Colorado D. A. Coppedo D. Being first duly sworn on oath ve-described well as filed and the	f sand across poks of cement.  f sand across poks of cement.  placed hole with rface. Well PEA  rles Crowe Dril  O. Box 706 Hays , COU  ge h, says: That I have know that the same are true and	erferation Shot pipe h 50 sacks A.  Idescription is necelling Co. , Kansas  UNTY OF  (nowledge of the ad correct. So	s. Plug sat 348', of cemen sat 348', of cemen sat 348'.  Seary, use BACK of 67601  Denver employee of or facts, statemen	STATE CORP  CONSERV  Victor  of this sheet)	depth is joints of s of gel,  CEIVED  ORATION COM  ATION DIVISIONAL Kansas  ss.  herein contain	4700' F 5 1/2'' 35 sack  MISSION  F 5 1/2''  MISSION  F 5 1/2''  Of the above	s of

Lime & Shale

Lime & Shale

Lime & Shale

Lime & Shale

Mississippian

Mississippian

Mississippian

Mississippian

T.D.

### DRILLERS' LOG

Company: Jones-Gebert Oil Co. Contractor: Jones-Gebert Oil, Inc. Farm: #2 Mellecker, C SE SE Sec. 17-24S-22W Hodgeman County, Kansas Commenced: 4/20/63 Completed: 5/6/63 Casing: 8 5/8" @ 242 w/200 sx. 5 1/2" @ 4788 w/125 sx. 0 -242 Red Bed & Shale 242 - 1340Clay & Red Bed 1340 - 1510 Shale 1510 - 1585 Anhydrite 1585 - 1650 Shale 1650 - 1970 Shale & Shells Shale w/Lime Streaks 1970 - 2350 23.50 - 2530Lime & Shale 2530 - 2640 Lime & Some Chert 2640 - 2725 Lime 2725 - 2795Lime 2795 - 2865 Lime 2865 - 2955 Lime 2955 - 3070 Lime w/Shale 3070 = 3155 RECEIVED Brown Lime & Some Chalk STATE CORPORATION COMMISSION 3155 - 3310 Shale w/Lime Streaks 3310 - 3460 Shale w/Lime & Chalk Streaks JAN 3 0 1975 3460 - 3536 Shale w/Lime & Chalk Streaks 3536 - 3650 Shale w/Lime & Chalk Streaks . CONSERVATION DIVISION 3650 - 3755 Lime & Shale Wichita, Kansas 3755 - 3860Lime & Shale 3860 - 3970 Shale w/Lime & Chalk Sections 3970 - 4024 Shale & Lime 4024 - 4118 Shale & Lime w/Chalk Streaks 4118 - 4173 Lime & Shale - K.C. (?) 4173 - 4215 Lime 4215 - 4272 Lime 4272 - 4346 Lime w/Chert & Chalk 4346 - 4394 K.C. Lime 4394 - 4432Lime 4432 - 4477 Lime 4477 - 4531 Lime & Shale 4531 ~ 4578 Lime & Shale

4578 - 4598

4598 - 4630

4630 - 4678

4678 - 4710

4710 - 4715

4715 - 4725

4725 - 4740

4740 - 4785

4785

I, George R. Jones, do hereby certify that the above and foregoing is a true and correct copy of the log of the #2 Mellecker, C SE SE, Sec. 17-24S-22W, Hodgeman County, Kansas, as reflected by the files of Jones-Gebert Oil, Inc.

George R. Jones

State of Kansas - County of Sedgwick ) ss.
Subscribed and sworn to before me, a Notary Public, in and for Sedgwick
County, Kansas, this 9th day of May, 1963.

Barbara J. Layton

My Commission Expires: February 1, 1964

STATE CORPORATION COMMISSION

JAN 3 0 1975

CONSERVATION DIVISION
Wichita, Kansas