

Notice: Fill out COMPLETELY and return to Conservation Division at the address below within 60 days from plugging date.

KANSAS CORPORATION COMMISSION  
OIL & GAS CONSERVATION DIVISION  
**WELL PLUGGING RECORD**  
K.A.R. 82-3-117

Form CP-4  
March 2009  
Type or Print on this Form  
Form must be Signed  
All blanks must be Filled

OPERATOR: License #: 34521  
Name: Finley Resources Inc  
Address 1: 1308 Lake Street  
Address 2: \_\_\_\_\_  
City: Fort Worth State: TX Zip: 76102 + \_\_\_\_\_  
Contact Person: Josh Morgan  
Phone: (817) 231-8756  
Type of Well: (Check one)  Oil Well  Gas Well  OG  D&A  Cathodic  
 Water Supply Well  Other: \_\_\_\_\_  SWD Permit #: \_\_\_\_\_  
 ENHR Permit #: E-04587.3  Gas Storage Permit #: \_\_\_\_\_  
Is ACO-1 filed?  Yes  No If not, is well log attached?  Yes  No  
Producing Formation(s): List All (If needed attach another sheet)  
G.G.I.T Depth to Top: 3018 Bottom: 3177 T.D. 3290  
Gorham Sand Depth to Top: 3212 Bottom: 3216 T.D. 3290  
\_\_\_\_\_ Depth to Top: \_\_\_\_\_ Bottom: \_\_\_\_\_ T.D. \_\_\_\_\_

API No. 15 - 167-07048-00-02  
Spot Description: NW/4  
NW NW NW Sec. 27 Twp. 14 S. R. 14  East  West  
4,950 Feet from  North /  South Line of Section  
4,950 Feet from  East /  West Line of Section  
Footages Calculated from Nearest Outside Section Corner:  
 NE  NW  SE  SW  
County: Russell  
Lease Name: Olson AJ-A Well #: 2  
Date Well Completed: \_\_\_\_\_  
The plugging proposal was approved on: \_\_\_\_\_ (Date)  
by: \_\_\_\_\_ (KCC District Agent's Name)  
Plugging Commenced: 06/22/2012  
Plugging Completed: 06/27/2012

Show depth and thickness of all water, oil and gas formations.

Oil, Gas or Water Records		Casing Record (Surface, Conductor & Production)			
Formation	Content	Casing	Size	Setting Depth	Pulled Out
		Surface	20"	315	
		Production	7"	2981	
		Liner	4 1/2"	2936	

KCC WICHITA  
DEC 11 2015  
11-15  
RECEIVED

Describe in detail the manner in which the well is plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same depth placed from (bottom), to (top) for each plug set.

Ran tubing to 3180'. Pumped 16 sx gel w/50 sx cement w/100 # hulls. pulled tubing to 1590'. Pumped 100 sx cement w/300 # hulls. Pulled tubing to 970'. Pumped 100 sx cement w/200 # hulls. Pulled tubing to 372'. Pumped 125 sx cement w/no return. Tagged TOC @ 1576'. Pumped 15 sx gel w/500 # hulls mixed in w/100 Class A cement w/4% cc. The well started to circulate. Pulled tubing up to 753'. Tagged top @ 1497'. Pulled up and pumped 250 sx cement w/800 # hulls. Pumped 10 sx cement and filled casing. Dug out surface pipe. No pipe was found, ran 1 joint of tubing in beside 7" casing and pumped 10 sx cement to circulate cellar.

Plugging Contractor License #: 6426 Name: Express Well Service & Supply, Inc.  
Address 1: 1110 US Highway 40 Address 2: \_\_\_\_\_  
City: Victoria State: KS Zip: 67671 + \_\_\_\_\_  
Phone: (785) 735-9405  
Name of Party Responsible for Plugging Fees: Finley Resources Inc  
State of Texas County, Tarrant, ss.  
Josh Morgan  Employee of Operator or  Operator on above-described well,  
(Print Name)

being first duly sworn on oath, says: That I have knowledge of the facts statements, and matters herein contained, and the log of the above-described well is as filed, and the same are true and correct, so help me God.

Signature: Josh Morgan  
Mail to: KCC - Conservation Division, 130 S. Market - Room 2078, Wichita, Kansas 67202

SR

No. 5705

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

Company Finley Oper. Date 6-22 2012

Lease Olson Well # A-2 Co. Russell KANSAS

Directions \_\_\_\_\_

Job Description	Cause of Failure	No. of Rods or Joints Deep	Size and Type of Replacement (new) (used)
<u>Plug well</u>			

WELL RECORD

PULLED FROM WELL				RERAN IN WELL			
Feet	Joints	Description	Condition	Equipment	Feet	Joints	Description
				Polish Rod			
				Liner			
				Rod Subs			
				Rods			
				Rods			
				Rods			
				Pump			
				Tubing Subs			
				Tubing			
				Tubing			
				Bbl. Seat N.			
		Where Set Type Size		Packer or Tubing Anchor			Where Set Type Size
				Mud Anchor			

- Y  Paint \_\_\_\_\_
- Y  Diesel \_\_\_\_\_ Gal x \_\_\_\_\_ = \_\_\_\_\_
- Thread Dope \_\_\_\_\_ # \_\_\_\_\_ each = \_\_\_\_\_
- Y  Stuff Box Rub \_\_\_\_\_
- Y  Fishing Tool \_\_\_\_\_
- Y  Circ Head \_\_\_\_\_
- Circ Rubber New \_\_\_\_\_ Used \_\_\_\_\_
- Y  Packer (type) \_\_\_\_\_
- Y  Plug \_\_\_\_\_
- N Sand Pump 4 1/2 \_\_\_\_\_ 195.00
- Y  Swab Equip \_\_\_\_\_
- N Oil Saver Rub 1-Blue \_\_\_\_\_ 19.75
- Y  Swab Cups \_\_\_\_\_

Unit D.D. RIG # 11  
 Operator Kris S  
 Floorman Mike K  
 Floorman Corey L

Hrs.	Per Hr.	Amount
<u>8 1/2</u>	<u>10400</u>	<u>884.00</u>
<u>8 1/2</u>	<u>3800</u>	<u>323.00</u>
<u>8 1/2</u>	<u>3400</u>	<u>289.00</u>
<u>8 1/2</u>	<u>3400</u>	<u>289.00</u>
EXTRA EQUIP		<u>214.75</u>
SALES TAX		<u>165.98</u>
TOTAL		<u>2165.73</u>

Bad	Replacements
# _____ jts _____	# _____ jts _____
# _____ rods _____	# _____ rods _____
Rod Boxes Replaced 3/4" _____	7/8" _____ 1" _____

Y  Testing tbg: Who tested: \_\_\_\_\_

Results: \_\_\_\_\_ **KCC WICHITA**

Items used from Express: \_\_\_\_\_ **DEC 11 2015**

Items used from other suppliers: \_\_\_\_\_ **RECEIVED**

Remarks: D.T.C. M.I.R.U. Hooked up S.P. + R.T.H. + tagged C.I.B.f  
at 3002. Stroked S.P. a few times + came out clear. Layed  
S.P. v + cut S.C. + poured stinger for S.C.D. + put it together.  
Finally at 6:30 got plug to go v 150. Cost on plug till  
7:00 + didn't make it anymore. Cleared up loc. + shut v.

By: [Signature] Express Well Service & Supply, Inc. "Thank You" By: \_\_\_\_\_ Authorized Signature

No. 5704

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

Company FANLEY Date 12-25-2015

Lease Olson Well # A-2 Co. Russell KANSAS

Directions \_\_\_\_\_

Job Description \_\_\_\_\_ Cause of Failure \_\_\_\_\_ No. of Rods or Joints Deep \_\_\_\_\_ Size and Type of Replacement (new) (used) \_\_\_\_\_

WELL RECORD

PULLED FROM WELL				RERAN IN WELL			
Feet	Joints	Description	Condition	Equipment	Feet	Joints	Description
				Polish Rod			
				Liner			
				Rod Subs			
				Rods			
				Rods			
				Rods			
				Pump			
				Tubing Subs			
				Tubing			
				Tubing			
				Bbl. Seat N.			
		Where Set Type Size		Packer or Tubing Anchor			Where Set Type Size
				Mud Anchor			

- Y  Paint \_\_\_\_\_
- Y  Diesel \_\_\_\_\_ Gal x \_\_\_\_\_ = \_\_\_\_\_
- Thread Dope 5 lbs # 4.55 each = 22.75
- Y  Stuff Box Rub \_\_\_\_\_
- Y  Fishing Tool \_\_\_\_\_
- Y  Circ Head \_\_\_\_\_
- Circ Rubber New \_\_\_\_\_ Used \_\_\_\_\_
- Y  Packer (type) \_\_\_\_\_
- Y  Plug \_\_\_\_\_
- Y  Sand Pump \_\_\_\_\_
- Y  Swab Equip \_\_\_\_\_
- Y  Oil Saver Rub \_\_\_\_\_
- Y  Swab Cups \_\_\_\_\_

Unit DJTRK#11  
 Operator Kris S  
 Floorman Mike K  
 Floorman Corey C

Hrs.	Per Hr.	Amount
7 1/2	10400	780 00
7 1/2	3800	285 00
7 1/2	3400	255 00
7 1/2	3400	255 00
EXTRA EQUIP		22 75
SALES TAX		132 61
TOTAL		1730 36

Bad	Replacements
# _____ jts _____	# _____ jts _____
# _____ rods _____	# _____ rods _____
Rod Boxes Replaced 3/4" _____ 7/8" _____ 1" _____	

Y  Testing tbg: Who tested: KCC WICHITA  
 Results: \_\_\_\_\_  
 Items used from Express: \_\_\_\_\_  
RECEIVED

Items used from other suppliers: \_\_\_\_\_  
(sandline drill)  
 Remarks: D.T.L. back to S.C.D. till 8:30 & didn't make any more hole. Hooked up loggers - perf. Tallied in w/ tubing - got to 3185. Staged cement at 3185, 1590, 970 & 372. At 372 still didn't circ, any cement. P.O.D.H. w/ tubing - picked up loc. & shut down

By: [Signature] Express Well Service & Supply, Inc. "Thank You" By: \_\_\_\_\_ Authorized Signature

No. 5708

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

Company Finley Res. Date 10-26-20 12

Lease Olson Well # A-2 Co. Russell KANSAS

Directions \_\_\_\_\_

Job Description Cause of Failure No. of Rods or Joints Deep Size and Type of Replacement (new) (used)

WELL RECORD

PULLED FROM WELL				RERAN IN WELL			
Feet	Joints	Description	Condition	Equipment	Feet	Joints	Description
				Polish Rod			
				Liner			
				Rod Subs			
				Rods			
				Rods			
				Rods			
				Pump			
				Tubing Subs			
				Tubing			
				Tubing			
				Bbl. Seat N.			
		Where Set Type Size		Packer or Tubing Anchor			Where Set Type Size
				Mud Anchor			

- Y  Paint \_\_\_\_\_
- Y  Diesel \_\_\_\_\_ Gal x \_\_\_\_\_ = \_\_\_\_\_
- Thread Dope 4 lbs # 4.55 each = \$18.20
- Y  Stuff Box Rub \_\_\_\_\_
- Y  Fishing Tool \_\_\_\_\_
- Y  Circ Head \_\_\_\_\_
- Circ Rubber New \_\_\_\_\_ Used \_\_\_\_\_
- Y  Packer (type) \_\_\_\_\_
- Y  Plug \_\_\_\_\_
- Y  Sand Pump \_\_\_\_\_
- Y  Swab Equip \_\_\_\_\_
- Y  Oil Saver Rub \_\_\_\_\_
- Y  Swab Cups \_\_\_\_\_

Unit DD TRIG # 11  
 Operator Kris S  
 Floorman mile JL  
 Floorman Corey L

Hrs.	Per Hr.	Amount
10 1/2	10400	1092.00
10 1/2	3800	399.00
10 1/2	3400	357.00
10 1/2	3400	357.00
EXTRA EQUIP		18.20
SALES TAX		184.53
TOTAL		2407.73

Bad	Replacements
# _____ jts _____'	# _____ jts _____'
# _____ rods _____"	# _____ rods _____"
Rod Boxes Replaced 3/4" _____ 7/8" _____ 1" _____	

KCC WICHITA

Y  Testing tbg: Who tested: DEC 11 2015

Results: RECEIVED

Items used from Express: \_\_\_\_\_

Items used from other suppliers: \_\_\_\_\_

Remarks: D.T.C. R.I.H. w/ tubing & tagged cement at 1530. Pulled up 1 1/2' & pumped 100 sacks w/ 4% water & w/ halli-gel. Go well to circ. & pulled up to 600' & let set for 2 1/2 hours. At 1:00 P.M. w/ tubing again & it was 30' higher. Pumped cement again & pull out w/ tubing & topped off well. Well was still on a vacuum, so let it set 1 hour. Topped off well few more times & called it good. Cleaned up loc. & shut in.

By: [Signature] Express Well Service & Supply, Inc. "Thank You"

By: \_\_\_\_\_ Authorized Signature

No. 5706

EXPRESS WELL SERVICE & SUPPLY, INC.

Victoria, Kansas 67671

Company Fioley Res. Date 6-27-2012

Lease Olsen Well # A-2 Co. Russell KANSAS

Directions \_\_\_\_\_

Job Description Cause of Failure No. of Rods or Joints Deep Size and Type of Replacement (new) (used)

WELL RECORD

PULLED FROM WELL

RERAN IN WELL

Feet	Joints	Description	Condition	Equipment	Feet	Joints	Description
				Polish Rod			
				Liner			
				Rod Subs			
				Rods			
				Rods			
				Rods			
				Pump			
				Tubing Subs			
				Tubing			
				Tubing			
				Bbl. Seat N.			
		Where Set Type Size		Packer or Tubing Anchor			Where Set Type Size
				Mud Anchor			

- Y  Paint \_\_\_\_\_
- Y  Diesel \_\_\_\_\_ Gal x \_\_\_\_\_ = \_\_\_\_\_
- Thread Dope \_\_\_\_\_ # \_\_\_\_\_ each = \_\_\_\_\_
- Y  Stuff Box Rub \_\_\_\_\_
- Y  Fishing Tool \_\_\_\_\_
- Y  Circ Head \_\_\_\_\_
- Circ Rubber New \_\_\_\_\_ Used \_\_\_\_\_
- Y  Packer (type) \_\_\_\_\_
- Y  Plug \_\_\_\_\_
- Y  Sand Pump KCC WICHITA
- Y  Swab Equip DEC 11 2015
- Y  Oil Saver Rub \_\_\_\_\_
- Y  Swab Cups RECEIVED

Unit D.D. RIG # 11  
 Operator KRIS S  
 Floorman MIKE K  
 Floorman COREY L

Hrs.	Per Hr.	Amount
<u>2</u>	<u>104.00</u>	<u>208.00</u>
<u>2</u>	<u>38.00</u>	<u>76.00</u>
<u>2</u>	<u>34.00</u>	<u>68.00</u>
<u>2</u>	<u>34.00</u>	<u>68.00</u>
EXTRA EQUIP		<u>331.00</u>
SALES TAX		<u>62.33</u>
TOTAL		<u>813.33</u>

Bad	Replacements
# _____ Jts _____	# _____ Jts _____
# _____ rods _____	# _____ rods _____
Rod Boxes Replaced 3/4" _____ 7/8" _____ 1" _____	

Y  Testing tbg. Who tested: \_\_\_\_\_

Results: \_\_\_\_\_

Items used from Express: pit liner \$331.00 (used on 6/22 - missed putting on ticket)

Items used from other suppliers: \_\_\_\_\_

Remarks: D.T.L. Fluid was only fifty feet from surface so R.D.M.O.

By: [Signature]  
Express Well Service & Supply, Inc. "Thank You"

By: \_\_\_\_\_  
Authorized Signature