

## KCC OIL/GAS REGULATORY OFFICES

Inspection Date 12/15/2015 District: 3 Incident Number: 5316

- New Situation       Lease Inspection  
 Response to Request       Complaint  
 Follow-up       Field Report

Operator License No: 3749 API: Q3 Q2: Q1: SE

Operator Name: JCB Resources, Inc. SEC 27 TWP 22 RGE 19 RGEDIR E

Address: RR 1 FSL:

City: Welda FEL:

State KS Zip Code: 66091 Lease: Hester Well No.: 2

Phone contact:

County: AN

**Reason for Investigation:**

Request by Jon Myers (KCC Litigation Counsel) to determine status of well.

**Problem:**

Well status is "drilled" for an operator whose license expired in 1989.

**Persons contacted:**

Brad Cook (MAE Resources; 620-363-0785)

**Findings:**

The well in question, Hester #2 (15-003-22911-00-00) was located and recorded with a GPS unit. The casing was above the surface and appeared to be plugged. Hester #1 (15-003-22909-00-00), which is on record as plugged, was also located and recorded with GPS. According to Brad Cook (MAE Resources and former JCB Resources), both wells were plugged.

**Actions / Recommendation**

**Follow-up Required**

**Deadline Date:**

Submit report to Jon Myers and John Almond. Change status of Hester #2 to plugged. Turn GPS session sheet and file in for mapping and processing of legal spot locations.

**Photo's Taken:** -1

RBDMS

KGS

TA DBF

Report Prepared By: Levi Short

T1 DBF

District Files

Courthouse

Position: ECRS