

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM

Lease Owner John Lindas Oil, Inc. Address 1316 Union National Bank Bldg. Wichita 2, Kansas
(Applicant)
Lease (Farm Name) Giles Well No. 1

Well Location SW SW SE Sec. 35 Twp. 24 Rge. 15 (E)-(W) W

County Stafford Field Name (if any) _____

Total Depth 4480' Oil Gas Dry Hole Dry Hole

Was well log filed with application? Yes. If not, explain: _____

Date and hour plugging is desired to begin August 3, 1952

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission, or with the approval of the following exceptions: Explain fully any exceptions desired.
(Use an additional sheet if necessary) _____

Name of the person on the lease in charge of well for owner _____
Mr. Fred Moore Address P. O. Box 479 Great Bend, Kansas

Name of Plugging Contractor John Lindas Oil, Inc.
Address 1316 Union National Bank Bldg; Wichita 2, Kansas

Invoice covering assessment for plugging this well should be sent to
John Lindas Oil, Inc. Address 1316 Union National Bank Bldg. Wichita 2, Kansas

and payment will be guaranteed by applicant.

RECEIVED
Conservation Commission
AUG - 6 - 1952
Wichita, Kansas

[Signature]
Applicant

Date August 2, 1952

PLUGGING DIVISION
FILE SEC-35T-29-KANSAS
BOOK PAGE 35 LINE 33



STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

August 6, 1952

Well No.	1
Lease	Giles
Description	SW SW SE 35-24-15W
County	Stafford
File No.	35-33

John Linds Oil, Inc.
1316 Union Nat'l. Bank Bldg.
Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. M. A. Rives, Box 118, Pratt, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

BY: J. P. Roberts
J. P. ROBERTS

cc: DISTRICT PLUGGING SUPERVISOR