## 4-<u>020150</u>

SEP 0 6 2000 CONSERVATION DIVISION

TO:	API Number: 15-051-25,034-0000 Wichita. Kansas
STATE CORPORATION COMMISSION	00 YE YE /4 ODG 00 11 0 10 11
CONSERVATION DIVISION - PLUGGING	S2 NE NE /4 SEC. 26 ,11 S, 17 W
130 SOUTH MARKET, SUITE 2078	4280 feet from S section line
WICHITA, KANSAS 67202	feet from E section line
Operator license# <u>5259</u>	Lease: Denis Vine Well # 1
Operator: Mai Oil Operations, Inc.	County: Ellis 1928
Address: P.O. Box 33	Well total depthfeet
Russell, Kansas 67665	Conductor Pipe: 0 inch @ 0 feet
	Surface pipe 8 5/8 Inch @ 244 feet
Aband. oil well_X, Gas well, Input well,	SWD, D & A
Plugging contractor: Quality Well Service	License# 31925
Address: 249 E. Beth Drive - Sterling, Kansa	s 67579
Company to plug at: Hour: 3:00 P.M.Day: 28 Month	: August Year: 2000
Plugging proposal received from: Richard McI	ntyre
Company: Quality Well Service	Phone: 316-278-2476
	· · · · · · · · · · · · · · · · · · ·
Were: Ordered out 270 sxs 60/40 pozmix - 10% ge	<u>l - 400# hulls</u>
Shot off casing at 2418'.	<u> </u>
Prod Perfs at 3627' - 3630'; 3615' - 3618	1,
	<del></del>
<del></del>	
<del></del>	
Plugging Proposal Received by: <u>Herb Deines</u>	
Plugging operations attended by agent? All[X	l Part[   None[ ]
rragging operations acconded by agent. Air a	], Fait[ ], None[ ]
Completed: Hour: 6:00 P.M. , Day: 28 Mont	h: <u>August</u> , Year: 2000
Actual plugging report: 8 5/8" set at 244' w/16	0 eve 5 1/1 cet at 36671 w/200 cvc
Sanded back to 3560' and topped with 5 sxs deme	
Shot casing off at 2418'.	no wrong buries
Pulled casing to 2000' - tied onto and pumped 1	40 sxs with 300# hulls.
Pulled casing to 1473' - tied onto and spotted	
Pulled casing to 850' - tied onto and spotted 3	
Pulled casing to 150' - tied onto and circulate	
Pulled casing out of hole.	a comers -
Hole standing full of cement.	
MOLO Beauting Lazz of Committee	
Remarks: Allied Cementing Company.	
Condition of casing(in hole): GOOD X BAD	Anhy.plug: YES X NO
Bottom plug(in place): YES_X_, CALC, NO	Dakota plug: YES_X NO
Plugged through TUBING, CASINGX	
zzagged chrough fobing, Cabing	
I did[ $\mathbf{x}$ ] / did not[ ] observe the plugging.	Jay I feefer
INVOICE	(agent)