To: "	API NUMBER 15- 151- 21,064-60-00
STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING SECTION	SW , Sec. 6 , T 26 S, R 11 WXX
200 COLORADO DERBY BUILDING WICHITA, KANSAS 67202	feet from XXV/S section line
TECHNICIAN'S PLUGGING REPORT	feet from WAX section line
Operator License # <b>5692</b>	Lease Name Schlenz Well # 3
Operator: American Petrofina Co. of Texas Name & 4613 Jacksboro Highway	County Pratt
Address Wichita Falls, TX 76302	Well Total Depth 4375 feet 142.18
	Conductor Pipe: Sizefeet
•	Surface Casing: Size 8 5/8 feet 350
Abandoned Oil Well X Gas Well Inpu	t Well SWD Well D&A
Other well as hereinafter indicated .	
Plugging Contractor Clarke Corp.	License Number 5105
Address 107 West Fowler, Medicine Lodge, H	S 67104
Company to plug at: Hour: 9:00 am Day: 13	Month: February Year:19 84
VERBAL PLUGGING ORDERS GIVEN TO Elmo Morgenst	tern
(company name) Clarke	(phone) <b>316-886-5665</b>
were: 5 1/2 set at 4375 Perfs 4118-25	
1st plug sand back to 4060 and dump 5 sx c	·
2nd plug squeezed through head with 2 sx h	
1 sack hulls and released 8 5/8" rubber plu	ng and pump an additional 125 sx cement.
Maximum pressure 350# and shut-in pressure	
	Signed (TECHNICIAN)
Plugging Operations attended by Agent?: All	X None
	13 Month: February Year: 19 84
ACTUAL DINCCINC DEDODT 5 1/0 mat at 4275 T	13 Month: February Year: 19 84
	Perfs 4118-25 4138-40
1st plug sand back to 4060 and dump 5 sx c	Perfs 4118-25 4138-40 cement on top of sand through bailer
1st plug sand back to 4060 and dump 5 sx conditions 2nd plug squeezed through head with 2 sx h	Perfs 4118-25 4138-40 cement on top of sand through bailer nulls, 10 sx gel, 50 sx cement, 10 sx gel
1st plug sand back to 4060 and dump 5 sx c	Perfs 4118-25 4138-40 cement on top of sand through bailer nulls, 10 sx gel, 50 sx cement, 10 sx gel
1st plug sand back to 4060 and dump 5 sx c 2nd plug squeezed through head with 2 sx h	Perfs 4118-25 4138-40  cement on top of sand through bailer  nulls, 10 sx gel, 50 sx cement, 10 sx gel  nug and pumped an additional 125 sx cement
1st plug sand back to 4060 and dump 5 sx of 2nd plug squeezed through head with 2 sx h	Perfs 4118-25 4138-40  cement on top of sand through bailer  nulls, 10 sx gel, 50 sx cement, 10 sx gel  nug and pumped an additional 125 sx cement
1st plug sand back to 4060 and dump 5 sx of 2nd plug squeezed through head with 2 sx half sack hulls and released 8 5/8" rubber plum Maximum pressure 350# and shut-in pressure	Perfs 4118-25 4138-40  cement on top of sand through bailer  nulls, 10 sx gel, 50 sx cement, 10 sx gel  ug and pumped an additional 125 sx cement
1st plug sand back to 4060 and dump 5 sx of 2nd plug squeezed through head with 2 sx half 1 sack hulls and released 8 5/8" rubber plut Maximum pressure 350# and shut-in pressure  Remarks: Use 60/40 Pozmix 2% gel 3% cc by Sur	Perfs 4118-25 4138-40  cement on top of sand through bailer  nulls, 10 sx gel, 50 sx cement, 10 sx gel  ug and pumped an additional 125 sx cement
1st plug sand back to 4060 and dump 5 sx of 2nd plug squeezed through head with 2 sx half sack hulls and released 8 5/8" rubber plum Maximum pressure 350# and shut-in pressure	Perfs 4118-25 4138-40  cement on top of sand through bailer  nulls, 10 sx gel, 50 sx cement, 10 sx gel  ug and pumped an additional 125 sx cement
1st plug sand back to 4060 and dump 5 sx of 2nd plug squeezed through head with 2 sx half 1 sack hulls and released 8 5/8" rubber plus Maximum pressure 350# and shut-in pressure Remarks: Use 60/40 Pozmix 2% gel 3% cc by Sur	Perfs 4118-25 4138-40  cement on top of sand through bailer  nulls, 10 sx gel, 50 sx cement, 10 sx gel  ug and pumped an additional 125 sx cement  250#
2nd plug squeezed through head with 2 sx h  1 saak hulls and released 8 5/8" rubber plu  Maximum pressure 350# and shut-in pressure  Remarks: Use 60/40 Pozmix 2% gel 3% cc by Sur	Perfs 4118-25 4138-40  cement on top of sand through bailer  nulls, 10 sx gel, 50 sx cement, 10 sx gel  ug and pumped an additional 125 sx cement  250#
1st plug sand back to 4060 and dump 5 sx of 2nd plug squeezed through head with 2 sx half 1 sack hulls and released 8 5/8" rubber plus Maximum pressure 350# and shut-in pressure Remarks: Use 60/40 Pozmix 2% gel 3% cc by Sur	Perfs 4118-25 4138-40  cement on top of sand through bailer  nulls, 10 sx gel, 50 sx cement, 10 sx gel  ig and pumped an additional 125 sx cement  250#  Cementing They recovered 2660' of 5 1/
2nd plug squeezed through head with 2 sx h  1 sack hulls and released 8 5/8" rubber plu  Maximum pressure 350# and shut-in pressure  Remarks: Use 60/40 Pozmix 2% gel 3% cc by Sur  production casing.	Perfs 4118-25 4138-40  cement on top of sand through bailer  nulls, 10 sx gel, 50 sx cement, 10 sx gel  ag and pumped an additional 125 sx cement  250#  Cementing They recovered 2660' of 5 1/
Ist plug sand back to 4060 and dump 5 sx of 2nd plug squeezed through head with 2 sx half sack hulls and released 8 5/8" rubber plug Maximum pressure 350# and shut-in pressure Remarks: Use 60/40 Pozmix 2% gel 3% cc by Surproduction casing.  I hereby certify that the above plugging and that I (did / **********************************	Perfs 4118-25 4138-40  cement on top of sand through bailer  nulls, 10 sx gel, 50 sx cement, 10 sx gel  ag and pumped an additional 125 sx cement  250#  Cementing They recovered 2660' of 5 1/

INVOICED

DATE 3-5-54

INV. NO. OS/3

STATE CORPORATION COMMISSION

FEB 2 9 i984

Signed

Signed

(TECHNICIAN

FORM CP-2/3 Rev. 9-82

CONSERVATION DIVISION Wichita, Kansas