

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
500 INSURANCE BUILDING
212 NORTH MARKET
WICHITA, KANSAS 67202

FORM CP-1

RECEIVED
STATE CORPORATION COMMISSION
AUG 25 1969
CONSERVATION DIVISION
Wichita, Kansas

WELL PLUGGING APPLICATION FORM
File One Copy

8-25-69

Lease Owner Robert L. Austin

Address P. O. Box 159, Stafford, Kansas 67578

Lease (Farm Name) Cline Well No. 2

Well Location NE SW SE/4 Sec. 25 Twp. 24S Rge. 13W (E) (W)

County Stafford Field Name (If Any) _____

Total Depth 4160 Oil Well X Gas Well _____ Input Well _____ SWD Well _____ D & A _____

Well Log filed with application Yes or Well Log filed with Plugging Supervisor _____

Date and hour plugging is desired to begin Immediately

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of company representative in charge of plugging operations Robert L. Austin

P. O. Box 159 Address Stafford, Kansas

Plugging Contractor Ralph Comstock Casing & Pulling License No. 490

Address Stafford, Kansas 67578

Invoice covering assessment for plugging this well should be sent to Robert L. Austin

P. O. Box 159 Address Stafford, Kansas 67578

and payment will be guaranteed by applicant.

Signed: [Signature]
Applicant or Acting Agent

Date: August 22, 1969

State of Kansas



State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water)

500 Insurance Bldg.

212 N. Market

WICHITA, KANSAS 67202

August 25, 1969

WELL PLUGGING AUTHORITY

Well No.	2
Lease	Cline
Description	NE SW SE 25-24-13W
County	Stafford
Total Depth	4160
Plugging Contractor	Ralph Comstock Casing & Pulling


Robert L. Austin
Box 159
Stafford, Kansas 67578

Gentlemen:

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Very truly yours,


J. Lewis Brock, Administrator

Mr. R. J. Warren Box 322 Pratt, Kansas
is hereby assigned to supervise the plugging of the above named well.