STATE OF KANSAS STATE CORPORATION COMMISSION 200 Colorado Derby Building Wichita, Kansas 67202

## WELL PLUGGING RECORD K.A.R.-82-3-117

API	NUMBER_	015	20253	-00-00
,			_	

TYPE OR PRINT			
NOTICE: FIII out	completely		
and return to	Cons. Div.		
office within	30 days.		

LEASE NAME	Smith
WELL NUMBER	2
Ft.	from S Section Line

. 011	TICE WITH	in su day:	5.				
					_ ft. tro	m E Sec	tion Line
LEASE OPERATOR Flowers Production	on Co. I	nc.		sec. 7	_TWP.27	RGE. 8	_(E)&&\\\\\\
ADDRESS Box 249 El Dorado, Kansa	as 6704	2		COUNTY	Butle:	r	
PHONE#(316) 321 0550 OPERATORS L	ICENSE NO	64	107	Date We	11 Comple	ted	
Character of WellSWDFOR					g Commenc	$ed \frac{1}{}$	7/91
(Oll, Gas, D&A, SWD, Input, Water Sup	oply Well	)		Pluggin	g Complet	ed <u>1/</u> 2	29/91
The plugging proposal was approved or	1/2	9/91					(date)
Don Thompson				(KC	C Distric	t Agenti	s Name).
is ACO-1 filed? <u>ves</u> if not, i	is well l	og attache	ed?				
Producing Formation	Depth to Top		·	Bott	om	_T.D	3116 <b>'</b>
Show depth and thickness of all water	oil and	d gas form	nations	5 <b>.</b>			·
OIL, GAS OR WATER RECORDS	<u> </u>		CAS	NG RECO	RD		
Formation Content	From	To Size	Pi	ıt în	Pulled o	ut	

Formation	Content	From	То	Size	Put in	Pulled out
<del></del>		\-\	-	8 5/8	205	0
				5 ½	2847	0
·			_			

Describe in detail the manner in which the well was plugged, indicating where the mud fluid was placed and the method or methods used in introducing it into the hole. If cement or other plugs were used, state the character of same and depth placed, from feet to feet each set.

SEE_PAGE	2 (over)
	-Z-\DVEL)

(If additional description is necessary, use BACK of this form.)

Name of Plugging Contractor Dale Wilson W W Drilling Co. License No. 6012

Address RR #3 Box 66, El Dorado, Kansas 67042

NAME OF PARTY RESPONSIBLE FOR PLUGGING FEES: Dallas Flowers

STATE OF Kansas COUNTY OF Butler ,ss.

Dale Wilson (plugging contractor) (Employee of Operator) or (Operator) of above-described well, being first duly sworn on oath, says: That I have knowledge of the facts, statements, and matters herein contained and the log of the above-described well as filled that

the same are true and correct, so help me God.

(Signature) Wale Wilson

(Address) RR #3 Box 66, El Dorado, Ks 67042

SUBSCRIBED AND SWORN TO before me this 31st day of January ,19 91

My Commission Expires



Smith Well #2 SWD plugging report: Butler County, Kansas Sec 7, Twp 27, Rge 8 E.

1/7/91 Strung up 5" tools. Tools stopped @ 30' from top. Went through bridge. Tools stopped @ 90'. Run impression block . Slivers of tubing./ 1/9/91 Clean out with cherry picker to 95'. Bail scale & iron sulfide. Run impression block. no picture. 1/11/91 Put on drilling jars & bit. Drilling on iron @ 97' withbit & cherry picker. Run impression block. Got out sliver of pipe. 1/14/91 Dug cellar. Had swedge cut off of 8 5/8" & 5½" csg, United pumped down  $5\frac{1}{2}$ " csg. Circulated out 8 5/8" csg. Run 5' of 5 3/4 pipe between  $5\frac{1}{2}$  & 8 5/8 Csg. 1/15/91 Pulled 10' of  $5\frac{1}{2}$ " csg. Had plate welded on 8 5/8" csg. United pumped down 8 5/8" csq. Circulated on outside of 8 5/8" csq.

## 1/16 Rig down.

1/22/91 riq up.


Run 3 jts of 7 3/8" wash pipe. Washing over 5½" csg from 10' to 92'. 1/23/91

1/24/91 Washing over  $5\frac{1}{2}$ " csg from 92' to 97'. Pulled wash pipe and had

60' of 5½" csg inside of wash pipe. Run wash pipe & mill.

1/25/91 Milling over  $5\frac{1}{2}$ " csg from 97' to 107'. 1/28/91 Milling over  $5\frac{1}{2}$ " csg from 97' to 142'. Pulled wash pipe and mill.

Had 20' of  $5\frac{1}{2}$ " csg and tubing in wash pipe. 1/29/91 Run 7 jts of 3/4" pipe to 142'. United circulated 114 sacks of 60 40 pozmix cement & 2% gel from 142' to surface. Rig down.



7/91 Strung up 5" tools. Tools stopped @ 30' from top. Went through bridge. pls stopped @ 90'. Run impression block . Slivers of tubing./ )/91 Clean out with cherry picker to 95". Bail scale & iron sulfide. Run pression block. no picture. 11/91 Put on drilling jars & bit. Drilling on iron @ 97' withbit & cherry cker. Run impression block. Got out sliver of pipe. 14/91 Dug cellar. Had swedge cut off of 8 5/8" & 5½" csg, United pumped down "csg. Circulated out 8 5/8" csg. Run 5' of 5 3/4 pipe between 5½ & 8 5/8 Csg. 15/91 Pulled 10' of 5½" csg. Had plate welded on 8 5/8" csg. United pumped wn 8 5/8" csg. Circulated on outside of 8 5/8" csg.

## 16 Rig down.

22/91 rig up.

23/91 Run 3 jts of 7 3/8" wash pipe. Washing over 5½" csg from 10' to 92'. 24/91 Washing over 5½" csg from 92' to 97'. Pulled wash pipe and had

' of 5½" csg inside of wash pipe. Run wash pipe & mill.

25/91 Milling over 5½" csg from 97' to 107'.
28/91 Milling over 5½" csg from 97' to 142'. Pulled wash pipe and mill.

d 20' of 5½" csg and tubing in wash pipe.
29/91 Run 7 jts of 3/4" pipe to 142'. United circulated 114 sacks of 40 pozmix cement & 2% gel from 142' to surface. Rig down.