

15-095-17549-000

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner FORBES CASING PULLING CO. Address P.O. BOX 221, Great Bend, Kansas
(Applicant)

Lease (Farm Name) FREELAND Well No. 1

Well Location Well Site: Sw Sw Se S/2 NE/4 SE/4 Sec. 13 Twp. 27 Rge. (E) - (W) 10

County Kingman Field Name (if any) _____

Total Depth 4319 Oil Gas Dry Hole Dry

Was well log filed with application? no If not, explain: Will Follow

Date and hour plugging is desired to begin 1-9-56

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner _____

J.O. FORBES Address P.O. BOX 221, Great Bend, Kansas

Plugging Contractor FORBES CASING PULLING CO.

RECEIVED
STATE CORPORATION COMMISSION

Plugging Contractor's License No. 49 JAN 7 - 1956

Address P.O. BOX 221, Great Bend, Kansas

CONSERVATION DIVISION
Wichita, Kansas

Invoice covering assessment for plugging this well should be sent to _____

Forbes Casing Pulling Co. Address P.O. Box 221, Great Bend, Kansas

and payment will be guaranteed by applicant.

J. O. Forbes
Applicant or Acting Agent

Date 1-6-56

PLUGGING
FILE SEC. 13, TWP. 27, R. 10W
BOOK PAGE 29, LINE 45



15095-17549-0000

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

January 9, 1956

Well No.	1
Lease	Freeland SW-SW-SE
Description	S/2 NE SE 13-27-10W
County	Kingman
File No.	29-45

Forbes Casing Pulling Company
P. O. Box 221
Great Bend, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. M. A. Rives, Box B, Pratt, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

By S. S. Greider
S. S. Greider
WELL PLUGGING SUPERVISOR

cc:
District Plugging Supervisor