

STATE OF KANSAS
 STATE CORPORATION COMMISSION
 CONSERVATION DIVISION
 211 NORTH BROADWAY
 WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
 File One Copy

Lease Owner Theodore Gore Address 400 Brown Building, Wichita 2, Kansas
 (Applicant)

Lease (Farm Name) Koelsch Well No. 2

Well Location NE SE SE Sec. 23 Twp. 24 Rge. 14 ~~14~~ (W)

County Stafford Field Name (if any) Koelsch

Total Depth 3820 Oil Gas Dry Hole

Was well log filed with application? No If not, explain: _____

Will be filed with plugging data

Date and hour plugging is desired to begin as soon as contractor is available.

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner _____

Cleo Combs, Box 162, Address Russell, Kansas

Plugging Contractor R & S Pipe Pulling Company

Plugging Contractor's Licence No. _____

Address Russell, Kansas

Invoice covering assessment for plugging this well should be sent to _____

Theodore Gore Address 400 Brown Building, Wichita 2, Kansas

and payment will be guaranteed by applicant.

RECEIVED
 STATE CORPORATION COMMISSION

JUN 6 1956

Theodore Gore
 Applicant or Acting Agent

Date May 31, 1956

PLUGGING		CONSERVATION DIVISION	
FILE	SEC. <u>23</u>	T. <u>24</u>	R. <u>14</u>
BOOK	PAGE <u>68</u>	LINE	<u>29</u>

Wichita, Kansas



STATE OF KANSAS
 STATE CORPORATION COMMISSION
 CONSERVATION DIVISION
 211 NORTH BROADWAY
 WICHITA, KANSAS

June 6, 1956

Well No.	2
Lease	Koelsch
Description	NE SE SE 23-24-14W
County	Stafford
File No.	68-29

Theodore Gore
 400 Brown Building
 Wichita, Kansas

Dear Sir:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. R. M. Frundage, Box 283, Hoisington, Kansas.

STATE CORPORATION COMMISSION
 CONSERVATION DIVISION

By S. S. Greider
 S. S. Greider
 WELL PLUGGING SUPERVISOR

cc:
 District Plugging Supervisor