


Strike out upper line when reporting plugging off formations.

CASING RECORD

[illegible]

Mudded to 200'. Set 5 Sack Cement Plug at 200'. Mudded to 15' and set 3 sack cement Cap.



(If additional description is necessary, use BACK of this sheet)

Correspondence regarding this well should be addressed to..... The Barnsdall Oil Company
Address Box 2039, Tulsa, Okla.

STATE OF Oklahoma, COUNTY OF Tulsa, SS.
C. D. MILLER (employee of owner) or (~~owner or operator~~) of the above-described well,
 being first duly sworn on oath, says: That I have knowledge of the facts, statements, and matters herein contained and the log of the above-described well as filed and that the same are true and correct. So help me God.

(Signature) _____

Barnsdall Oil Co., Box 2039, Tulsa, Okla.
(Address)

SUBSCRIBED AND SWORN to before me this 18 day of September 1941

My commission expires... 1-22-42

Notary Public

BARNSDALL OIL COMPANY

LOG RECORD - M. SABIN C- #13

15-155-19184-0000

LOCATION:

990' N & 990' W of SE Cor of SE/4
of Sec. 11-23-4, Reno County, Kans

DRILLING COMM: 3/17/35

DRILLING COMP: 3/24/35

CASING RECORD:

10 3/4" OD LW & SS	40.5#	Set at 429.07 with 380 Sacks Cement
7" OD LW	24#	Set at 430' with 118 Sacks Cement

FORMATION:

Sand	0	28
Sand & Gravel	28	130
Sand & Shale	130	405
Shale & Gyp	405	455
Salt & Gyp	455	490
Shale	490	500

