	4 050478	DEC 3 1 1986	
To:	ORATION COMMISSION	API NUMBER 15- 095-21,	562-000
CONSERVATION DIVISION - PLUGGING SECTION 200 COLORADO DERBY BUILDING WICHITA, KANSAS 67202		NW, SEC31, 1	S, RW/&
		4705	from S section line
TECHNICIAN	'S PLUGGING REPORT	4125 feet 1	from E section line
Operator L	icense # 04915	Lease NameStucky	
	Montgomery Exploration	CountyKingman	148.8
Name& Address _	101 Park Avenue, Ste 1200		
_	Oklahoma City, OK 73102	Conductor Pipe: Size	-
_		Surface Casing: Size 8	
Abandoned (Oli Well Gas Well		
	as hereinafter indicated		
	ontractor_H-30		
	plug at: Hour: Day:		
	oposal received from_		
	, nme)		
•	35 sacks at 940'		
	35 sacks at 330'		
•	25 sacks at 60'		
	10 sacks in rathole		
	10 sacks in mousehole		
10 sac	ks in water well Plugging Prop	osal Received by Warren K	lirkpatrick
	3 3 3 4 4 5		TECHNICIAN)
Plugging Of	perations attended by Agent?: A		None <u>y</u>
Operations	Completed: Hour: 12:30 am Day:	21 Month: 12	Year:19 86
			
	GGING REPORT Run drilling pipe	to 940' and circulated hol	e with mud.
ACTUAL PLUC			
ACTUAL PLUC	GGING REPORT Run drilling pipe d 35 sacks cement. Pulled drill	ing pipe to 300' and spotte	ed 35 sacks cement.
Spotted Pulled	GGING REPORT Run drilling pipe	ing pipe to 300' and spotte	ed 35 sacks cement.
Spotted Pulled	GGING REPORT Run drilling pipe d 35 sacks cement. Pulled drill drilling pipe to 60' and spotte	ing pipe to 300' and spotte	ed 35 sacks cement.
Spotted Pulled	GGING REPORT Run drilling pipe d 35 sacks cement. Pulled drill drilling pipe to 60' and spotte	ing pipe to 300' and spotte ed 25 sacks cement. Circula	ed 35 sacks cement.
Spotted Pulled rathole	GGING REPORT Run drilling pipe d 35 sacks cement. Pulled drill drilling pipe to 60' and spotte e and mousehole and water well. B-J 284322	ing pipe to 300' and spotted 25 sacks cement. Circula S)A	ed 35 sacks cement. Ited cement in ITE CORPORATION COMMISSION CONSERVATION DAYSON
Spotted Pulled rathole	GGING REPORT Run drilling pipe d 35 sacks cement. Pulled drill drilling pipe to 60' and spotte e and mousehole and water well. B-J 284322 (If additional description is	ing pipe to 300' and spotted 25 sacks cement. Circula S)A	od 35 sacks cement. Ited cement in ITE CORPORATION COMMISSION CONSERVATION PROSERVA
Spotted Pulled rathole	GGING REPORT Run drilling pipe d 35 sacks cement. Pulled drill drilling pipe to 60' and spotte e and mousehole and water well. B-J 284322	ing pipe to 300' and spotted 25 sacks cement. Circula STA	od 35 sacks cement. Ited cement in ITE CORPORATION COMMISSION CONSERVATION PROSERVA
Spotted Pulled rathole	B-J 284322 (If additional description is	ing pipe to 300' and spotted 25 sacks cement. Circula S)A	ed 35 sacks cement. Ited cement in ITE CORPORATION COMMISSION CONSERVATION DAYSON

FORM CP-2/3 Rev.01-84