

15-003-20417-00-00

### KCC OIL/GAS REGULATORY OFFICES

Inspection Date 07/22/2016 District: 3 Incident Number: 5486

- New Situation  Lease Inspection  
 Response to Request  Complaint  
 Follow-up  Field Report

Operator License No: 31788 API: 15-003-20417-00-00 Q3 nw Q2: sw Q1: nw  
Operator Name: Veenker Resources, Inc. SEC 4 TWP 23 RGE 21 RGEDIR E  
Address: P.O. Box 14339 FSL: 3507  
City: Oklahoma City FEL: 4835  
State Oklaho Zip Code: 73113 Lease: MCCASLIN-VAN Well No.: 118  
Phone contact: 405-751-1414 County: AN

**Reason for Investigation:**

Request from Amy Banks in Wichita concerning the status of well #118 on the MCCASLIN-VAN BUSKIRK lease located in Section 4, Township 23 South, Range 21 East, Anderson County.

**Problem:**

In June 2016 Veenker Resources, Inc. #31788 filed a CP-111 TA form on well #118 on the MCCASLIN-VAN BUSKIRK lease located in Section 4, Township 23 South, Range 21 East, Anderson County. The operator had also filed a CP-4 plugging report on the same well in 2013.

**Persons contacted:**

Pumper of the lease.

**Findings:**

I located the well #118 by using the latitude 38.07648 and longitude -95.112589 in my GPS unit and it directed me within five (5) feet of the well location listed as being 3507 FSL and 4835 FEL of Section 4, Township 23 South, Range 21 East, Anderson County. The pumper of the lease also verified that the well #118 was at the location and that it was abandoned but it is not plugged. The operator inadvertently filed the CP-4 on the wrong well in 2013. The well #118 is not plugged. Picture #1 attached.

**Actions / Recommendation**

**Follow-up Required**

**Deadline Date:**

Forward information to Amy Banks Wichita Central Office confirming the status of well #118 on the MCCASLIN-VAN BUSKIRK lease. The well #118 is not plugged, the well is abandoned and has an approved TA form on file.

**Photo's Taken:** 1

RBDMS  KGS  TA DBF Report Prepared By: John Almond District #3  
 T1 DBF  District Files  Courthouse Position: Compliance Officer

# KCC DISTRICT III OFFICE FIELD REPORT PHOTO ID FORM



<b>Operator:</b>	Veenker Resources, Inc.	<b>KLN:</b>	#31788
<b>Lease:</b>	MCCASLIN-VAN BUSKIRK	<b>Legal:</b>	4/23/2021
<b>County</b>	Anderson	<b>PIC ID #:</b>	PICTURE #1
<b>Subject:</b>	Well #118	<b>Pic Orientation:</b>	Facing Northeast
<b>FEL:</b>	4835	<b>LATITUDE</b>	38.07648
<b>FSL:</b>	3507	<b>LONGITUDE</b>	-95.112589
<b>API#:</b>	15-003-20417-00-00		
<b>Date:</b>	7/22/2016	<b>TIME:</b>	9:30 AM
<b>Staff:</b>	John Almond		

## Additional Information:

Picture #1 shows the well #118 on the MCCASLIN-VAN BUSKIRK lease, I entered the lat and long into my GPS unit and it directed to to the well location. I also visited with the pumper of the lease and he assured me that this well is not plugged and I can see down into the casing, this well is not plugged, the landowner ran over this well with a bush hog, the operator inadvertently filed the wrong well number and location for the CP-4 in 2013. The well #118 is not plugged.