

15-179-19002-0000

INSPECTION REPORT

Case# _____

<input type="checkbox"/>	Complaint
<input type="checkbox"/>	New Situation
<input checked="" type="checkbox"/>	Response to request
<input type="checkbox"/>	Follow-up

Date of Inspection: December 14, 2015

Operator: Continental Oil Company

License: _____

Address: 3535 NW 58th St.

Location: NW-NW-SW-NE/4 Sec. 11-6-27W

City/St: Oklahoma City, Oklahoma

Lease: Adell LKC Unit # 308

Phone: _____

County: Sheridan

Reason for investigation: Response to request from compliance officer.

Problem: Incorrect location on scout card.

Findings:

- On the above reported date an inspection was conducted to determine the status of the Adell LKC Unit # 308.
- The scout card for the Adell LKC Unit # 308 incorrectly places the well @ W2-W2-NE/4 of section 2-6-27W. The surface casing was reported to be set @ 214 ft. 5 1/2 production casing was set @ 3849'. The scout card indicates 'input' well. The elevation was reported as 2624' KB. The API # is listed as 15-179-05507.
- The Adell LKC Unit # 308 located NW-NW-SW-NE/4 of section 11-6-27W is a plugged input well. The GPS location is -100.30028W & 39.54890N. The use of a metal detector was used to locate the well. The signal was weaker than normal. A 'step' appeared to have been excavated from a hillside that is large enough to set-up a drill rig. An area measuring approximately 15' X 12' was void of vegetation and is enduring severe erosion. It appears that the well is located in the eroded area.
- The operator's and technicians plugging reports indicate that the well was plugged on November 3, 1976 and witnessed by Conservation Agent, Gilbert Balthazor.

Photos: No

Action /recommendations:

- The information indicated by the plugging reports coincide with the pipe settings, elevation, top perforation, TD and spud date of May 10, 1962, identical to the scout card. An API # of 15-179-19,002 was assigned to the plugging reports. The well has been assigned two different API numbers.
- The well has been determined to have been plugged.
- This report will be submitted to the compliance officer for review.

Darrel Dipman ECRS
(agent)

Darrel Dipman
(signature)

cc: file