

INSPECTION REPORT

15-193-19001-00-00
15-193-19002-00-00

Case# _____

<input type="checkbox"/>	Complaint
<input type="checkbox"/>	New Situation
<input checked="" type="checkbox"/>	Response to request
<input type="checkbox"/>	Follow-up

Date of Inspection: February 8, 2016

Operator: John Ackard

License: Unknown

Address: _____

Location: E2 Sec. 24-7-34W

City/St: _____

Lease: Charles Murray # 1 & 2

Phone: _____

County: Thomas

Reason for investigation: Request by Compliance Officer.

Problem: Conformation of status of wells.

Findings:

- > On the above reported date research was conducted to determine the well status of the Charles Murray # 1 & 2 wells.
- > The Charles Murray # 1 located SE-SE-NE/4 is reported as a 'Doodlebug' or 'Core /Seismic' test well. The well was reported to have been drilled by a water well drilling rig to a depth of 428 feet. The well was commenced on October 29, 1941 with drilling being completed on November 19, 1941. It is unknown if the well was plugged or what method was utilized if plugged. The well is identified by two different API numbers. The old number is 15-193-19,001 and the new number of 15-193-15,258.
- > The Charles Murray # 2 located SE-SE-SE/4 is reported as being a dry hole. The well was drilled to a depth of 602 feet. The well was spudded on October 29, 1941 with drilling completed on November 12, 1941. It is un-known if the well was plugged or what method was utilized if plugged. The well is identified with two different API numbers. The old number being 15-193-19,002 and the new number of 15-193-15,259.

Photos: No

Action /recommendations:

- > There is limited information regarding both of these wells. The # 1 was reported as a test well. The # 2 may have been drilled for natural gas and is listed as being dry and abandoned. There is no indication of surface pipe having been set on either well.

Darrel Dipman ECRS
(agent)

Darrel Dipman
(signature)

cc: file

