

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner National Cooperative Refinery Association Address 305 Rule Building, Wichita, Kansas
(Applicant)

Lease (Farm Name) CARRICK "B" Well No. 2

Well Location NW SE SW Sec. 21 Twp. 30S Rge. 8 W () (W)

County Kingman Field Name (if any) Spivey-Grabs

Total Depth 4370 Oil Gas Dry Hole XX

Was well log filed with application? No If not, explain:

Will File When Available from Contractor.

Date and hour plugging is desired to begin At Once

Plugging of the well will be done in accordance with the Rules and Regulations of the State Corporation Commission.

Name of the person on the lease in charge of well for owner Lawrence Detmer

Address Box 6, Great Bend, Kansas

Plugging Contractor Virginia Drilling Company

Plugging Contractor's License No.

Address Brown Building, Wichita, Kansas

Invoice covering assessment for plugging this well should be sent to National Cooperative

Refinery Association Address 305 Rule Building, Wichita, Kansas

and payment will be guaranteed by applicant.

PLUGGING
FILE SEC. 21 T. 30 R. 8W
BOOK PAGE 35 LINE 34

C. R. Sears
Applicant or Acting Agent
C.R. Sears 8-13-57

Date August 12, 1957 RECEIVED
STATE CORPORATION COMMISSION

AUG 13 1957

CONSERVATION DIVISION
Wichita, Kansas



STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION

211 NORTH BROADWAY
WICHITA, KANSAS

August 14, 1957


Well No. 2
Lease Garrick "B"
Description NW SE SW 21-30-8W
County Kingman
File No. 35-34

National Cooperative Refinery Ass'n.
305 Rule Building
Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. M. A. Rives, Box 8, Pratt, Kansas.

Very truly yours,


Jewel M. Ogden
Director of Conservation Division

cc:
District Plugging Supervisor