## STATE OF KANSAS STATE CORPORATION COMMISSION

Give All Information Completely Make Required Affidavit Mail

15-009-15048-00-03

## WELL PLUGGING RECORD

make reduired willdavir			29 1WP 10 180 1	<u></u>
Mail or Deliver Report to	Location as "N	IE/CNW\SW\\" or foot	age from lines	
Conservation Division		BW NW NW		
State Corporation Comm.	Lease Owner	Kelso Casing Pu	olling	,
245 North Water	Lease Name	Esfeld #4	Well No.	
Wichita, KS 67202	Office Address	- · · · · · · · · · · · · · · · · · · ·	Kansas 67524	
			Oil, Gas or Dry Hole	)
		•		
	Date Well comp	1 at a d		19
		r plugging filed	<del></del>	<u>19</u>
		r plugging approve		${19}^{13}$
	Plugging comme	_		— <u>19</u> —
	Plugging compl	<del></del>	<del></del>	19
			or producing formation	
	reason for aba		=	"———
	Te a sussing	deplet	ed	
	II a producing	well is abandoned	i, date of last produc	
	<del></del>	1.6-4-1.6	O	19
Locale well correctly on above Section Fish			Conservation Division	on or
· · ·		ore plugging was o		
Name of Conservation Agent who		<u></u>	Rankin	<del></del>
Producing formation	Depth to t	·	Total Depth of Wel	<u>-3333</u>
Show depth and thickness of al	I water, oil and ga	s formations.		
ATT OF OR WARRED DESCRIPTION	•		•	
OIL, GAS OR WATER RECORDS	<del></del>		CASIN; REC	ORD
FDRMATION	CONTENT FROM	TE SIZE	PUT EN PULLEO DUT	r
		8-5/8	46 none	
		7"	511none	=
		411	3324 1516'	
plugs were used, state the cha feet for each pl		depth placed, from	nfeet	to 
Checked hole, bridge at 2035	moved bridge 301	with small weight	Got a injust of	<del></del>
2" tubing and moved bridge to	2210 sanded on t	on of bridge with	201 gand and 4 ganks	
cement. Welded on 42" slip o	n collar, shot pine	at 2041! 2016!	2001 19171 15161	
pulled 48 joints. Set rock b	ridge at 400 and r	an At yards of cem	ent on top	<del></del>
The state of the s	11180 01 400; 0110 1	an 42 Jarab or cem	<del></del>	
PLUGGING COMPLETE.	<del></del>	···	RECEIVED COMMISSION	<del></del>
	<del></del>	AT2	TE CORPORATION COMMITTEE 9-1	2 21
	<del></del>	211	<u></u>	<u>2-76</u>
<del></del>	<del></del>	<del>, , , ; ; ; , </del>	SEP 1319/6	<del></del>
	<u> </u>			·
(If additional	description is nece	ssary, use BACK of	this cheet MISTON	
Name of Plugging Contractor	KELSO CASING	PULLING	Wichita, Kansas	
- 4-7	CHASE, KANS	AS.		
•		• • •	•	
STATE OF	KANSAS COUNTY OF _	RICE	8a.	
<u> </u>		. ,	owner or operator) of the above-de	escribed
. well, being first duly sworn on oath, sa	ys: That I have knowledge of	the facts, statements, and ma	tters herein contained and the los	of the
above-described well as filed and that (	the same are true and correct.	So help me God.		
	(Signature)	Fland	19-12-	
	farkina		- June	<del></del>
	e e	CHASE, ]	(ANSAS (Address)	
SUNCERIBED AND SWORN TO before	me this 10th day	september		
	(aa)	- Specialor	19	
	<u>•</u>	- Man	raset Melcher	
My commission expires MOTARY PUBLIC M	ARGARET MELCHER	May	paret Melcher Notary Pr	ublic.
A COMMISSION EXPERIENCE	ARGARET MELCHER Rice County, Ks.	- May	vaset Meleker Notary Pi	ublic.
A A A	ARGARET MELCHER Rice County, Ks. Comm. Exp. Feb. 15, 1979		vaset Breleher Notary Pr	ublic.
A COMMISSION EXPERIENCE	Rice County Ke 1 .	May	paset <u>Melcher</u> Notary Pi	ublic.

## PRODUCTION DEPARTMENT

WORKOVER RECORD

	****	
`		
1.7		

SUBSEQUENT OPERATION NO.

		2.70				
D	age	• '			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
г	ane	•	U1.			
				24.	-1-	
:						- E i

		•	17	-007	-13 098-
District:	<u>Wichita</u>	٠.		٠. `	

	1cnita							
-ease:	isfeld 168 p.	110.	Well No.	Barton	Field:	Kreft-P Kansas	100	
Speration Commen		May 24, 19		,	Completed:			
Nature of Operatio		Acidize	(Dump Tres	••		حد .		
	1.54	6	•	7. 7		· · ·		
	* - £ -,		, <del>-</del> -		-			

Producing formation and interval before this workover: Douglas Sand

3324-3333

Douglas Sand: Producing formation and interval after this workover:

Qzztic Sand:

(Mark out choke size, etc., or pump size, etc. if not applicable)

		5.0	. '			1	CXXIII II I	j. • • •	ROST.D. Before Workover 3333
Dotes	Production	Bbls. Oil	Bbls. Water	MCF Gas	Prod. Method	Pump Size	Longth Stroke	S.P.M.	ROBET.D. After Workover 3333 (Mark out P.B. if not
3-14-66	Before workover, normal	3.54	18.61		Pump	1 <u>1</u> ti	30.	-3	applicable)
6-18-66	After workover, normal	6.04	29.96	•	Pump	1 <u>1</u> "	, 30	14	
	Potential after workover					,			

Datails of operation; all plugs, perforations, comenting, treatments, test, logs, etc., in chronological order.

Treated w/5 gals: Hy-Flo mixed w/10 bbls. oil. Dumped 150 gals. casing, filled casing with oil, let set 48 hours.

MAR 1.8 1976

CONSERVATION DIVISION Wichita, Kansas

(Continue on back if additional space required)

ments or Recommendations for additional recompletion work:

Distribution	
Dist.Prod	,
Field	
Denver Prod	1 12