

15-107-22771-00-00

KCC OIL/GAS REGULATORY OFFICES

Inspection Date 06/10/2016 District: 3 Incident Number: 5588

- New Situation
- Lease Inspection
- Response to Request
- Complaint
- Follow-up
- Field Report

Operator License No: 34239 API: Q3 Q2: Q1:
 Operator Name: Thornberry Family Partnershi SEC 10 TWP 23 RGE 22 RGEDIR E
 Address: PO Box 469 FSL:
 City: New Waverly FEL:
 State TX Zip Code: 77358 Lease: Cobb Well No.: 3-85
 Phone contact: (936) 344-7000 County: LN

Reason for Investigation:

Check status of "inactive" well.

Problem:

Operator says this well was never drilled.

Persons contacted:

Leland Jackson (620-363-0492)

Findings:

Well #3-85 (15-107-22771-00-00) is listed on the operator's well inventory as inactive, but the operator says that well was never drilled. Meet pumper Leland Jackson on lease to inspect the location and dig with a backhoe to see if casing can be found. There is a riser pipe from a flow line visible at the surface. Digging with the backhoe found no well casing at that location.

Well #3-85 was listed on a 2010 KCC GPS session sheet from a lease inspection. After reviewing KCC records, it appears this location is where well #4-85 (15-107-22772-00-00), was plugged as a dry hole on October 26, 1985, and that well #3-85 was never drilled.

Actions / Recommendation

Follow-up Required

Deadline Date:

Recommend changing well #3-85 from inactive to intent to drill. Have operator remove well #3-85 from their well inventory.

Photo's Taken: 0

- RBDMS
- KGS
- TA DBF
- Report Prepared By: Levi Short
- T1 DBF
- District Files
- Courthouse
- Position: ECRS

KCC OIL/GAS REGULATORY OFFICES

Additional Findings: