

15-015-40245-00-00

KCC OIL/GAS REGULATORY OFFICES

Date: 12/28/16

District: 02

Case #: _____

- New Situation
- Response to Request
- Follow-Up

- Lease Inspection
- Complaint
- Field Report

Operator License No: 5394

API Well Number: 15-015-40245-00-00

Op Name: R.R. ABDERHALDEN

Spot: SW Sec 10 Twp 27 S Rng 4 E / W

Address 1: 100 S. MAIN

Feet from N / S Line of Section

Address 2: STE 510

Feet from E / W Line of Section

City: WICHITA

GPS: Lat: _____ Long: _____ Date: _____

State: KS Zip Code: 67202

Lease Name: BATES Well #: 2

Operator Phone #: (316) 262-3411

County: Butler

Reason for Investigation:

TA / COMPLIANCE

Problem:

COULD NOT LOCATE WELL

Persons Contacted:

DWAIN STOUT / JR HOGOBOOM

Findings:

DAVID BOLLENBOCK LOCATED AREA OF WELL WITH METAL DETECTOR. MET WITH RRA DWAIN STOUT & DOZER OPERATOR JR HOGOBOOM. WITH THE USE OF DOZER & METAL DETECTOR WE COULD NOT LOCATE THE BATES #2. WE WORKED ON 2 DIFFERENT AREAS, WORKED AREA CIRCLE OF 200' AROUND EACH AREA, WE MOVED LOTS OF TREES & DIRT. DID NOT LOCATE ANY WELL CASINGS. WELL MUST BE PLUGGED.

Action/Recommendations:

Follow Up Required Yes No

Date: _____

CHANGE WELL STATUS TO PLUGGED

Verification Sources:

Photos Taken: NO

- | | | |
|--------------------------------------------------------------------|-----------------------------------------|-------------------------------------|
| <input type="checkbox"/> RBDMS | <input type="checkbox"/> KGS | <input type="checkbox"/> TA Program |
| <input type="checkbox"/> T-I Database | <input type="checkbox"/> District Files | <input type="checkbox"/> Courthouse |
| <input checked="" type="checkbox"/> Other: <u>LEASE INSPECTION</u> | | |

By: DUANE KRUEGER

Retain 1 Copy District Office
Send 1 Copy to Conservation Division

Form: 01/17/2017