Form CP-4

STATE OF KANSAS STATE CORPORATION COMMISSION

Give All Information Completely
Make Required Affidavit
Mail or Deliver Report to:
Conservation Division
State Corporation Commission
211 No. Broadway

WELL PLUGGING RECORD

			r tootomo tr	om lines	THE MISSION IN	
NORTH	Location as "N					
		Bachus Oi				_ Well Nol
						_ Well No
	Date well com		э. Он, Сав	or 1919 11010,		19
i l i	Application for	Application for plugging filed 12-19-63				
	Application for	Application for plugging approved 12-20-63				
	Plugging comm	Plugging commenced 1=1=0/1				
! ! !	Plugging comp	leted:		<u> </u>	<u> </u>	19
	Reason for aba	ndonment of well	or produci	ng formation	Dry	
i t						
						19
Locate well correctly on above				vation Division	or its agents bef	ore plugging was cor
Locate well correctly on above Section Plat	menced?	Ye:	S Amaka	T TO and the second		
me of Conservation Agent who s	supervised plugging of the	is well	WLCÚTE	. A. WIATUS	T . 1 D . 2 . 5	OE 20 H
ducing formation	 	Depth to top	Botto	om	Total Depth of	Well 25 (U F
ow depth and thickness of all wa	ster, on and gas requiation	us.				
OIL, GAS OR WATER RECO	ORDS				_	CASING RECORD
FURMATION	CONTENT	FROM	то	SIZE	PUT IN	PULLED OUT
4.0.000		, , , , , , , , , , , , , , , , , , , ,		5-5/8	327	None
	**************************************			1, 1/2	None	1859
		<u> </u>				
		<u>'</u>		<u> </u>		
Cleaning out cell Rigging up jacks.	Working pipe.	•	1 to 24	70° and 3 s		ment.
Cleaning out cell Rigging up jacks. Shot well at 2132 1945'. Working p Plugging well at Mudded to 40'. B	ar. Measured T. Working pipe. '. 'Working pipe ipe. Shot at 18	2. Shot at 864'. Pull-	2021:	70: and 3 s Working p	acks of ce	ment.
Shot well at 2132 1945. Working p	ar. Measured T. Working pipe. '. 'Working pipe ipe. Shot at 18	2. Shot at 864'. Pull-	2021:	70: and 3 s Working p	acks of ce	ment.
Shot well at 2132 1945. Working p	ar. Measured T. Working pipe. '. 'Working pipe ipe. Shot at 18	2. Shot at 864'. Pull-	2021:	70: and 3 s Working p	acks of ce	at ATION CONNESSION
Shot well at 2132 1945. Working p	ar. Measured T. Working pipe. '. 'Working pipe ipe. Shot at 18	2. Shot at 864'. Pull-	2021:	70! and 3 s Working p e. nd 25 sacks of cement.	acks of ce ipe. Shot of cement STATE CHRPOR	at ATION COMMISSION 8 1964
Shot well at 2132 1945. Working p	ar. Measured T. Working pipe. '. 'Working pipe ipe. Shot at 18	2. Shot at 864'. Pull-	2021:	70! and 3 s Working p e. nd 25 sacks of cement.	acks of ce ipe. Shot of cement STATE CORPOR	at ATION COMMISSION 8 1984 - 8 - 6 4
Shot well at 2132 1945. Working p	ar. Measured T. Working pipe. '. 'Working pipe ipe. Shot at 18	2. Shot at 864'. Pull-	2021:	70! and 3 s Working p e. nd 25 sacks of cement.	acks of ce ipe. Shot of cement STATE CORPOR	at Alion Commission 8 1984 - 8 - 6 4
Shot well at 2132 1945. Working p	ar. Measured T. Working pipe. '. 'Working pipe ipe. Shot at 18	2. Shot at 864'. Pull-	2021:	70! and 3 s Working p e. nd 25 sacks of cement.	acks of ce ipe. Shot of cement STATE CORPOR	at ATION COMMISSION 8 1984
Rigging up jacks. Shot well at 2132 1945'. Working p Plugging well at Mudded to 40'. B	ar. Measured T. Working pipe. '. Working pipe ipe. Shot at 18 270'. Building uild 10' rock br	e. Shot at. 864. Pull- 18 rock by ridge and 10	20211. 20211. ing pip ridge an	701 and 3 s Working p e. nd 25 sacks of cement.	acks of ce ipe. Shot of cement STATE CORPOR	at Alion Commission 8 1984 - 8 - 6 4
Rigging up jacks. Shot well at 2132 1945'. Working p Plugging well at Mudded to 40'. B	ar. Measured T. Working pipe. '. Working pipe ipe. Shot at 18 270'. Building uild 10' rock br	2. Shot at. 18' rock by ridge and 10 aldescription is necess	202);; ing pip ridge an) sacks	70! and 3 s Working p e. ad 25 sacks of cement.	acks of ce ipe. Shot of cement STATE CORPOR	at Alion Commission 8 1984 - 8 - 6 4
Rigging up jacks. Shot well at 2132 1945'. Working p Plugging well at Mudded to 40'. B	ar. Measured T. Working pipe. '. Working pipe ipe. Shot at 18 270'. Building uild 10' rock br	e. Shot at. 864. Pull- 18 rock by ridge and 10	202);; ing pip ridge an) sacks	70! and 3 s Working p e. ad 25 sacks of cement.	acks of ce ipe. Shot of cement STATE CORPOR	at ATION COMMISSION 8 1984
Rigging up jacks. Shot well at 2132 1945'. Working p Plugging well at Mudded to 40'. B	ar. Measured T. Working pipe. '. Working pipe ipe. Shot at 18 270'. Building uild 10' rock br	2. Shot at. 18' rock by ridge and 10 aldescription is necess	202);; ing pip ridge an) sacks	70! and 3 s Working p e. ad 25 sacks of cement.	acks of ce ipe. Shot of cement STATE CORPOR	at ATION COMMISSION 8 1984 - 8 - 6 4
Rigging up jacks. Shot well at 2132 1945. Working p Plugging well at Mudded to 40. B	ar. Measured T. Working pipe. '. Working pipe ipe. Shot at 18 270'. Building uild 10' rock br (If additional P. O. Box 221	aldescription is neces	202);; ing pip ridge an) sacks sary, use BA	70! and 3 s Working p e. and 25 sacks of cement.	acks of ce ipe. Shot of cement STATE CHRFOR JAN CONSERVAT	at Alion Commission 8 1984 - 8 - 6 4
Rigging up jacks. Shot well at 2132 1945'. Working p Plugging well at Mudded to 40'. B	ar. Measured T. Working pipe. '. Working pipe ipe. Shot at 18 270'. Building uild 10' rock br (If additional Processing	al description is neces Pulling, J Great F	2024!. 2024!. ing pip ridge and sacks sary, use BAG nc. Barton	701 and 3 s Working p e nd 25 sacks of cement.	acks of ce ipe. Shot of cement STATE CORFOR Vichita	at ATION COMMUSSION 8 1984 8 8 6 4 ION DIVISION Kansas
Rigging up jacks. Shot well at 2132 1945'. Working p Plugging well at Mudded to 40'. B me of Plugging Contractor dress ATE OF	ar. Measured T. Working pipe. '. Working pipe ipe. Shot at 18 270'. Building uild 10' rock br (If additions Forbes Casing P. O. Box 221	al description is neces Pulling, I Great I UNTY OF	2024! ing pip ridge ar) sacks Barton employee of	701 and 3 s Working p e. Morking p e. Mork	acks of ce ipe. Shot of cement STATE CHRFOR Vichita , ss. ner or operator)	at ATION COMMISSION 8 1984 8 -6 4 ION DIVISION Kansas
Rigging up jacks. Shot well at 2132 1945'. Working p Plugging well at Mudded to 40'. B me of Plugging Contractor Idress ATE OF	ar. Measured T. Working pipe. '. Working pipe ipe. Shot at 18 270'. Building uild 10' rock br (If additions Forbes Casing P. O. Box 221	al description is neces Pulling, I Great I UNTY OF	2024! ing pip ridge ar) sacks Barton employee of	701 and 3 s Working p e. Morking p e. Mork	acks of ce ipe. Shot of cement STATE CHRFOR Vichita , ss. ner or operator)	at ATION COMMUSSION 8 1984 FOR DIVISION Kansas
Rigging up jacks. Shot well at 2132 1945'. Working p Plugging well at Mudded to 40'. B me of Plugging Contractor dress ATE OF	ar. Measured T. Working pipe. '. Working pipe ipe. Shot at 18 270'. Building uild 10' rock br (If additions Forbes Casing P. O. Box 221	al description is neces Pulling, I Great F UNTY OF Inowledge of the and correct, Sp in	2024! ing pip ridge ar) sacks Barton employee of	701 and 3 s Working p e. Morking p e. Mork	acks of ce ipe. Shot of cement STATE CHRFOR Vichita , ss. ner or operator)	at ATION COMMISSION 8 1984 8 -6 4 ION DIVISION Kansas
Rigging up jacks. Shot well at 2132 1945. Working p Plugging well at Mudded to 40. B me of Plugging Contractor dress ATE OF	ar. Measured T. Working pipe. '. Working pipe ipe. Shot at 18 270'. Building uild 10' rock br (If additions Forbes Casing P. O. Box 221	al description is neces Pulling, I Great I UNTY OF	2024! ing pip ridge ar) sacks Barton employee of	701 and 3 s Working p e. Morking p e. Mork	acks of ce ipe. Shot of cement STATE CHRFOR Vichita , ss. ner or operator)	at ATION COMMUSSION 8 1984 FOR DIVISION Kansas
Rigging up jacks. Shot well at 2132 1945. Working p Plugging well at Mudded to 40. B mudded to 40. B Market of Language Contractor Market of Language	ar. Measured T. Working pipe. '. Working pipe ipe. Shot at 18 270'. Building uild 10' rock br (If additions Forbes Casing P. O. Box 221	al description is neces Pulling, I Great F UNTY OF Inowledge of the and correct, Sp in	2024! ing pip ridge ar) sacks Barton employee of	701 and 3 s Working p e. Morking p e. Mork	acks of ce ipe. Shot of cement STATE CHRFOR Vichita , ss. ner or operator)	at ATION COMMUSSION 8 1984 FOR DIVISION Kansas
Rigging up jacks. Shot well at 2132 1945'. Working p Plugging well at Mudded to 40'. B me of Plugging Contractor dress ATE OF Kansas J. O. Forbe all, being first duly sworn on oa ove-described well as filed and	ar. Measured T. Working pipe. '. Working pipe ipe. Shot at 18 270'. Building uild 10' rock br (If additions Forbes Casing P. O. Box 221	al description is neces Pulling J Creat I UNTY OF (Signature)	2021: 2021: ing pip ridge and sary, use BAC Bend, Kac Barton employee of facts, state ielp me Go	70! and 3 s Working p e. ad 25 sacks of cement. CK of this sheet) ansas f owner) or (ow ments, and matte	acks of ce ipe. Shot of cement STATE CORPOR JAN CONSERVAT Wichita , ss. ner or operator) ers herein conta	at ATION COMMISSION 8 1984 8 -6 4 ION DIVISION Kansas of the above descripted and the log of
Rigging up jacks. Shot well at 2132 1945'. Working p Plugging well at Mudded to 40'. B me of Plugging Contractor dress ATE OF	ar. Measured T. Working pipe. '. Working pipe ipe. Shot at 18 270'. Building uild 10' rock br (If additions Forbes Casing P. O. Box 221	al description is neces Pulling, I Great F UNTY OF Inowledge of the and correct, Sp in	2021: 2021: ing pip ridge and sary, use BAC Bend, Kac Barton employee of facts, state ielp me Go	701 and 3 s Working p e. Morking p e. Mork	acks of ce ipe. Shot of cement STATE CORPOR JAN CONSERVAT Wichita , ss. ner or operator) ers herein conta	at ATION COMMUSSION 8 1984 FOR DIVISION Kansas
Shot well at 2132 1945. Working p Plugging well at Mudded to 40. B ame of Plugging Contractor ddress TATE OF Kansas J. O. Forbeell, being first duly sworn on oacove-described well as filed and	ar. Measured T. Working pipe. '. Working pipe ipe. Shot at 18 270'. Building uild 10' rock br (If additiona Forbes Gasing P. O. Box 221 , CO es th, says: That I have to that the same are true a	al description is neces Pulling J Creat I UNTY OF (Signature)	2021: 2021: ing pip ridge and sary, use BAC Bend, Kac Barton employee of facts, state ielp me Go	70! and 3 s Working p e. ad 25 sacks of cement. CK of this sheet) ansas f owner) or (ow ments, and matte	acks of ce ipe. Shot of cement STATE CORPOR JAN CONSERVAT Wichita , ss. ner or operator) ers herein conta	at ATION COMMUSSION 8 1984 8 -64 ION DIVISION Kansas of the above descripted and the log of