

STATE OF KANSAS  
STATE CORPORATION COMMISSION  
CONSERVATION DIVISION  
P. O. BOX 17027  
Wichita, Kansas 67217

Rev. 3-15-72  
FORM CP-1

MAY 29 1975

WELL PLUGGING APPLICATION FORM  
File One Copy

5-29-75

Lease Owner Theodore I. Leben & Associates

Address 1555 East Second, Wichita, Kansas 67214

Lease (Farm Name) Neufeld Well No. 1

Well Location NE NW SE Sec. 24 Twp. 22S Rge. 2W (E)      (W) X

County Harvey Total Depth 3351' Field Name     

Oil Well      Gas Well      Input Well      SWD Well      Rotary D & A X

Well Log filed with application as required Yes

Date and hour plugging is desired to begin May 16, 1975 - 3:00 P.M.

PLUGGING OF THIS WELL WILL BE DONE IN ACCORDANCE WITH K.S.A. 55-128 OF THE RULES AND REGULATIONS OF THE STATE CORPORATION COMMISSION.

Name of company representative authorized to be in charge of plugging operations:

     Address     

Plugging Contractor Red Tiger Drilling Company License No.     

Address 1720 Wichita Plaza, Wichita, Kansas 67202

Invoice covering assessment for plugging this well should be sent to:

Name Theodore I. Leben & Associates

Address 1555 East Second, Wichita, Kansas 67214

and payment will be guaranteed by applicant or acting agent.

THEODORE I. LEBEN & ASSOCIATES

Signed: *Robert G. Brooks*  
Applicant or Acting Agent

Date: 5/28/75

State of Kansas



15-079-20232-0000

State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water)

P. O. Box 17027 3830 S. Meridian  
WICHITA, KANSAS 67217

May 20, 1975

WELL PLUGGING AUTHORITY

Well No.	1
Lease	R. Neufeld
Description	NE NW SE 24-22-2W
County	Harvey
Total Depth	3351
Plugging Contractor	Red Tiger Drlg.


T. I. Legen & Assoc.  
1555 East 2nd  
Wichita, Kansas 67214

Gentlemen:

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Yours very truly,

  
J. Lewis Brock, Administrator

Mr. ~~Hugh Scott, Box 924, McPherson, Kansas 67460~~  
is hereby assigned to supervise the plugging of the above  
named well.