

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
P. O. BOX 17027
WICHITA, KANSAS 67217

Rev. 6-3-74
FORM CP-1

WELL PLUGGING APPLICATION FORM
File One Copy

RECEIVED
STATE CORPORATION COMMISSION

SEP 21 1976
CONSERVATION DIVISION
Wichita, Kansas

9-21-76

API Number 15 - 083 - 20,490-0000 (of this well)
Lease Owner O. A. Sutton
Address 800 Sutton Place, Wichita, Kansas 67202
Lease (Farm Name) Korf Well No. 1
Well Location C SE SE Sec. 36 Twp. 22S Rge. (E) 22 (W)
County Hodgeman Total Depth 4562' Field Name _____
Oil Well _____ Gas Well _____ Input Well _____ SWD Well _____ Rotary D & A x
Well Log attached with this application as required Yes
Date and hour plugging is desired to begin _____

PLUGGING OF THIS WELL WILL BE DONE IN ACCORDANCE WITH K.S.A. 55-128 OF THE RULES AND REGULATIONS OF THE STATE CORPORATION COMMISSION.

Name of company representative authorized to be in charge of plugging operations:

_____ Address _____

Plugging Contractor Gabbert-Jones, Inc. License No. _____

Address 830 Sutton Place, Wichita, Kansas 67202

Invoice covering assessment for plugging this well should be sent to:

Name O. A. Sutton

Address 800 Sutton Place, Wichita, Kansas 67202

and payment will be guaranteed by applicant or acting agent.

Signed: Jack G. Paulsen
Jack G. Paulsen Applicant or Acting Agent

Date: September 20, 1976



State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water)
245 North Water
WICHITA, KANSAS 67202

September 9, 1976

WELL PLUGGING AUTHORITY

Well No.	1
Lease	Korf
Description	C SE SE Sec. 36-22-22W
County	Hodgeman
Total Depth	4562
Plugging Contractor	Gabbert-Jones Drilling Inc.


O. A. Sutton
800 Sutton Place
Wichita, Kansas 67202

Gentlemen:

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Yours very truly,


J. Lewis Brock, Administrator

Mr. ~~Clarence Thomas 403 Davis, Garden City, Kansas 67846~~
is hereby assigned to supervise the plugging of the above named well.