STATE OF KANSAS
STATE CORPORATION COMMISSION
200 Colorado Derby Building

WELL PLUGGING RECORD K.A.R.-82-3-117

API NUMBER 15-097-21,127-00-01

'200 Colorado Derby Bulle						
Wichita, Kansas 67202	aing		LEASE N	NAME Light		
$+rac{\hat{\mathbf{t}}_{i}_{i}p_{i}}{2}$	TYPE	OR PRINT	WELL NU	JMBER 1 (SWD)		
- P	NOTICE: FILL	out completel	Y.			
j., 9 1. (n to Cons. Div. Thin 30 days.	•	Ft. from S S	ection Lin	
				Ft. from E S	ection Lin	
LEASE OPERATOR Continental Energy			SEC3	SEC. 3 TWP. 285 RGE. 16W (E) or (W		
ADDRESS Box 918 Garden City, KS 67846			COUNTY	COUNTY Kiowa		
PHONE#(316) 276-8710	_OPERATORS LICENSE	NO. 5317	Date We	oll Completed _	·	
Character of Well <u>SWD</u>			Pluggin	Plugging Commenced 6-16-94		
(OII, Gas, D&A, SWD, Inp	out, Water Supply We	11)	_ Pluggin	g Completed	6-21-94	
The plugging proposal wa	s approved on				(date	
bySteve I	Pfeifer		(KC	C District Age	ni's Name)	
Is ACO-1 filed?	lf not, is wall	log attached?_	· · · · · · · · · · · · · · · · · · ·		o.	
roducing Formation	Dept	h to Top	Botte	omT.D	4820'	
show depth and thickness	of all water, oil	and gas formati	ons.			
OIL, GAS OR WATER RECOR	os	c	ASING RECO	RD	·	
		· · · · · · · · · · · · · · · · · · ·	····	,		
Formation Conte	nt From	To Size	Put in	Pulled out		
Formation Conte	nt From					
Formation Conte	nt From	8 5/8	432	none 2600'		
		8 5/8 4 1/2	432' 4819'	none 2600'	ud fluld	
escribe in detail the malaced and the method or ere used, state the clault box cellar & back worked pipe. Shot @ 26 pulled all pipe. Tore	anner in which the war methods used in in haracter of same a filled. Sanded bo 00', worked pipe, so down rig & tallied	8 5/8 4 1/2 vell was pluggentroducing it is and depth place ttom @ 4100' & wedged in, left pipe. Plugged	432' 4819' d, Indicating to the holed, from ran 4 sks on tension well down	none 2600' Ing where the m le. If cement of the feet to feet to shot on. Worked pip 8 5/8 casing w	or other p ot oach s @ 2800', e loose,	
escribe in detail the malaced and the method or ere used, state the current box cellar & back worked pipe. Shot @ 26 pulled all pipe. Tore hulls, 10 gel, 50 cemen	anner in which the war methods used in in haracter of same a filled. Sanded bo 00', worked pipe, so down rig & tallied	8 5/8 4 1/2 Well was plugged in troducing it is and depth place ttom @ 4100' & wedged in, left pipe. Plugged is, drop plug,	432' 4819' d, Indication to the holed, from ran 4 sks. on tension well down 150 cement	none 2600' Ing where the magnetic feet to feet to feet to feet makes and the second of the second	or other pot oach sed 2800', e loose, ith 300# 0/40 6% complete.	
escribe in detail the malaced and the method or ere used, state the consult box cellar & back worked pipe. Shot @ 260 pulled all pipe. Tore thulls, 10 gel, 50 cemen (if additional ame of Plugging Contract	anner in which the war methods used in in haracter of same a filled. Sanded bo 00', worked pipe, so down rig & tallied t, 10 gel, 100# hull description is necession.	8 5/8 4 1/2 Well was plugged ind depth place ttom @ 4100' & wedged in, left pipe. Plugged ls, drop plug, cossary, uso BA	432' 4819' d, Indication to the holed, from ran 4 sks on tension well down 150 cement CK of this	none 2600' Ing where the magnetic feet to feet to feet to feet makes and the second of the second	or other pot oach : @ 2800', e loose, ith 300# 0/40 6% complete.	
escribe in detail the malaced and the method or ere used, state the claused box cellar & back worked pipe. Shot @ 260 pulled all pipe. Tore hulls, 10 gel, 50 cemen (If additional ame of Plugging Contract	anner in which the war methods used in in haracter of same a filled. Sanded bo 00', worked pipe, so down rig & tallied t, 10 gel, 100# hull description is necession.	8 5/8 4 1/2 Well was plugged ind depth place ttom @ 4100' & wedged in, left pipe. Plugged ls, drop plug, cossary, uso BA	432' 4819' d, Indication to the holed, from ran 4 sks on tension well down 150 cement CK of this	none 2600' Ing where the m le. If cement of the total feet to	or other pot oach : @ 2800', e loose, ith 300# 0/40 6% complete.	
escribe in detail the malaced and the method or ere used, state the clause back worked pipe. Shot @ 260 pulled all pipe. Tore hulls, 10 qel, 50 cemen (If additional ame of Plugging Contract ddress P.O. Box 34	anner in which the war methods used in in haracter of same a filled. Sanded bo 00', worked pipe, so down rig & tallied t, 10 gel, 100# hull description is need to KELSO CASIN 17 Chase, Kansas	8 5/8 4 1/2 Well was plugged ind depth place ttom @ 4100' & wedged in, left pipe. Plugged ls, drop plug, cossary, uso BA	432' 4819' d, Indication to the hole of from ran 4 sks. on tension well down 150 cement CK of this	none 2600' Ing where the mode of the lift cement of the cement. Shot in. Worked pip 8 5/8 casing we have a shut in. 6 form.) Plugging leense No. 6/260	or other pot oach seed 2800', e loose, ith 300# 0/40 6% complete.	
escribe in detail the manage laced and the method or ere used, state the constitution box cellar & back worked pipe. Shot @ 260 pulled all pipe. Tore thulls, 10 gel, 50 cemen (if additional ame of Plugging Contract ddress P.O. Box 34	anner in which the war methods used in in haracter of same a filled. Sanded bo 00', worked pipe, so down rig & tallied t, 10 gel, 100# hull description is need to KELSO CASING TOWN TOWN TOWN TOWN TOWN TOWN TOWN TOWN	8 5/8 4 1/2 Well was plugged ind depth place throm @ 4100' & wedged in, left pipe. Plugged ls, drop plug, cossary, uso BA 1G PULLING, I 67524 Kelso Casing	432' 4819' d, indication to the hole of, from ran 4 sks on tension well down 150 cement CK of this NC. L	none 2600' Ing where the magnetic feet to feet to feement. Shot in. Worked pip 8 5/8 casing was Shut in. 6 form.) Plugging Icense No. 6/65	or other pot oach seed 2800', e loose, ith 300# 0/40 6% complete.	
escribe in detail the malaced and the method or ere used, state the consult box cellar & back worked pipe. Shot @ 26 pulled all pipe. Tore hulls, 10 gel, 50 cemen (if additional ame of Plugging Contract ddress P.O. Box 34 AME OF PARTY RESPONSIBLE TATE OF Kansas	anner in which the war methods used in in haracter of same a filled. Sanded bo 00', worked pipe, so down rig & tallied t, 10 gel, 100# hull description is need to KELSO CASING TOWN TOWN TOWN TOWN TOWN TOWN TOWN TOWN	8 5/8 4 1/2 Well was plugged ind depth place throm @ 4100' & wedged in, left pipe. Plugged ls, drop plug, cossary, uso BA 1G PULLING, I 67524 Kelso Casing	432' 4819' d, indication to the hole of, from ran 4 sks on tension well down 150 cement CK of this NC. L	none 2600' Ing where the magnetic feet to feet to feement. Shot in. Worked pip 8 5/8 casing was Shut in. 6 form.) Plugging Icense No. 6/65	or other pot oach seed 2800', e loose, ith 300# 0/40 6% complete.	
escribe in detail the malaced and the method or ere used, state the consult box cellar & back worked pipe. Shot @ 26 pulled all pipe. Tore hulls, 10 gel, 50 cemen (if additional ame of Plugging Contract ddress P.O. Box 34 AME OF PARTY RESPONSIBLE TATE OF Kansas	anner in which the war methods used in in haracter of same a filled. Sanded bo 00', worked pipe, so down rig & tallied t, 10 gel, 100# hull description is need to KELSO CASING FEES: COUNTY OF Trell Kelso	8 5/8 4 1/2 Vell was plugge atroducing it is and depth place ttom @ 4100' & wedged in, left pipe. Plugged ls, drop plug, cossary, use BA Kelso Casing Rice	432' 4819' d, Indicating the hole of the hole of the hole on tension well down 150 cement CK of this pulling,	none 2600' Ing where the magnetic of the second of the s	or other pot oach seed 2800', e loose, ith 300# 0/40 6% complete.	
escribe in detail the malaced and the method or ere used, state the consult box cellar & back worked pipe. Shot @ 26 pulled all pipe. Tore hulls, 10 gel, 50 cemen (if additional ame of Plugging Contract ddress P.O. Box 34 publications P.O. Box 34	anner in which the very methods used in in haracter of same a filled. Sanded bo 00', worked pipe, so down rig & tallied t, 10 gel, 100# hull description is need to KELSO CASING TO Chase, Kansas E FOR PLUGGING FEES: COUNTY OF Trell Kelso Ing first duly sworms herein contained as	8 5/8 4 1/2 Well was plugged it oddepth place ttom @ 4100' & wedged in, left pipe. Plugged ls, drop plug, cossary, uso BA Kelso Casing Rice On oath, says: and the log of the	432' 4819' d, Indicating the hole of the above of the hole of the	none 2600' Ing where the magnetic of the second of the s	or other pot oach a 2800', e 100se, ith 300# 0/40 6% complete 050///////////////////////////////////	
Describe in detail the management of the method or dere used, state the continuous particles and the method or dere used, state the continuous particles and pipe. Shot @ 26 pulled all pipe. Tore that the method is a possible of the property of the proper	anner in which the very methods used in in haracter of same a filled. Sanded bo 00', worked pipe, so down rig & tallied t, 10 gel, 100# hull description is need to KELSO CASING TO Chase, Kansas E FOR PLUGGING FEES: COUNTY OF Trell Kelso Ing first duly sworms herein contained as	8 5/8 4 1/2 Well was plugged it oddepth place ttom @ 4100' & wedged in, left pipe. Plugged ls, drop plug, cossary, uso BA Kelso Casing Rice On oath, says: and the log of d. (Signature)	432' 4819' d, indicating the hole of the	none 2600¹ Ing where the magnetic left comment of the state of the comment of the comment of the comment. Shot in the state of the st	or other pot oach seed 2800', eloose, ith 300# 0/40 6% complete. 550///////////////////////////////////	
Describe in detail the man of laced and the method or dere used, state the constitution of the method of the state of the constitution of the lace of	anner in which the very methods used in in haracter of same a filled. Sanded bo 00', worked pipe, so down rig & tallied t, 10 gel, 100# hull description is need to KELSO CASING TO Chase, Kansas E FOR PLUGGING FEES: COUNTY OF Trell Kelso Ing first duly sworms herein contained as	8 5/8 4 1/2 Vell was plugged it oddepth place ttom @ 4100' & wedged in, left pipe. Plugged ls, drop plug, cossary, uso BA IG PULLING, I 67524 Kelso Casing Rice On oath, says: Ind the log of the	432' 4819' d, Indicating the hole of from ran 4 sks on tension well down 150 cement CK of this NC. Imployee of That I had the above of P.O. Box	none 2600¹ Ing where the magnetic left comment of the state of the comment of the comment of the comment. Shot in the comment of the commen	or other pot oach seed 2800', eloose, ith 300# 0/40 6% complete. 050///////////////////////////////////	
Describe in detail the management of the content of	anner in which the very methods used in in haracter of same a filled. Sanded bo 00', worked pipe, so down rig & tallied t, 10 gel, 100# hull description is need to KELSO CASING TO Chase, Kansas E FOR PLUGGING FEES: COUNTY OF Trell Kelso Ing first duly sworms herein contained as	8 5/8 4 1/2 reli was pluggentroducing it indidepth place them @ 4100' & wedged in, left pipe. Plugged is, drop plug, cossary, uso BA G PULLING, I 67524 Kelso Casing Rice On oath, says: and the log of id. (Signature)	432' 4819' d, indicating the hole of the	none 2600¹ Ing where the magnetic left comment of the state of the comment of the comment of the comment. Shot in the comment of the commen	or other pot oach seed 2800', eloose, ith 300# 0/40 6% complete. 550///////////////////////////////////	

My Commission Expires:__

IREME HERZBERG
State of Kenses
My Appl. Etc. Aug. 24, 1897

Form CP-4