

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

15-155-19269-0000

Lease Owner The Texas Company Address 614 Bitting Building
(Applicant)
Lease (Farm Name) F. C. Hornbaker Well No. 4
Well Location SW SW NE Sec. 32 Twp. 23 Rge. 10W (E)-(W)
County Reno Field Name (if any) Zenith Peace Creek
Total Depth 3851' Oil X Gas Dry Hole
Was well log filed with application? No . If not, explain:
Will be filed with plugging record

Date and hour plugging is desired to begin 8:00 AM April 11, 1953

Plugging of the well will be done in accordance with the Rules and Regulations
of the State Corporation Commission, or with the approval of the following
exceptions: Explain fully and exceptions desired.

(Use an additional sheet if necessary)

Name of the person on the lease in charge of well for owner 4-11-53

R. M. Langdon Address Route 1, Raymond, Kansas


Name of Plugging Contractor R & S Pipe Pulling Company

Address Box 192, Ellinwood, Kansas

Invoice covering assessment for plugging this well should be sent to Wichita, Kansas

M. C. Harrell Address Box 1801, Wichita, Kansas

and payment will be guaranteed by applicant.



M. C. Harrell
Applicant or Acting Agent

Date April 10, 1953

RECEIVED
STATE CORPORATION COMMISSION

APR 11 1953

CONSERVATION DIVISION



STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
800 BITTING BUILDING
WICHITA, KANSAS

April 13, 1953

15-155-19269-0000

Well No. 4
Lease F. C. Hornbaker
Description S1 SW NE 32-23-10W
County Reno
File No. 52-9

The Texas Company,
P. O. Box 1801,
Wichita, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. Ruel Durkoo, Box 597, McPherson, Kansas.

STATE CORPORATION COMMISSION
CONSERVATION DIVISION

By J. P. Roberts
J. P. Roberts

cc: DISTRICT PLUGGING SUPERVISOR