## KCC OIL/GAS REGULATORY OFFICES

•	inspection Da	re 00/30/2010	District:	3	inc	ident Nu	mper:		5621
Operator License No: 33097 API: 15-003-21915-00-00 Q3 SW Q2: SW Q1: SO Operator Name: Southern Star Central Gas Pi SEC 14 TWP 21 RGE 19 RGEDIR E Address: 4700 Hwy, 56 FSL: 2 City: Owensboro FEL: 46 State KY Zip Code: 42301 Lease: BENJAMIN-KNIG Well No.: 5 Phone contact: 270-852-5000 County: AN Reason for Investigation: Operator requested inspection.  Problem: Well on inventory as status inactive, but operator says well found plugged in 2009.  Persons contacted: Buzzy Barker (785-448-7853); Charlie McConnell (270-852-5000)  Findings: According to the operator, in 2009 when preparing wells on the lease for plugging, they had the plugging contractor attempt to wash well #5 to TD. The contractor was only able to run the tubing in the production casing to approximately 10 feet. According to Southern Star, it appears well #5 had been previously plugged. On Oct. 6, 2009, all well locations on the lease were recorded by the KCC using a GPS unit. This well was recorded as "abandoned" at that time.  Actions / Recommendation Follow-up Required Deadline Date: Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.		[	☐ New Situation		🗆 Lease Ir	spection			
Operator License No: 33097 API: 15-003-21915-00-00 Q3 SW Q2: SW Q1: SOperator Name: Southern Star Central Gas Pi SEC 14 TWP 21 RGE 19 RGEDIR E Address: 4700 Hwy. 56 FSL: 2 City: Owensboro FEL: 46 State KY Zip Code: 42301 Lease: BENJAMIN-KNIG Well No: 5 Phone contact: 270-852-5000 County: AN Reason for Investigation:  Operator requested inspection.  Problem:  Well on inventory as status inactive, but operator says well found plugged in 2009.  Persons contacted:  Buzzy Barker (785-448-7853); Charlie McConnell (270-852-5000)  Findings:  According to the operator, in 2009 when preparing wells on the lease for plugging, they had the plugging contractor attempt to wash well #5 to TD. The contractor was only able to run the tubing in the production casing to approximately 10 feet. According to Southern Star, it appears well #5 had been proviously plugged. On Oct. 6, 2009, all well locations on the lease were recorded by the KCC using a GPS unit. This well was recorded as "abandoned" at that time.  Actions / Recommendation Follow-up Required Deadline Date:  Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.		[	Response to F	Request	Complai	nt			
Operator Name: Southern Star Central Gas Pi SEC 14 TWP 21 RGE 19 RGEDIR E Address: 4700 Hwy. 56 FSL: 2 City: Owensboro FEL: 46 State KY Zip Code: 42301 Lease: BENJAMIN-KNIG Well No.: 5 Phone contact: 270-852-5000' County: AN Reason for Investigation: Operator requested inspection.  Problem: Well on inventory as status inactive, but operator says well found plugged in 2009.  Persons contacted: Buzzy Barker (785-448-7853); Charlie McConnell (270-852-5000)  Findings: According to the operator, in 2009 when preparing wells on the lease for plugging, they had the plugging contractor attempt to wash well #5 to TD. The contractor was only able to run the tubing in the production casing to approximately 10 feet. According to Southern Star, it appears well #5 had been proviously plugged. On Oct. 6, 2009, all well locations on the lease were recorded by the KCC using a GPS unit. This well was recorded as "abandoned" at that time.  Actions / Recommendation Follow-up Required Deadline Date: Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.		] ب	☐ Follow-up		☑ Field Re	port			
Operator Name: Southern Star Central Gas Pi SEC 14 TWP 21 RGE 19 RGEDIR E Address: 4700 Hwy. 56 FSL: 2 City: Owensboro FEL: 46 State KY Zip Code: 42301 Lease: BENJAMIN-KNIG Well No.: 5 Phone contact: 270-852-5000' County: AN Reason for Investigation: Operator requested inspection.  Problem: Well on inventory as status inactive, but operator says well found plugged in 2009.  Persons contacted: Buzzy Barker (785-448-7853); Charlie McConnell (270-852-5000)  Findings: According to the operator, in 2009 when preparing wells on the lease for plugging, they had the plugging contractor attempt to wash well #5 to TD. The contractor was only able to run the tubing in the production casing to approximately 10 feet. According to Southern Star, it appears well #5 had been proviously plugged. On Oct. 6, 2009, all well locations on the lease were recorded by the KCC using a GPS unit. This well was recorded as "abandoned" at that time.  Actions / Recommendation Follow-up Required Deadline Date: Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.	Operator Licer	se No: 33097	API:	15-00	3-21915-00 <sup>-</sup>	-00 Q3	SW Q	2: SW	Q1: SW
Address: 4700 Hwy. 56 FSL: 2 City: Owensboro FEL: 46 State KY Zip Code: 42301 Lease: BENJAMIN-KNIG Well No.: 5 Phone contact: 270-852-5000 County: AN Reason for Investigation: Operator requested inspection.  Problem: Well on inventory as status inactive, but operator says well found plugged in 2009.  Persons contacted: Buzzy Barker (785-448-7853); Charlie McConnell (270-852-5000)  Findings: According to the operator, in 2009 when preparing wells on the lease for plugging, they had the plugging contractor attempt to wash well #5 to TD. The contractor was only able to run the tubing in the production casing to approxitmately 10 feet. According to Southern Star, it appears well #5 had been previously plugged. On Oct. 6, 2009, all well locations on the lease were recorded by the KCC using a GPS unit. This well was recorded as "abandoned" at that time.  Actions / Recommendation Follow-up Required Deadline Date: Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.	Operator Name	: Southern Star							
State KY Zip Code: 42301 Lease: BENJAMIN-KNIG Well No.: 5 Phone contact: 270-852-5000 County: AN  Reason for Investigation: Operator requested inspection.  Problem: Well on inventory as status inactive, but operator says well found plugged in 2009.  Persons contacted: Buzzy Barker (785-448-7853); Charlie McConnell (270-852-5000)  Findings: According to the operator, in 2009 when preparing wells on the lease for plugging, they had the plugging contractor attempt to wash well #5 to TD. The contractor was only able to run the tubing in the production casing to approxitmately 10 feet. According to Southern Star, it appears well #5 had been previously plugged. On Oct. 6, 2009, all well locations on the lease were recorded by the KCC using a GPS unit. This well was recorded as "abandoned" at that time.  Actions / Recommendation Follow-up Required Deadline Date: Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.	•						FSL:		209
Phone contact: 270-852-5000 County: AN  Reason for Investigation:  Operator requested inspection.  Problem:  Well on inventory as status inactive, but operator says well found plugged in 2009.  Persons contacted:  Buzzy Barker (785-448-7853); Charlie McConnell (270-852-5000)  Findings:  According to the operator, in 2009 when preparing wells on the lease for plugging, they had the plugging contractor attempt to wash well #5 to TD. The contractor was only able to run the tubing in the production casing to approximately 10 feet. According to Southern Star, it appears well #5 had been previously plugged. On Oct. 6, 2009, all well locations on the lease were recorded by the KCC using a GPS unit. This well was recorded as "abandoned" at that time.  Actions / Recommendation Follow-up Required Deadline Date:  Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.  Photo's Taken: 0  Photo's Taken: 0	City: Ower	ısbora					FEL:		4653
Reason for Investigation:  Operator requested inspection.  Problem:  Well on inventory as status inactive, but operator says well found plugged in 2009.  Persons contacted: Buzzy Barker (785-448-7853); Charlie McConnell (270-852-5000)  Findings:  According to the operator, in 2009 when preparing wells on the lease for plugging, they had the plugging contractor attempt to wash well #5 to TD. The contractor was only able to run the tubing in the production casing to approxitmately 10 feet. According to Southern Star, it appears well #5 had been previously plugged. On Oct. 6, 2009, all well locations on the lease were recorded by the KCC using a GPS unit. This well was recorded as "abandoned" at that time.  Actions / Recommendation Follow-up Required Deadline Date: Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.  Photo's Taken: 0  Photo's Taken: 0	State KY	Zip Code: 42	301 <b>L</b> e	ease: E	BENJAMIN-K	NIG We	II No.:	5	
Problem:  Well on inventory as status inactive, but operator says well found plugged in 2009.  Persons contacted: Buzzy Barker (785-448-7853); Charile McConnell (270-852-5000)  Findings: According to the operator, in 2009 when preparing wells on the lease for plugging, they had the plugging contractor attempt to wash well #5 to TD. The contractor was only able to run the tubing in the production casing to approxitmately 10 feet. According to Southern Star, it appears well #5 had been previously plugged. On Oct. 6, 2009, all well locations on the lease were recorded by the KCC using a GPS unit. This well was recorded as "abandoned" at that time.  Actions / Recommendation Follow-up Required □ Deadline Date: Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.  Photo's Taken: 0  Photo's Taken: 0	Phone contact	<b>:</b> 270-852-5	000			County	: AN		
Problem:  Well on inventory as status inactive, but operator says well found plugged in 2009.  Persons contacted: Buzzy Barker (785-448-7853); Charlie McConnell (270-852-5000)  Findings: According to the operator, in 2009 when preparing wells on the lease for plugging, they had the plugging contractor attempt to wash well #5 to TD. The contractor was only able to run the tubing in the production casing to approxitmately 10 feet. According to Southern Star, it appears well #5 had been previously plugged. On Oct. 6, 2009, all well locations on the lease were recorded by the KCC using a GPS unit. This well was recorded as "abandoned" at that time.  Actions / Recommendation Follow-up Required Deadline Date: Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.  Photo's Taken: 0  Photo's Taken: 0	Reason for Inv	estigation:							
Persons contacted: Buzzy Barker (785-448-7853); Charlie McConnell (270-852-5000)  Findings: According to the operator, in 2009 when preparing wells on the lease for plugging, they had the plugging contractor attempt to wash well #5 to TD. The contractor was only able to run the tubing in the production casing to approxitmately 10 feet. According to Southern Star, it appears well #5 had been previously plugged. On Oct. 6, 2009, all well locations on the lease were recorded by the KCC using a GPS unit. This well was recorded as "abandoned" at that time.  Actions / Recommendation Follow-up Required □ Deadline Date: Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.  Photo's Taken: 0  Photo's Taken: 0	Operator reques	sted inspection.							
Persons contacted: Buzzy Barker (785-448-7853); Charlie McConnell (270-852-5000)  Findings: According to the operator, in 2009 when preparing wells on the lease for plugging, they had the plugging contractor attempt to wash well #5 to TD. The contractor was only able to run the tubing in the production casing to approxitmately 10 feet. According to Southern Star, it appears well #5 had been previously plugged. On Oct. 6, 2009, all well locations on the lease were recorded by the KCC using a GPS unit. This well was recorded as "abandoned" at that time.  Actions / Recommendation Follow-up Required □ Deadline Date: Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.  Photo's Taken: 0  Photo's Taken: 0									
Persons contacted: Buzzy Barker (785-448-7853); Charlie McConnell (270-852-5000)  Findings: According to the operator, in 2009 when preparing wells on the lease for plugging, they had the plugging contractor attempt to wash well #5 to TD. The contractor was only able to run the tubing in the production casing to approxitmately 10 feet. According to Southern Star, it appears well #5 had been previously plugged. On Oct. 6, 2009, all well locations on the lease were recorded by the KCC using a GPS unit. This well was recorded as "abandoned" at that time.  Actions / Recommendation Follow-up Required Deadline Date: Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.  Photo's Taken: 0  Photo's Taken: 0									
Buzzy Barker (785-448-7853); Charlie McConnell (270-852-5000)  Findings:  According to the operator, in 2009 when preparing wells on the lease for plugging, they had the plugging contractor attempt to wash well #5 to TD. The contractor was only able to run the tubing in the production casing to approxitmately 10 feet. According to Southern Star, it appears well #5 had been previously plugged. On Oct. 6, 2009, all well locations on the lease were recorded by the KCC using a GPS unit. This well was recorded as "abandoned" at that time.  Actions / Recommendation Follow-up Required □ Deadline Date:  Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.  Photo's Taken: 0  ■ RBDMS ■ KGS □ TA DBF Report Prepared By: Levi Short	Well on inventor	ry as status inacti	ve, but operator s	says well	found plugge	ed in 200	9.		
Buzzy Barker (785-448-7853); Charlie McConnell (270-852-5000)  Findings:  According to the operator, in 2009 when preparing wells on the lease for plugging, they had the plugging contractor attempt to wash well #5 to TD. The contractor was only able to run the tubing in the production casing to approxitmately 10 feet. According to Southern Star, it appears well #5 had been previously plugged. On Oct. 6, 2009, all well locations on the lease were recorded by the KCC using a GPS unit. This well was recorded as "abandoned" at that time.  Actions / Recommendation Follow-up Required □ Deadline Date:  Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.  Photo's Taken: 0  ■ RBDMS ■ KGS □ TA DBF Report Prepared By: Levi Short	D				į•				
Findings:  According to the operator, in 2009 when preparing wells on the lease for plugging, they had the plugging contractor attempt to wash well #5 to TD. The contractor was only able to run the tubing in the production casing to approxitmately 10 feet. According to Southern Star, it appears well #5 had been previously plugged. On Oct. 6, 2009, all well locations on the lease were recorded by the KCC using a GPS unit. This well was recorded as "abandoned" at that time.  Actions / Recommendation Follow-up Required Deadline Date:  Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.  Photo's Taken: 0  RBDMS KGS TADBF Report Prepared By: Levi Short		<del></del>							
According to the operator, in 2009 when preparing wells on the lease for plugging, they had the plugging contractor attempt to wash well #5 to TD. The contractor was only able to run the tubing in the production casing to approxitmately 10 feet. According to Southern Star, it appears well #5 had been previously plugged. On Oct. 6, 2009, all well locations on the lease were recorded by the KCC using a GPS unit. This well was recorded as "abandoned" at that time.  **Actions / Recommendation Follow-up Required Deadline Date:  Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.  **Photo's Taken: 0  **Photo's Taken: 0  **RBDMS ***ERBDMS ***CGS ***ITA DBF Report Prepared By: Levi Short	Buzzy Barker (1	785-448-7853); C	harlie McConnell	(270-85	2-5000)				
According to the operator, in 2009 when preparing wells on the lease for plugging, they had the plugging contractor attempt to wash well #5 to TD. The contractor was only able to run the tubing in the production casing to approxitmately 10 feet. According to Southern Star, it appears well #5 had been previously plugged. On Oct. 6, 2009, all well locations on the lease were recorded by the KCC using a GPS unit. This well was recorded as "abandoned" at that time.  **Actions / Recommendation Follow-up Required Deadline Date:  Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.  **Photo's Taken: 0  **Photo's Taken: 0  **RBDMS ***ERBDMS ***CGS ***ITA DBF Report Prepared By: Levi Short	, Finalina.								
plugging contractor attempt to wash well #5 to TD. The contractor was only able to run the tubing in the production casing to approxitmately 10 feet. According to Southern Star, it appears well #5 had been previously plugged. On Oct. 6, 2009, all well locations on the lease were recorded by the KCC using a GPS unit. This well was recorded as "abandoned" at that time.  **Actions / Recommendation Follow-up Required Deadline Date:  Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.  **Photo's Taken: 0  **Phot									
Actions / Recommendation Follow-up Required Deadline Date:  Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.  Photo's Taken:  O RBDMS KGS TADBF Report Prepared By: Levi Short	plugging contract	ctor attempt to wa	ish well #5 to TD	. The cor	ntractor was o	only able	to run th	e tubing	
Actions / Recommendation Follow-up Required Deadline Date:  Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.  Photo's Taken: 0  RBDMS KGS TADBF Report Prepared By: Levi Short	previously plugg	jed. On Oct. 6, 20	109, all well locati	ons on th	ne lease were				
Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.  Photo's Taken:  RBDMS KGS TA DBF Report Prepared By: Levi Short	GPS unit. This v	vell was recorded	as "abandoned"	at that ti	me.				_
Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.  Photo's Taken:  RBDMS KGS TA DBF Report Prepared By: Levi Short									
Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.  Photo's Taken:  RBDMS KGS TA DBF Report Prepared By: Levi Short									
Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.  Photo's Taken:  RBDMS KGS TA DBF Report Prepared By: Levi Short									
Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.  Photo's Taken:  RBDMS KGS TA DBF Report Prepared By: Levi Short									
Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.  Photo's Taken:  RBDMS KGS TA DBF Report Prepared By: Levi Short					4				
Enter latitude and longitude for well and indicate plugged. Remove the "inactive" well from the Southern Star well inventory.  Photo's Taken:  RBDMS KGS TA DBF Report Prepared By: Levi Short	Actions / Reco	mmendation	Follow-up F	Required		Deadline	Date:		
Southern Star well inventory.  Photo's Taken: 0  RBDMS KGS TA DBF Report Prepared By: Levi Short				• •				tho	
☑ RBDMS ☑ KGS ☐ TA DBF Report Prepared By: Levi Short			and molcate p	ruggeu. r	veillove lite	mactive	well itoli	i tile	
☑ RBDMS ☑ KGS ☐ TA DBF Report Prepared By: Levi Short									
☑ RBDMS ☑ KGS ☐ TA DBF Report Prepared By: Levi Short									
☑ RBDMS ☑ KGS ☐ TA DBF Report Prepared By: Levi Short									
☑ RBDMS ☑ KGS ☐ TA DBF Report Prepared By: Levi Short					-				
	7 pp=144		T. 555	_					U
☐ T1 DBF ☑ District Files ☐ Courthouse <b>Position:</b> <u>ECRS</u>	∠I RBDMS	¥ KG5 ∐	TA DBF	Report	Prepared By	: Levi S	short		
	T1 DBF	☑ District Files	☐ Courthouse	Po	sition: <u>EC</u>	CRS			