

## KCC OIL/GAS REGULATORY OFFICES

Inspection Date 01/26/2017 District: 3 Incident Number: 5669

- ☐ New Situation ☐ Lease Inspection  
☒ Response to Request ☐ Complaint  
☐ Follow-up ☒ Field Report

Operator License No: 6279 API: 15-207-02206-00-01 Q3 SE Q2: NE Q1: NE

Operator Name: Patrick Development Corp SEC 19 TWP 26 RGE 17 RGEDIR E

Address: 3408 W 93 Rd

FSL: 4320

City: Leawood

FEL: 145

State KS Zip Code: 66206

Lease: Gray

Well No.: N-17

Phone contact: 913-375-8368

County: WO

E-08990

### Reason for Investigation:

To try and locate well and determine the status of the well.

### Problem:

No well at the location provided.

### Persons contacted:

James Haclarod, pumper, 620-363-0062

### Findings:

I met with James Haclarod, pumper for Patrick Development, to locate well #N-17 on the Gray Lease. KCC staff had previously tried to locate this well and noted with a field report that this well was not at the given location. Mr. Haclarod and I looked for the well and determined there was no well at this location.

### Actions / Recommendation

### Follow-up Required ☐

### Deadline Date:

Refer my findings to Larry Marchant, District #3 UIC Coordinator, and recommend that this well be removed from Docket #E-08990 and removed from Patrick Development License.

### Photo's Taken:

0

☒ RBDMS ☐ KGS ☐ TA DBF

Report Prepared By: Ryan Duling

☐ T1 DBF ☒ District Files ☐ Courthouse

Position: E.C.R.S.

# KCC OIL/GAS REGULATORY OFFICES

Inspection Date 08/24/2015 District: 3 Incident Number: 5392

☒ New Situation ☐ Lease Inspection  
☐ Response to Request ☐ Complaint  
☐ Follow-up ☒ Field Report

Operator License No: 6279 API: 15-207-02206-00-01 Q3 SE Q2: NE Q1: NE  
Operator Name: Patrick Development Corporat SEC 19 TWP 26 RGE 17 RGEDIR E  
Address: 3408 W. 93rd St. FSL: 4320  
City: Leawood FEL: 145  
State KS Zip Code: 66206 Lease Gray Well No.: N 17  
Phone contact: 913-381-2814 County: WO

## Reason for Investigation:

A MIT was due for well #N 17. Well could not be located at the time the test was suppose to be performed. Staff went back to investigate and try to locate well. Docket #E-08990

## Problem:

No well at the listed location.

## Persons contacted:

*MIT Due 8/10/2015*

## Findings:

Larry Marchant, District #3 UIC Coordinator, and I arrived on location in the morning of 08/24/2015. I downloaded the coordinates for well #N 17 into the gps device. We arrived at the correct site were well # N17 was suppose to be drilled. No well was present at this location. A metal detector was used and no well could be located in area 100' from the desired location.

## Actions / Recommendation

Follow-up Required ☐

Deadline Date:

The operator needs to locate the well or turn in an U-5 and cancel the authorization for this well.

Photo's Taken: 0

☒ RBDMS ☐ KGS ☐ TA DB Report Prepared By Ryan Duling  
☐ T1 DBF ☒ District Files ☐ Courthouse Position: PIRT II