¹050478

TO: State corf	2010 A 1 1 1 1 M 1 1 1 C			. CU NT	are -	F (2)		* 00	_		
CONSERVATI	ON DIVISIO	N - PLUG	GING SECTION	A DW ME	SW , S	EU	_27		5,	R 13	
200 COLORA Wichita, K	NDO DERBY E Kansas 672	101LD1NG 202			1650)	feet	from	\$ se	action	iln
	N'S PLUGGII				3630)	feet	from	£ 50	e c tlon	l i n
Operator L	.ícense 🐔	5146		Lea	se Name	Broo	lie	No:) # <u>_</u>	1	
			son Dil Co.	, Inc. Cou	unty		Staffo	ord_		125	.09
Names Address	435 P.a	•			II Total						
		Douglas			nductor						_
	Wichit	a, KS 672	.02	Sur							
Abandoned	Oll Well_	X	Gas Well								
Other well	t as herei	nafter in	dicated			 -					
			sing Pullin	1							
			ase, KS 675		·					-	
			:00 am_ Day		Mont	h:	March	,	Year:	19 85	
• •	_		rom								
riugging (ριυρυsαι Γ	Kelso			_					 938-:	2457
(company r	name)	10020						(Dhone	8) -		
				 .							
			7' Open Ho								
were:	5 1/2" s	et at 384		le							
were:	5 1/2" s	et at 384 to 3800'	7' Open Ho	le sx cement	on top	of s	and				
were:	5 1/2" s sand back squeeze we	et at 384 to 3800'	7' Open Ho	le sx cement	on top	of s	and				
lst plug : 2nd plug :	5 1/2" s sand back squeeze we	et at 384 to 3800'	7' Open Ho	le sx cement	on top	of s	and				
lst plug : 2nd plug :	5 1/2" s sand back squeeze we	et at 384 to 3800'	and dump 5 sx hulls,	sx cement 10 sx gel	on top	of sa	and nt, 10	sx gel	, 1 s		
lst plug : 2nd plug :	5 1/2" s sand back squeeze we	et at 384 to 3800'	7' Open Ho	sx cement 10 sx gel	on top	of sa	and nt, 10	sx gel	, 1 s	sack h	
lst plug : 2nd plug : and 100 s:	5 1/2" s sand back squeeze we x cement.	et at 384 to 3800'	and dump 5 sx hulls,	sx cement 10 sx gel	on top , 50 sx	of sacemen	and nt, 10 Paul A	sx gel	, 1 s	sack h	
lst plug : 2nd plug : and 100 s:	5 1/2" s sand back squeeze we x cement. Operations	et at 384 to 3800' 11 with 3	and dump 5 sx hulls, Plugging P	sx cement 10 sx gel roposal R	on top , 50 sx	of society	and nt, 10 Paul A	sx gel	, 1 s	sack h	ulls,
lst plug : 2nd plug : and 100 s: Plugging	5 1/2" s sand back squeeze we x cement. Operations s Complete	et at 384 to 3800' 11 with 3 aftended d: Hour:	open Ho and dump 5 sx hulls, Plugging P by Agent?:	sx cement 10 sx gel roposal R All x	on top , 50 sx ecelved	of sacemen	and nt, 10 Paul A	sx gel	i NICIA one	N)	ulls,
lst plug : 2nd plug : and 100 s: Plugging Operation ACTUAL PL	5 1/2" s sand back squeeze we x cement. Operations s Complete UGGING REP	et at 384 to 3800' 11 with 3 aftended d: Hours	and dump 5 and dump 5 sx hulls, Plugging P by Agent?: 10:30 am Da plug sanded	sx cement 10 sx gel roposal R Ail x y: 11 back to	eceived Mon 3800' ar	of sacement	Paul A	sx gel	i NICIA one Year:	19 85	ulls,
lst plug : 2nd plug : and 100 s: Plugging Operation ACTUAL PL of sand t	5 1/2" s sand back squeeze we x cement. Operations s Complete UGGING REP hrough bai	attended to 3800' 11 with 3 attended Hours ORT 1st ler. 2nd	Plugging P by Agent?: 10:30 am Da plug squeez	sx cement 10 sx gel roposal R Ai!x y:11. back to ded well w	eceived Mon 3800' ar	of sacement	Paul A March mped 5	sx gel	i NICIA one Year: ment c	19 85	ulls,
lst plug : 2nd plug : and 100 s: Plugging Operation ACTUAL PL of sand t	5 1/2" s sand back squeeze we x cement. Operations s Complete UGGING REP hrough bai	attended to 3800' 11 with 3 attended Hours ORT 1st ler. 2nd	and dump 5 and dump 5 sx hulls, Plugging P by Agent?: 10:30 am Da plug sanded	sx cement 10 sx gel roposal R Ai!x y:11. back to ded well w	eceived Mon 3800' ar	of saccement	Paul A March mped 5	sx gel A. Luth (TECH Sx cem sx gel	i NICIA one Year: ment c	n) 19 85 on top	ulls,
lst plug : 2nd plug : and 100 s: Plugging Operation ACTUAL PL of sand t	5 1/2" s sand back squeeze we x cement. Operations s Complete UGGING REP hrough bai	attended to 3800' 11 with 3 attended Hours ORT 1st ler. 2nd	Plugging P by Agent?: 10:30 am Da plug squeez	sx cement 10 sx gel roposal R Ai!x y:11. back to ded well w	eceived Mon 3800' ar	of saccement	Paul A March mped 5 1s, 10	SX gel A. Luth (TECH SX cem SX gel RECEIVE	i NICIA OneYear: ment co., 50	n) 19 85 on top	ulls,
lst plug: 2nd plug: and 100 s: Plugging Operation ACTUAL PL of sand t 10 sx gel	5 1/2" s sand back squeeze we x cement. Operations s Complete UGGING REP hrough bai , 1 sack h	attended attended attended to 3800' Il with 3 Attended to Hours ORT lst Ier. 2nd ulls and	and dump 5 and dump 5 sx hulls, Plugging P by Agent?: 10:30 am Da plug sanded plug squeez 100 sx ceme	sx cement 10 sx gel roposal R All _x y: 11 back to ed well went.	eceived Mon 3800' ar	of saccement	Paul A March mped 5 ls, 10 TATE CORE	sx gel A. Luth (TECH Sx cem sx gel RECEIVE	, 1 s i NICIA one Year: hent c COMMIS	n) 19 85 on top	ulls.
lst plug: 2nd plug: and 100 s: Plugging Operation ACTUAL PL of sand t 10 sx gel	5 1/2" s sand back squeeze we x cement. Operations s Complete UGGING REP hrough bai , 1 sack h	attended attended attended Hours ORT lst ler. 2nd ulls and	and dump 5 and dump 5 sx hulls, Plugging P by Agent?: 10:30 am Da plug sanded plug squeez 100 sx ceme	sx cement 10 sx gel roposal R All _x y: 11 back to ed well went.	eceived Mon 3800' ar	of sacemen	Paul A March mped 5 1s, 10 TATE CORI	sx gel A. Luth (TECH Sx cem Sx gel RECEIVE PORATION RYATION D	, 1 s i NICIA one Year: hent o	sack hone is sack to the sack hone is sack hone	ulls.
lst plug: 2nd plug: and 100 s: Plugging Operation ACTUAL PL of sand t 10 sx gel	5 1/2" s sand back squeeze we x cement. Operations s Complete UGGING REP hrough bai , 1 sack h	attended attended Hours ORT 1st ler. 2nd ulls and Pozmix 2	and dump 5 and dump 5 sx hulls, Plugging P by Agent?: 10:30 am Da plug sanded plug squeez 100 sx ceme	sx cement 10 sx gel roposal R Ai!x y: 11 back to ed well went.	eceived Mon 3800' ar	of sacement	Paul A March mped 5 Is, 10 TATE CORE CONSER 2785	sx gel Luth (TECH sx cem sx gel RECEIVE PORATION D Chila Kann	i NICIA one year: eent commis	sack hone is sack to the sack hone is sack hone	ulls
lst plug 2nd plug 2nd plug and 100 s: Plugging Operation ACTUAL PL of sand to 10 sx gel Maximum p Remarks:	5 1/2" s sand back squeeze we x cement. Operations s Complete UGGING REP hrough bai , 1 sack h	attended attended attended d: Hours ORT lst ler. 2nd ulls and Pozmix 2 ditional	Plugging P by Agent?: 10:30 am Da plug sanded plug squeez 100 sx ceme	sx cement 10 sx gel roposal R Allx y: _11 back to ded well went.	eceived Mon 3800' ar	of sacement	Paul A March mped 5 Is, 10 TATE CORE CONSER 2785	sx gel Luth (TECH sx cem sx gel RECEIVE PORATION D Chila Kann	i NICIA one year: eent commis	sack hone is sack to the sack hone is sack hone	ulls
Plugging Operation ACTUAL PL of sand t 10 sx gel	5 1/2" s sand back squeeze we x cement. Operations s Complete UGGING REP hrough bai , 1 sack h	attended attended attended d: Hours ORT lst ler. 2nd ulls and Pozmix 2 ditional	and dump 5 and dump 5 sx hulls, Plugging P by Agent?: 10:30 am Da plug sanded plug squeez 100 sx ceme	sx cement 10 sx gel roposal R Allx y: _11 back to ded well went.	eceived Mon 3800' ar	of sacement	Paul A March mped 5 1s, 10 TATE CORE CONSER 2785	sx gel A. Luth (TECH Sx cem Sx gel RECEIVE PORATION D Chila Kann This to	i NICIA one year: eent commis	sack hone is sack to the sack	ulls
lst plug 2nd plug 2nd plug and 100 s: Plugging Operation ACTUAL PL of sand to 10 sx gel Maximum p Remarks:	5 1/2" s sand back squeeze we x cement. Operations s Complete UGGING REP hrough bai , 1 sack h	attended attended attended d: Hours ORT lst ler. 2nd ulls and Pozmix 2 ditional	Plugging P by Agent?: 10:30 am Da plug sanded plug squeez 100 sx ceme	sx cement 10 sx gel roposal R Allx y: _11 back to ded well went.	eceived Mon 3800' ar	of sacement	Paul A March mped 5 1s, 10 TATE CORE CONSER 2785	sx gel A. Luth (TECH Sx cem Sx gel RECEIVE PORATION D Chila Kann This to	i NICIA one year: eent commis	sack hone is sack to the sack	ulls