ATE CORPORATION COMMISSION  NSERVATION DIVISION - PLUGGING SECTION  O COLORADO DERBY BUILDING	API NUMBER 15- 185-22,246-000
	SW NW SE, SEC. 21 , T 22 S, R 14 b
CHITA, KANSAS 67202	1650 feet from S section   1
CHNICIAN'S PLUGGING REPORT	feet from E section is
erator License # 6581	Loase Name Vice Well # 3-21
erator: Bison Energy Corporation	County Stafford /28.
dress Box 782317	Well Total Depth 3950 fe
Wichita, KS 67278-2317	Conductor Pipe: Sizefeet
	Surface Casing: Size 8 5/8 feet 304
pandoned Oli Weil X Gas Well	_ Input Well D&A
ther well as hereinafter indicated	
	ers, Inc. License Number 4635
idress Box 768, Great Bend, KS 67530	
	6 Month: 5 Year: 19 88
lugging proposal received from Gary Burk	e
•	Tnc. (phone) 316-793-971
•	
company name) <u>Great Bend Casing Pullers;</u>	Tnc. (phone) 316-793-971
company name) Great Bend Casing Pullers;  are: 4½" at 3942' Perfs at 3631-35'  lst plug sand back to 3550' and dump 4 sx	Inc. (phone) 316-793-971 cement on top of sand through bailer.
Great Bend Casing Pullers; ere: 4½" at 3942' Perfs at 3631-35'  Set plug sand back to 3550' and dump 4 sx  2nd plug pump 4 sx hulls, 10 sx gel, 50 s	cement on top of sand through bailer, x cement, 10 sx gel, 1 sx hulls, release 8 5
company name) Great Bend Casing Pullers;  are: 4½" at 3942' Perfs at 3631-35'  lst plug sand back to 3550' and dump 4 sx	cement on top of sand through bailer, x cement, 10 sx gel, 1 sx hulls, release 8 5
Great Bend Casing Pullers; are: 4½" at 3942' Perfs at 3631-35'  Let plug sand back to 3550' and dump 4 sx 2nd plug pump 4 sx hulls, 10 sx gel, 50 st wiper plug and pump 100 sx cement.	cement on top of sand through bailer.  x cement, 10 sx gel, 1 sx hulls, release 8 5
Great Bend Casing Pullers; are: 4½" at 3942' Perfs at 3631-35'  Let plug sand back to 3550' and dump 4 sx 2nd plug pump 4 sx hulls, 10 sx gel, 50 st wiper plug and pump 100 sx cement.	cement on top of sand through bailer, x cement, 10 sx gel, 1 sx hulls, release 8 5
Great Bend Casing Pullers; are: 4½" at 3942' Perfs at 3631-35'  Let plug sand back to 3550' and dump 4 sx 2nd plug pump 4 sx hulls, 10 sx gel, 50 st wiper plug and pump 100 sx cement.  Plugging Propo	Inc. (phone) 316-793-971  cement on top of sand through bailer.  x cement, 10 sx gel, 1 sx hulls, release 8 5  osal Received by Duane Rankin (TECHNICIAN)
Great Bend. Casing Pullers;  are: 4½" at 3942' Perfs at 3631-35'  Ist plug sand back to 3550' and dump 4 sx  2nd plug pump 4 sx hulls, 10 sx gel, 50 s:  wiper plug and pump 100 sx cement.  Plugging Propertions attended by Agent?: A	Inc(phone) 316-793-971  cement on top of sand through bailer.  x cement, 10 sx gel, 1 sx hulls, release 8 5  osal Received by
Great Bend Casing Pullers;  ore: 4½" at 3942' Perfs at 3631-35'  lst plug sand back to 3550' and dump 4 sx  2nd plug pump 4 sx hulls, 10 sx gel, 50 si  wiper plug and pump 100 sx cement.  Plugging Propertions attended by Agent?: A  perations Completed: Hour: 4 p.m. Day:	cement on top of sand through bailer.  x cement, 10 sx gel, 1 sx hulls, release 8 5  osal Received by Duane Rankin (TECHNICIAN)  II X Part None  6 Month: 5 Year:19 88
Great Bend. Casing Pullers;  are: 4½" at 3942' Perfs at 3631-35'  Let plug sand back to 3550' and dump 4 sx  2nd plug pump 4 sx hulls, 10 sx gel, 50 si  wiper plug and pump 100 sx cement.  Plugging Propertions attended by Agent?: A  perations Completed: Hour: 4 P.M. Day:  CTUAL PLUGGING REPORT 1st plug sanded back	cement on top of sand through bailer.  x cement, 10 sx gel, 1 sx hulls, release 8 5   Duane Rankin (TECHNICIAN)  II X Part None  6 Month: 5 Year:19 88  k to 3580' and dumped 4 sx cement on top of
Great Bend Casing Pullers;  are: 4½" at 3942' Perfs at 3631-35'  Let plug sand back to 3550' and dump 4 sx  2nd plug pump 4 sx hulls, 10 sx gel, 50 si  wiper plug and pump 100 sx cement.  Plugging Propertions attended by Agent?: A  perations Completed: Hour: 4 P.M. Day:  CTUAL PLUGGING REPORT 1st plug sanded back  sand through bailer,	cement on top of sand through bailer.  x cement, 10 sx gel, 1 sx hulls, release 8 5  osal Received by
Great Bend Casing Pullers;  are: 4½" at 3942' Perfs at 3631-35'  Let plug sand back to 3550' and dump 4 sx  2nd plug pump 4 sx hulls, 10 sx gel, 50 st  wiper plug and pump 100 sx cement.  Plugging Properations attended by Agent?: A  perations Completed: Hour: 4 p.m. Day:  CTUAL PLUGGING REPORT 1st plug sanded back  sand through bailer,  2nd plug pumped into 8 5/8" surface casing	cement on top of sand through bailer.  x cement, 10 sx gel, 1 sx hulls, release 8 5   osal Received by
Great Bend Casing Pullers;  are: 4½" at 3942' Perfs at 3631-35'  Let plug sand back to 3550' and dump 4 sx  2nd plug pump 4 sx hulls, 10 sx gel, 50 st  wiper plug and pump 100 sx cement.  Plugging Properations attended by Agent?: A  perations Completed: Hour: 4 p.m. Day:  CTUAL PLUGGING REPORT 1st plug sanded back  sand through bailer,  2nd plug pumped into 8 5/8" surface casing	cement on top of sand through bailer.  x cement, 10 sx gel, 1 sx hulls, release 8 5  osal Received by
Great Bend Casing Pullers;  are: 4½" at 3942' Perfs at 3631-35'  Let plug sand back to 3550' and dump 4 sx  2nd plug pump 4 sx hulls, 10 sx gel, 50 st  wiper plug and pump 100 sx cement.  Plugging Properations attended by Agent?: A  perations Completed: Hour: 4 p.m. Day:  CTUAL PLUGGING REPORT 1st plug sanded back  sand through bailer,  2nd plug pumped into 8 5/8" surface casing	cement on top of sand through bailer.  x cement, 10 sx gel, 1 sx hulls, release 8 5  osal Received by Duane Rankin (TECHNICIAN)  II X Part None 6 Month: 5 Year:19 88 k to 3580' and dumped 4 sx cement on top of g with 400 lbs. hulls, 10 sx gel, 50 sx ceme "wiper plug and pumped 100 sx cement on communication c
Great Bend Casing Pullers;  are: 4½" at 3942' Perfs at 3631-35'  Let plug sand back to 3550' and dump 4 sx  2nd plug pump 4 sx hulls, 10 sx gel, 50 st  wiper plug and pump 100 sx cement.  Plugging Properations attended by Agent?: A  perations Completed: Hour: 4 p.m. Day:  CTUAL PLUGGING REPORT 1st plug sanded back  sand through bailer,  2nd plug pumped into 8 5/8" surface casing	cement on top of sand through bailer.  x cement, 10 sx gel, 1 sx hulls, release 8 5  osal Received by
company name) Great Bend Casing Pullers;  are: 4½" at 3942' Perfs at 3631-35'  lst plug sand back to 3550' and dump 4 sx 2nd plug pump 4 sx hulls, 10 sx gel, 50 s;  wiper plug and pump 100 sx cement.  Plugging Propertions attended by Agent?: A perations Completed: Hour: 4 p.m. Day:  CTUAL PLUGGING REPORT 1st plug sanded back sand through bailer, 2nd plug pumped into 8 5/8" surface casing 10 sx gel, 100 lbs. hulls, released 8 5/8"	cement on top of sand through bailer.  x cement, 10 sx gel, 1 sx hulls, release 8 5   osal Received by Duane Rankin (TECHNICIAN)  II X Part None  6 Month: 5 Year: 19 88  k to 3580' and dumped 4 sx cement on top of  g with 400 lbs. hulls, 10 sx gel, 50 sx ceme "wiper plug and pumped 100 sx cement on common com

DATE 5-17-88 NV. NO. 20619