To:	4 4 5 5 5 5 5 5	/- H
CTXTE	+ 12U/U8	5-7 API NUMBER 15- E-25,102 15- (85-01023-000)
CONSERVATI	PORATION COMMISSION ON DIVISION - PLUGGING S	
-200 COLORA	DO DERBY BUILDING ANSAS 67202	4950 feet from S section line
-	'S PLUGGING REPORT	2970 feet from E section line
	icense / none	Lease Name Stalcup Well # 1
-	Doug Holtz	County Stafford
Name&	30 W. 14th	Well Total Depth 3784 /22.98 feet
	Hutchinson KS 67501	Conductor Pipe: Size
		· · · · · · · · · · · · · · · · · · ·
	A11 N-11	Surface Casing: Size 8 5/8 feet 205
	Oli Well Gas We	
Other Well	as hereinafter indicate	
		y Inc. License Number 30752
Address	P.O. Box 7, Great Bend, K	KS 67530
		n. Day: 7 Month: 5 Year:19 92
2nd plug	pump in 8 5/8" surface ca	ump 5 sx cement on top of sand through bailer, asing with 300 lbs. hulls, 10 sx gel, 50 sx cement, 10 sx ger plug and pump 100 sx cement.
· · · · · · · · · · · · · · · · · · ·		Programme Description
	Plugg	ging Proposal Received by Duane Rankin
		(TECHNICIAN)
Pluggino C	perations attended by Ac	gent7: AllX PartNone
•		gent?: AllX PartNone
Operations	Completed: Hour: 10:30	gent?: All X Part None None 5 Year:19 92
Operations ACTUAL PLU	GGING REPORT 1st plug s	gent?: AllX PartNone
Operations ACTUAL PLU top of sar	GGING REPORT 1st plug sond through bailer,	gent?: All X Part None a.mDay: 7 Month: 5 Year:19 92 sanded 5½" casing back to 2950' and dumped 5 sx cement on
Operations ACTUAL PLU top of sar 2nd plug p	GGING REPORT 1st plug sond through bailer, pumped into 8 5/8" surface	a.mDay: 7 Month: 5 Year:19 92 sanded 5½" casing back to 2950' and dumped 5 sx cement on ce casing with 300 lbs. hulls, 10 sx gel, 50 sx cement,
Operations ACTUAL PLU top of sar 2nd vlug y 10 sx gel	Completed: Hour: 10:30 IGGING REPORT 1st plug s Ind through bailer, pumped into 8 5/8" surface, 100 lbs. hulls, release	gent?: All X Part None a.mDay: 7 Month: 5 Year:19 92 sanded 5½" casing back to 2950' and dumped 5 sx cement on ce casing with 300 lbs. hulls, 10 sx gel, 50 sx cement, ed 8 5/8" wiper plug and pumped 100 sx cement.
Operations ACTUAL PLU top of sar 2nd plug p 10 sx gel Pumping pr	GGING REPORT 1st plug sond through bailer, pumped into 8 5/8" surface, 100 lbs. hulls, release ressure 0-500 psi and shu	gent?: All X Part None a.mDay: 7 Month: 5 Year:19 92 sanded 5½" casing back to 2950' and dumped 5 sx cement on ce casing with 300 lbs. hulls, 10 sx gel, 50 sx cement, ed 8 5/8" wiper plug and pumped 100 sx cement.
top of sar 2nd plug p 10 sx gel Pumping pr	GGING REPORT 1st plug some through bailer, pumped into 8 5/8" surface, 100 lbs. hulls, release ressure 0-500 psi and shubing at 3000'.	gent?: All X Part None a.mDay: 7 Month: 5 Year:19 92 sanded 5½" casing back to 2950' and dumped 5 sx cement on ce casing with 300 lbs. hulls, 10 sx gel, 50 sx cement, ed 8 5/8" wiper plug and pumped 100 sx cement. at in 250 psi.
top of sar 2nd plug p 10 sx gel Pumping pr	Completed: Hour:10:30 IGGING REPORT 1st plug sond through bailer, pumped into 8 5/8" surface, 100 lbs. hulls, release ressure 0-500 psi and shubing at 3000". Used 60/40 Pozmix 6% gel	gent?: All X Part None a.mDay: 7 Month: 5 Year:19 92 sanded 5½" casing back to 2950' and dumped 5 sx cement on ce casing with 300 lbs. hulls, 10 sx gel, 50 sx cement, ed 8 5/3" wiper plug and pumped 100 sx cement. at in 250 psi. by B.J. Services. Recovered 2000' of 5½" casing:
Operations ACTUAL PLU top of sar 2nd plug p 10 sx gel Pumping pr 2 3/8" tul	IGGING REPORT 1st plug sond through bailer, pumped into 8 5/8" surface, 100 lbs. hulls, release ressure 0-500 psi and shubing at 3000'. Used 60/40 Pozmix 6% gel (If additional descriptional descriptions)	gent?: All X Part None a.mDay: 7 Month: 5 Year:19 92 sanded 5½" casing back to 2950' and dumped 5 sx cement on ce casing with 300 lbs. hulls, 10 sx gel, 50 sx cement, ed 8 5/3" wiper plug and pumped 100 sx cement. at in 250 psi. by B.J. Services. Recovered 2000' of 5½" casings. Iption is necessary, use BACK of this form.
Operations ACTUAL PLU top of sar 2nd plug p 10 sx gel Pumping pr 2 3/8" tul Remarks:	Completed: Hour: 10:30 GGING REPORT 1st plug so and through bailer, pumped into 8 5/8" surface, 100 lbs. hulls, release ressure 0-500 psi and shubing at 3000'. Used 60/40 Pozmix 6% gel (If additional descriptions)	gent7: AllX PartNone
Operations ACTUAL PLU top of sar 2nd plug p 10 sx gel Pumping pr 2 3/8" tul Remarks:	Completed: Hour: 10:30 IGGING REPORT 1st plug so and through bailer, pumped into 8 5/8" surface, 100 lbs. hulls, release ressure 0-500 psi and shubing at 3000'. Used 60/40 Pozmix 6% gel (If additional descriptions of this pictory)	gent?: All X Part None a.mDay: 7 Month: 5 Year:19 92 sanded 5½" casing back to 2950' and dumped 5 sx cement on ce casing with 300 lbs. hulls, 10 sx gel, 50 sx cement, ed 8 5/3" wiper plug and pumped 100 sx cement. at in 250 psi. by B.J. Services. Recovered 2000' of 5½" casings. Iption is necessary, use BACK of this form.