WICHITA.	RADO DERBY BUILDING KANSAS 67202	NE SE SW, SEC. 2 , 7 22 S, R 14 k
TECHNICIAN'S PLUGGING REPORT		2970 feet from E section II
		
	License # 5111	Lease Name Smallwood Unit Well # 2
Operator: Name& Address	Rockhold Engineering, Inc.	County Stafford 123.8
	Box 698	Well Total Depth 3810 fe
	Great Bend, KS 67530	Conductor Pipe: Sizefeet
	·	Surface Casing: Size 8 5/8 feet 340
Abandoned	Oll Well X Gas Well	Input Well SWD Well D&A
Other wel	I as hereinafter indicated	
		ng, Inc. License Number 5111
	•	
		26 Month: 9 Year:19 89
Plugging	proposal received from James R	ockhold
	name) Rockhold Engineering, Inc.	217 702 250
rcombana	Hame, Rockhord Engineering, Inc.	(phone) 316-792-250
		(phone)_310-/92-230
were: 5!	g" at 3810' Perfs at 3491, 3543	-52 '
#ere: 5! 1st plu	s" at 3810' Perfs at 3491, 3543 g sand back to 3440' and dump 5	=52' sx cement on top of sand through bailer,
lst plus	s" at 3810' Perfs at 3491, 3543 g sand back to 3440' and dump 5 g pump 4 sx hulls, 10 sx gel, 50	-52 '
lst plus	s" at 3810' Perfs at 3491, 3543 g sand back to 3440' and dump 5	=52' sx cement on top of sand through bailer,
lst plus	g sand back to 3440' and dump 5 g pump 4 sx hulls, 10 sx gel, 50 Lug and pump 100 sx cement.	=52' sx cement on top of sand through bailer, sx cement, 10 sx gel, 1 sx hulls, release 8 5
lst plus	g sand back to 3440' and dump 5 g pump 4 sx hulls, 10 sx gel, 50 Lug and pump 100 sx cement.	sx cement on top of sand through bailer, sx cement, 10 sx gel, 1 sx hulls, release 8 5
1st plug 2nd plug wiper p	g sand back to 3440' and dump 5 g pump 4 sx hulls, 10 sx gel, 50 lug and pump 100 sx cement. Plugging Pro	sx cement on top of sand through bailer, sx cement, 10 sx gel, 1 sx hulls, release 8 5 sposal Received by Steve Durrant (TECHNICIAN)
1st plug	g sand back to 3440' and dump 5 g pump 4 sx hulls, 10 sx gel, 50 Lug and pump 100 sx cement. Plugging Pro	sx cement on top of sand through bailer, sx cement, 10 sx gel, 1 sx hulls, release 8 5 sposal Received by Steve Durrant (TECHNICIAN) All X Part None
1st plug 2nd plug wiper p	g sand back to 3440' and dump 5 g pump 4 sx hulls, 10 sx gel, 50 lug and pump 100 sx cement. Plugging Pro Operations attended by Agent?: as Completed: Hour: 12:30 p.mpay:	sx cement on top of sand through bailer, sx cement, 10 sx gel, 1 sx hulls, release 8 5 sposa! Received by Steve Durrant (TECHNICIAN) Ali X Part None 26 Month: 9 Year:19 89
1st plug 2nd plug wiper p	g sand back to 3440' and dump 5 g pump 4 sx hulls, 10 sx gel, 50 lug and pump 100 sx cement. Plugging Pro Operations attended by Agent?: as Completed: Hour: 12:30 p.mpay:	sx cement on top of sand through bailer, sx cement, 10 sx gel, 1 sx hulls, release 8 5 sposal Received by Steve Durrant (TECHNICIAN) All X Part None
lst plugging Plugging Operation	g sand back to 3440' and dump 5 g pump 4 sx hulls, 10 sx gel, 50 lug and pump 100 sx cement. Plugging Pro Operations attended by Agent?: as Completed: Hour: 12:30 p.mpay:	sx cement on top of sand through bailer, sx cement, 10 sx gel, 1 sx hulls, release 8 5 sposa! Received by Steve Durrant (TECHNICIAN) Ali X Part None 26 Month: 9 Year:19 89
lst plug 2nd plug wiper p	g sand back to 3440' and dump 5 g pump 4 sx hulls, 10 sx gel, 50 Lug and pump 100 sx cement. Plugging Pro Operations attended by Agent?: as Completed: Hour: 12:30 p.mQay: UGGING REPORT 1st plug sanded of sand through bailer.	sx cement on top of sand through bailer, sx cement, 10 sx gel, 1 sx hulls, release 8 5 sposa! Received by Steve Durrant (TECHNICIAN) Ali X Part None 26 Month: 9 Year:19 89
lst plus 2nd plus wiper p Plugging Operation ACTUAL Pr on top of	g sand back to 3440' and dump 5 g pump 4 sx hulls, 10 sx gel, 50 lug and pump 100 sx cement. Plugging Pro Operations attended by Agent?: as Completed: Hour: 12:30 p.mpay: uses New Report 1st plug sanded of sand through bailer. g pumped into 8 5/8" surface cas	sx cement on top of sand through bailer, sx cement, 10 sx gel. 1 sx hulls, release 8 5 sposal Received by Steve Durrant (TECHNICIAN) All X Part None 26 Month: 9 Year:1989 5½" casing back to 3440' and dumped 5 sx cemen ing with 400 lbs. hulls, 10 sx gel, 50 sx cemen
lst plug 2nd plug wiper p Plugging Operation ACTUAL Plug 2nd plug 10 sx ge	g sand back to 3440' and dump 5 g pump 4 sx hulls, 10 sx gel, 50 lug and pump 100 sx cement. Plugging Pro Operations attended by Agent?: as Completed: Hour: 12:30 p.mpay: uses New Report 1st plug sanded of sand through bailer. g pumped into 8 5/8" surface cas	sx cement on top of sand through bailer, sx cement, 10 sx gel. 1 sx hulls, release 8 5 sposal Received by Steve Durrant (TECHNICIAN) All X Part None 26 Month: 9 Year:1989 5½" casing back to 3440' and dumped 5 sx cement ing with 400 lbs. hulls, 10 sx gel, 50 sx cement 8" wiper plug and pumped 100 sx cement.
lst plug 2nd plug wiper p Plugging Operation ACTUAL Plug 2nd plug 10 sx ge	g sand back to 3440' and dump 5 g pump 4 sx hulls, 10 sx gel, 50 lug and pump 100 sx cement. Plugging Pro Operations attended by Agent?: as Completed: Hour: 12:30 p.mpay: uselNe Report 1st plug sanded of sand through bailer. g pumped into 8 5/8" surface cas	sx cement on top of sand through bailer, sx cement, 10 sx gel. 1 sx hulls, release 8 5 sposa! Received by Steve Durrant (TECHNICIAN) All X Part None 26 Month: 9 Year:1989 5½" casing back to 3440' and dumped 5 sx cemen ing with 400 lbs. hulls, 10 sx gel, 50 sx cemen /8" wiper plug and pumped 100 sx cement. 350 psi.
lst plug 2nd plug wiper p Plugging Operation ACTUAL Pr on top of 2nd plug 10 sx go Pumping	g sand back to 3440' and dump 5 g pump 4 sx hulls, 10 sx gel, 50 lug and pump 100 sx cement. Plugging Pro Operations attended by Agent?: as Completed: Hour: 12:30 p.mpay: lugging Report 1st plug sanded of sand through bailer. g pumped into 8 5/8" surface cas el, 100 lbs. hulls, released 8 5 pressure 0-450 psi and shut in	sx cement on top of sand through bailer, sx cement, 10 sx gel, 1 sx hulls, release 8 5 sposa! Received by Steve Durrant (TECHNICIAN) All X Part None 1 26 Month: 9 Year:1989 5½" casing back to 3440' and dumped 5 sx cement ing with 400 lbs. hulls, 10 sx gel, 50 sx cement 8" wiper plug and pumped 100 sx cement 350 psi.
lst plug 2nd plug wiper p Plugging Operation ACTUAL Pr on top of 2nd plug 10 sx go Pumping	g sand back to 3440' and dump 5 g pump 4 sx hulls, 10 sx gel, 50 lug and pump 100 sx cement. Plugging Pro Operations attended by Agent?: as Completed: Hour: 12:30 p.mQay: lugging Report 1st plug sanded of sand through bailer. g pumped into 8 5/8" surface cas el, 100 lbs. hulls, released 8 5 pressure 0-450 psi and shut in Used 60/40 Pozmix 6% gel by B.J	sx cement on top of sand through bailer, sx cement, 10 sx gel. 1 sx hulls, release 8 5 sposa! Received by Steve Durrant (TECHNICIAN) All X Part None 26 Month: 9 Year:1989 5½" casing back to 3440' and dumped 5 sx cemen ing with 400 lbs. hulls, 10 sx gel, 50 sx cemen /8" wiper plug and pumped 100 sx cement. 350 psi.

FORM CP-2/3 Rev.01-84