

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
245 North Water
WICHITA, KANSAS 67202

Rev. 6-3-74
FORM CP-1

WELL PLUGGING APPLICATION FORM
File One Copy

MAR 22 1977
3-22-77
Curtis A. H. Hines

API Number 15 - (of this well)
Lease Owner Hinkle Oil Company
Address 1016 Union Center Building, Wichita, Kansas 67202
Lease (Farm Name) Kroutwurst #14 Well No. _____
Well Location SW NW SW Sec. 34 Twp. 16 Rge. 11 (E) _____ (W) _____
County Barton NE KC #3.17 Total Depth 3360 Field Name _____
Oil Well X Gas Well _____ Input Well _____ SWD Well _____ Rotary D & A _____
Well Log attached with this application as required yes
Date and hour plugging is desired to begin immediately

PLUGGING OF THIS WELL WILL BE DONE IN ACCORDANCE WITH K.S.A. 55-128 OF THE RULES AND REGULATIONS OF THE STATE CORPORATION COMMISSION.

Name of company representative authorized to be in charge of plugging operations:

MErvin Sheeks Address Claflin, Kansas

Plugging Contractor Kelso Casing Pulling License No. 683

Address Box 176, Chase, Kansas 67524

Invoice covering assessment for plugging this well should be sent to:

Name Hinkle Oil Company

Address 1016 Union Center Building, Wichita, Kansas 67202

and payment will be guaranteed by applicant or acting agent.

Signed: Margaret Bralcher
Applicant or Acting Agent

Date: March 21, 1977



State Corporation Commission

CONSERVATION DIVISION

(Oil, Gas and Water)

245 North Water
WICHITA, KANSAS 67202

March 22, 1977

WELL PLUGGING AUTHORITY

Well No.	14
Lease	Kroutwurst
Description	SW- ^{NE} SW Sec. 34-16-11W
County	Barton
Total Depth	3360
Plugging Contractor	Kelso Casing Pulling


Hinkle Oil Company
1016 Union Center Building
Wichita, Kansas 67202

Gentlemen:

This is your authority to plug the above subject well in accordance with the Rules and Regulations of the State Corporation Commission.

This authority is void after 90 days from the above date.

Yours very truly,


J. Lewis Brock, Administrator

Mr. Duane L. Rankin, P.O. Box 967, Great Bend, Kansas 67530
is hereby assigned to supervise the plugging of the above
named well.