## KCC OIL/GAS REGULATORY OFFICES

Inspection D	ate	01/26/20	17	District:	3	Incident Number:					5638
			✓ New	Situation		☐ Lea	se Inspe	ction			
			☐ Res	ponse to F	Request	☐ Cor	mplaint				
			☐ Follo	•			ld Report				
Operator Lice	ense	No: 3499	98	API: 15	037-0	1296	00.00	Q3	Q2	l: Q	1: SE
Operator Nar	ne:	Ace Energ	gy LLc		SEC	1 T\	WP 31	RGE	21	RGEDIR	. e
Address: 11			Rd						SL:		1724
-3	wood		00044	4					EL:	Lonior	135
State Ks Phone contact		ip Code:	9-8602	Le	ease: 1	Peggy Kr		Well N unty:	vo.: Cr	L88,L85	
Reason for In			0002				00	unity.	Ol		
TA / Plugging		<u>gactorni</u>									
17,77,1499,19											
Dualdana											
Problem:											
Well location /	statt	15									
Persons con	tacte	<u>ed:</u>									
Jonathan Fre	iden,	Casey Jes	sseph, Der	nnis Shultz	<u>.</u>						
<u>Findings:</u>											
Ace Energy's or records it was											017
the well was pl	lugge	d. A previ	ous operat	or had this	s well list	ed as L	88. RBDI	<b>dS</b> recor	rds no	w indicate	•
that there is ar updated to cor								ry on RE	BDMS	should be	9
apaated to cor	10011	mon #L o	0 (10 001	010207 40	HOL DOI	ig drilled.	•				
Actions / Reco	omm	<u>endation</u>	<u>Fo</u>	llow-up R	Required	. LJ	<u>Dea</u>	<u>dline Da</u>	<u>ate:</u>		
I will refer this	repor	t to correc	t the issue								
	استدا		F-7-7					's Take		0	
☑ RBDMS	<b>Y</b>	KGS	☐ TA DE	JF .	Report	Prepare	d By: <u>F</u>	Russell h	<u>line</u>		
☐ T1 DBF	✓	District Fil	es 🗆 C	ourthouse	Po	sition:	E.C.R.	<u>S.</u>			