## KANSAS STATE CORPORATION COMMISSION

CONSERVATION DIVISION AGENT'S REPORT

J. P. Roberts
Assitant Director
500 Insurance Building
212 North Market
Wichita 2, Kansas

10-21-66 9CT 21 1966

Cold of the test of the same

	5-185-11413-60-01
Operator's Full Name Morris Garvin	3 180 1110 30 01
Complete Address: 201 E. Third, St Johns, Kansas	
Lease Name Norris Well No.	<u># 1</u>
Location NW SW SW Sec. 27 Twp. 23	Rge. 13 (E) (W) W
County Stafford Total Depth	40001
Abandoned Oil WellGas WellInput WellSWD Well	X_D & A
Other well as hereafter indicated:	
Plugging Contractor: Santa Fe Pipe & Supply, Inc.	
Address: P. O. Box 562, Great Bend, Kansas Lie	cense No. 574
Operation Completed: Hour10:00AM Day 18th Month Oct.	Year 1966
The Above well was plugged as follows:	
258' of 8 5/8" surface pipe, cement circulated. 3936'	of $5\frac{1}{2}$ " long string.
No attempt was made to recover any pipe. Hole was sque	ezed with 10 sacks
of Gel-Mud and 75 sacks of cement, pumped through a 51	" swage into the long
string. The top of the cement was now at 256' in the 5	½". 5½" was shot off
at 256', the shot went off in cement, 40' of $5\frac{1}{2}$ " long	string was recovered
from the hole, this pipe was in very bad condition, at	e up with salt water.
When this hole was squeezed with 75 sacks of cement the $5\frac{1}{2}$ ", and out through the holes, circulating the cepipe. Hole was bailed down to 40', rock bridge from 40 with 10 sacks to the base of the cellar.	ment up into the surface
I hereby certify that the above well was plugged as herein stated.	
Signed: Well	Plugging Supervisor

Dear Greider:

This report is the replugging of Morris Garvin's, Norris # 1. The orginal plugging turned out better than I thought it would.

The  $5\frac{1}{2}$ " long string was so ate up with holes, that when the cement was pumped into the  $5\frac{1}{2}$ ", it circulated out in the hole and up in the surface pipe.

Yours Truly

Archie Elving

ri.n