STATE OF KANSAS STATE CORPORATION COMMISSION CONSERVATION DIVISION 211 NORTH BROADWAY WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

15-185.0040-000

PLUGGING

File One Copy
Lease Cwner W. J. Coppinger, Etal Address Union National Building, Wichita 2, Kansa (Applicant) Lease (Farm Name) Asher Well No. 1
Well Location NW NW SE Sec. 3 Twp.23SRge.14 (E) - (W) W
County Stafford Field Name (if any) Wildcat
Total Depth 3985 Oil Gas Dry Hole Dry Hole
Was well log filed with application? No If not, explain:
Filed with Plugging Report
Date and hour plugging is desired to begin September 22, 1957
Plugging of the well will be done in accordance with the Rules and Regulations
of the State Corporation Commission.
Name of the person on the lease in charge of well for owner
Otto L. Berens Address Box 334, El Dorado, Kansas
Plugging Contractor Rex & Morris Drilling Company
Plugging Contractor's License No. 71
Address Box 334, El Dorado, Kansas
Invoice covering assessment for plugging this well should be sent to
Rex & Morris Drilling Company Address Box 334, El Dorado, Kansas
and payment will be guaranteed by applicant.
STATE SEP 26-57 Rex & Morris Drilling Company By: C. E. McClure & McClure Applicant or Acting Agent
CONSERVATION D VISION Wichita, Manager PLUGGING FILE 250 3 503 (1/4) The september 25, 1957 PLUGGING FILE 250 3 503 (1/4)

BOOK PAGE 48 LINE 19



STATE OF KANSAS

STATE CORPORATION COMMISSION

CONSERVATION DIVISION 211 NORTH BROADWAY WICHITA, KANSAS Sep'omber 24, 1957

15-185-00690-000

Well No. Lease

Description

County File No. Ashor

IN IN EE 3-23-11W

Stafford 48-19

W. J. Coppinger 507 Union Marional Euilding Wichita, Kansas

Fear Sir:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. R. M. Brundege, Box 283. Hoisington, Kansas

Very truly yours,

Jewel M. Ogden

Director of Conservation Division

cc:

District Plugging Supervisor