

STATE OF KANSAS
STATE CORPORATION COMMISSION
CONSERVATION DIVISION
211 NORTH BROADWAY
WICHITA, KANSAS

WELL PLUGGING APPLICATION FORM
File One Copy

Lease Owner Stanolind Oil and Gas Co. Address Box 1654, Oklahoma City, Oklahoma
(Applicant)

Lease (Farm Name) P. R. Spangenberg "A" Well No. 5

Well Location NE SW SW Sec. 29 Twp. 22S Rge. 11 ~~BOOK~~ (W) W

County Stafford Field Name (if any) Richardson

Total Depth 3597 Oil X Gas Dry Hole

Was well log filed with application? No If not, explain:

To be forwarded with Well Plugging Record

Date and hour plugging is desired to begin 10-1-55, 8:00 AM

Plugging of the well will be done in accordance with the Rules and Regulations
of the State Corporation Commission.

Name of the person ~~on the lease~~ in charge of well for owner

F. H. Butcher Address Ellinwood, Kansas

Plugging Contractor Not designated

Plugging Contractor's License No.

Address

Invoice covering assessment for plugging this well should be sent to

G. A. Reynolds Address Box 7, Ellinwood, Kansas

and payment will be guaranteed by applicant.

Please mail plugging approval
or correspondence to:

G. A. Reynolds
Box 7
Ellinwood, Kansas

G. A. Reynolds
Applicant or Acting Agent

Date 9-20-55

PLUGGING
FILE SEC. 29 T. 22 R. 11 W
BOOK PAGE 2 LINE 22

STATE CORPORATION COMMISSION
CONSERVATION DIVISION
WICHITA, KANSAS

9-21-55



STATE OF KANSAS
 STATE CORPORATION COMMISSION
 CONSERVATION DIVISION
 211 NORTH BROADWAY
 WICHITA, KANSAS

September 21, 1955

Well No.	5
Lease	Spangenberg "A"
Description	NE SW SW 29-22-11W
County	Stafford
File No.	2-22

Stanolind Oil & Gas Company
 Box 7
 Ellirwood, Kansas

Gentlemen:

This letter is your authority to plug the above subject well, in accordance with the Rules and Regulations of the State Corporation Commission. When you are ready to plug this well, please contact our District Plugging Supervisor, Mr. M. A. Rives, Box 8, Pratt, Kansas.

STATE CORPORATION COMMISSION
 CONSERVATION DIVISION

BY:

S. S. Greider
 S. S. Greider
 WELL PLUGGING SUPERVISOR

cc:
 District Plugging Supervisor