Form CP-4

		1.	
ar T	4		6.
ST	TE OF KANS	AS .	. 4
	PORATION CO		SION
Give All Informat	ion Completely	.1	=
Make Required A			-
Mail or Delive-	prort to:	~ <u>-</u> -	-
Conservation	Division .	æ.	

NORTH			
	1   		
	<u></u>		
	!   		
	! !		

or Delive prort to: Conservation Division State Corporation Commission						
P. O. Box 17027 Wichita, Kansas 67217	В	e.rt.on_	County.	Sec. 25 '	Two. 19. Rge	. <u></u>
Wichita, Kansas 67217 NORTH						· · · · · · · · · · · · · · · · · · ·
NONTA ,						
i 1 i 1						Well No#2
						8.S
!					•	
i i !		oleted	-	•		19
i   i	Application for	plugging filed				19
	Application for	plugging approve	a		<del></del>	19
	Application for j	y binskmk abbiove	<u> </u>	21	1_72	19
	Plugging comme	encea		2 7	1 70	19
i   i						
	Reason for aban	donment of well o	or producing	tomation		
i i i						
						19
Locate well correctly on above	-				or its agents be	fore plugging was com
Section Plat	menced?		<del></del>			<del>-,</del>
e of Conservation Agent who superv	vised plugging of this	well		Donald	d 'll'ruan	
ucing formation			Bottom_		. Total Depth o	f Well 3320 Fee
v depth and thickness of all water, o	oil and gas formation	5.				
IL, GAS OR WATER RECORDS	•					CASING RECORD
in, one or market abouting		<del></del>	*		<del>                                     </del>	
FORMATION	CONTENT	FROM	TO	SIZE	PUT IN	PULLED DUT
				5 1/2"	3315'	1818.11
				8 5/8"	7651	
					<u> </u>	
				-		
	<del></del>					
ade bottom hole plug be	ack with sand	· · · · · · · · · · · · · · · · · · ·		nd ran 5	sacks com	
Made bottom hole plug be dumm bailer. Manueezed hole with 3 sad	ack with sand	0 sacks gel		nd ran 5	sacks com	ent thru
ade bottom hole plug be ump bailer. queezed hole with 3 sac	ack with sand	0 sacks gel		nd ran 5	sacks com	ent thru
ade bottom hole plug be ump bailer. queezed hole with 3 sac	ack with sand	0 sacks gel		nd ran 5	sacks com	ent thru
ade bottom hole plug be umm bailer. queezed hole with 3 sac	ack with sand	0 sacks gel		nd ran 5	and display	ent thru need with 125
ade bottom hole plug be umm bailer. queezed hole with 3 sac	ack with sand	0 sacks gel		nd ran 5	and display	ent thru need with 125
ade bottom hole plug be ump bailer. queezed hole with 3 sac	ack with sand	0 sacks gel		nd ran 5 sed plug	and display	ent thru
ade bottom hole plug be ump bailer. queezed hole with 3 sac	ack with sand	0 sacks gel		nd ren 5 sed plug	and displants  3-15  ECEIVEE PORATION COMM	ent thru  need with 125
ade bottom hole plug be ump bailer. queezed hole with 3 sac	ack with sand	0 sacks gel		nd ren 5 sed plug	and displants  3-15  ECEIVEE PORATION COMM	ent thru  need with 125
ade bottom hole plug be ump bailer. queezed hole with 3 sac	ack with sand	0 sacks gel		nd ran 5 sed plug- STATE COR. M,	and displant of the second sec	ent thru  need with 125
ade bottom hole plug be umm bailer. queezed hole with 3 sac	ack with sand	0 sacks gel		nd ran 5 sed plug- STATE COR. M,	and displant of the second sec	ent thru  need with 125
ade bottom hole plug be umm bailer. queezed hole with 3 sac	ack with sand	0 sacks gel		nd ran 5 sed plug- STATE COR. M,	and displants  3-15  ECEIVEE PORATION COMM	ent thru  need with 125
ade bottom hole plug be ump bailer. queezed hole with 3 sac	ack with sand	0 sacks gel		nd ran 5 sed plug- STATE COR. M,	and displant of the second sec	ent thru  need with 125
ade bottom hole plug be umm bailer. queezed hole with 3 sac	ack with sand	0 sacks gel		nd ran 5 sed plug- STATE COR. M,	and displant of the second sec	ent thru  need with 125
ade bottom hole plug be umm bailer. queezed hole with 3 sac	eck with sand	0 sacks gel	Relea	nd ren 5 sed plug  STATE COR.  GONSER	and displant of the second sec	ent thru  need with 125
ade bottom hole plug be ump beiler. queezed hole with 3 sad acks 50/50 pozmix with	eck with sand cks hulls - 2 2% gel.	O sacks gel	Relea	nd ren 5 sed plug  STATE COR.  GONSER	and displant of the second sec	ent thru  need with 125
ade bottom hole plug be ump beiler.  queezed hole with 3 sad acks 50/50 pozmix with	eck with sand  cks hulls - 2  2% gel.  (Hadditional outhwest Casin	O sacks gel	ary, use BACK of	nd ren 5 sed plug  STATE COR.  GONSER	and displant of the second sec	ent thru  need with 125
ade bottom hole plug be ump beiler.  queezed hole with 3 sad acks 50/50 pozmix with	eck with sand  cks hulls - 2  2% gel.	O sacks gel	ary, use BACK of	nd ren 5 sed plug  STATE COR.  GONSER	and displant of the second sec	ent thru  need with 125
ade bottom hole plug be ump beiler.  queezed hole with 3 sad acks 50/50 pozmix with	eck with sand  cks hulls - 2  2% gel.  (Hadditional outhwest Casin	O sacks gel	ary, use BACK of	nd ren 5 sed plug  STATE COR.  GONSER	and displant of the second sec	ent thru  need with 125
ade bottom hole plug be ump bailer.  queezed hole with 3 sac acks 50/50 pozmix with  e of Plugging Contractor Scress I	cks hulls - 2 2% gel. (Haddidonal outhwest Casin Box 364 Great	O sacks gel	ary, use BACK of	nd ren 5 sed plug  STATE COR.  GONSER	Soke come and display and display and display and display and a second s	ent thru  need with 125
ade bottom hole plug by ump bailer. queezed hole with 3 sad acks 50/50 pozmix with  e of Plugging ContractorSo essI  TE OFKansasSouthwest Casing Pull	GKS hulls - 2 2% gel. (Hadditional puthwest Casin Box 36h Grea:	description is necessary Pulling t Bend, Kan	ary, use BACK of Co. sas Barton moployee of or	sed plug- sed plug- STATE CUR  With the second seco	Sacke come and display and display and display and also play and a sacker and a sac	ent thru  need with 125  // //  // //  // //  // //  // //  // //  // //
ede bottom hole plug be ump bailer.  queezed hole with 3 sac ecks 50/50 pozmix with  e of Plugging ContractorSc essI  TE OFKansasSouthwest Casing Pull	GKS hulls - 2 2% gel. (Hadditional puthwest Casin Box 36h Grea:	description is necessary Pulling t Bend, Kan	ary, use BACK of Co. sas Barton moployee of or	sed plug- sed plug- STATE CUR  With the second seco	Sacke come and display and display and display and also play and a sacker and a sac	ent thru  need with 125  // //  // //  // //  // //  // //  // //  // //
ade bottom hole plug be ump bailer.  queezed hole with 3 sad acks 50/50 pozmix with with a sad acks 50/50 pozmix with a sad acks 50/	(Hadditonal cuthwest Casing Co., COU ling Co., ys: That I have known	description is necessing Pulling t Bend, Kan  NTY OF	ary, use BACK of Co. ses  Berton mployee of co. cots, statemen	sed plug- sed plug- STATE CUR  With the second seco	Sacke come and display and display and display and also play and a sacker and a sac	ent thru  need with 125  // //  // //  // //  // //  // //  // //  // //
ade bottom hole plug be ump bailer.  queezed hole with 3 sad acks 50/50 pozmix with with a sad acks 50/50 pozmix with a sad acks 50/	(Hadditional cuthwest Casing Co., COU ling Co., ys: That I have known are true and the same are true and the s	description is necessing Pulling t Bend, Kan  NTY OF	ary, use BACK of Co. ses  Berton mployee of co. cots, statemen	sed plug- sed plug- STATE CUR  With the second seco	Sacke come and display and display and display and also play and a sacker and a sac	ent thru  need with 125  // //  // //  // //  // //  // //  // //  // //
ade bottom hole plug be umm bailer.  queezed hole with 3 sad acks 50/50 pozmix with  e of Plugging Contractor Scress  TE OF Kansas  Southwest Casing Pull being first duly sworn on oath, sa	(Hadditional cuthwest Casing Co., COU ling Co., ys: That I have known are true and the same are true and the s	description is necessing Pulling t Bend, Kan  NTY OF	ary, use BACK of Co. ses  Berton mployee of co. cots, statemen	sed plug- sed plug- STATE CUR  With the second seco	Sacke come and display and display and display and also play and a sacker and a sac	ent thru  need with 125  // //  // //  // //  // //  // //  // //  // //
ade bottom hole plug be ump bailer.  queezed hole with 3 sad acks 50/50 pozmix with with a sad acks 50/50 pozmix with a sad acks 50/	(Hadditional cuthwest Casing Co., COU ling Co., ys: That I have known are true and the same are true and the s	description is necessary Pulling t. Bend, Kan  NTY OF	Barton cots, statementaling me God.	STATE COR.  STATE COR.  CONSER  VVIC.  Withis sheet)	and displand of the second displant displant of the second displant of the second displant dis	of the above-describe and the log of the
ade bottom hole plug be ump beiler.  queezed hole with 3 sad acks 50/50 pozmix with  e of Plugging Contractor Scress  TE OF Kansas  Southwest Casing Pull being first duly swom on oath, sage described well as filed and that the same described well as filed and the same described well as fi	(Hadditional cuthwest Casi) Box 364 Great  Country: That I have buther and the same are true and the same are	description is necessary Pulling t. Bend, Kan  NTY OF	Berton  mployee of contests, statement the God.  Dox 364	sed plug- STATE COR  CONSER  VIC	Sacke come and display and display and display and also play and a sacker and a sac	of the above-describe and the log of the
ade bottom hole plug be umm bailer. queezed hole with 3 sac acks 50/50 pozmix with  e of Plugging Contractor Sc ess TE OF Kansas Southwest Casing Pull being first duly sworn on oath, sa	(Hadditional cuthwest Casi) Box 364 Great  Country: That I have buther and the same are true and the same are	description is necessary Pulling t. Bend, Kan  NTY OF	Barton cots, statementaling me God.	sed plug- STATE COR  CONSER  VIC	and displand of the second displand of the second of the s	ont thru  need with 125  MISSION  SION  of the above describe ined and the log of the
ade bottom hole plug be umm bailer.  queezed hole with 3 sad acks 50/50 pozmix with  e of Plugging Contractor Scress TE OF Kans as Southwest Casing Pull being first duly swom on oath, sage-described well as filed and that the Subscribed well as filed and the subscribed well as fil	(Hadditional cuthwest Casi) Box 364 Great  Country: That I have buther and the same are true and the same are	description is necessary Pulling t. Bend, Kan  NTY OF	Berton  mployee of contests, statement the God.  Dox 364	STATE COR.  STATE COR.  When you con the contract of the contr	and disple  3-/5  ECEIVEE PORATION COMM AP 15 1972  VATION DIVIS  Mita, Kansas  A CI  end, Kansas  (Address)  19	of the above-describe ined and the log of the
Made bottom hole plug be dump beiler.  Equeezed hole with 3 sacks 50/50 pozmix with the sacks 50/50 pozmix with sa	cks hulls — 2 2% gel.  (Hadditional outhwest Casi) Box 364 Great  , COU ling Co.  ys: That I have known the same are true and the s	description is necessary Pulling to Bend, Kan  NTY OF	Berton  mployee of contests, statement the God.  Dox 364	STATE COR.  STATE COR.  When you con the contract of the contr	AP 15 1972 VATION DIVIS hita, Kansas  ACLA  Cand. Kansas  (Address)	of the above-describe and the log of the
ATE OF Kansas  Southwest Casing Pull  I, being first duly sworn on oath, sa we-described well as filed and that the	(Hadditional cuthwest Casi) Box 364 Great  Country: That I have buther and the same are true and the same are	description is necessary Pulling to Bend, Kan  NTY OF	Berton  mployee of contests, statement the God.  Dox 364	STATE COR.  STATE COR.  When you con the contract of the contr	and disple  3-/5  ECEIVEE PORATION COMM AP 15 1972  VATION DIVIS  Mita, Kansas  A CI  end, Kansas  (Address)  19	of the above-describe ined and the log of the

6 5/8" 0 765 - 275 sx 5 1/2" 0 3315 - 100 sx

ALLAN, et al #2 CLARKE
MR NE SE 25-19-14#
Barton County, Kansas
COMM: 5/27/52 COMFL: 6/12/52
CONTHACTOR: Tom Allan
ELEVATION: 1866 DF
1868 RB
L. P. Swab 12 to 15 DOPH

## Depth from Rotary Bushings

0 🕳	15	Surface Soil
	120	Sand
,	280	Gray Shale
	305	Sand
	764	Red Beds
	768	Anhydrite
	1180	Red & Gray Shalo with
		Anhydrite Stringers
	1280	Gray Shale
	1500	Shale & Salt
	1600	Shale, Salt & Amhydrite
	1740	Shale & Anhydrite
	1760	Shale
	2380	Lime & Shale
	2780	Shale & Shells
	3116	Lime & Shale
	3185	Sha <b>le</b>
	3315	(RTD) Lime with Shale
		breaks
	3315AB	= 331308

STATE CORPORATION COMMISSION
FERS 1977
CONSERVATION DIVISION
VICTURE, KARCUS

3317F Blue Shale 3317F Dense Brown Lime 3320F (TD) White colitic Lime - Show Oil

## PORMATIONS:

Anhydrite 764RB 1085RB 1085RB 1085RB 1085RB 1085RB 1095RB 1095RB

## TESTING:

Swab 1.20 bbl. Oil per hour Acidize with 2000 gel. Acid Swab 12 to 15 bbl. Oil per hour