STATE OF KANSAS STATE CORPORATION COMMISSION 200 Colorado Derby Bldg. Wichita, Kansas 67202

15-009-23257-2000

WELL PLUGGING RECORD

Make Required Affidavit COUNTY Barton Location as in quarters 330' from south line	_	
330' from south line	SEC. 8 TWP. 16 PGE. 12 s or footage from lines:	<u>3</u> ⅓/₩
	, 2310' from west line	
Lease Name <u>Luerman</u>	Well No. 1	
	, Box 183-B, Great Bend, Kansas 67	
Character of Well (Com	oleted as Oil, Gas or Dry Hole):	oil
Date Well Completed	10/08/83	
Application for pluggin	ng filed <u>04-12-85</u>	
Plugging commenced	04-15-85	
	04-25-85	
	of well or producing formation	
Locate Well		
	d from the Conservation Division or	
4.1.4	g was connenced? yes	
Name of Conservation Agent who supervised plugging	e of this well Gilbert Scheck	
Producing formation Topeka Depth to top		י
Show depth and thickness of all water, oil and gas	11 - 11	-(
OII GAS OR WATER RECORDS		Record
Formation Content From To Surface 0 31		ed Out N
Production 0 338		•
- AP (2017) - AP (2017)		
fluid was placed and the method or methods used in or other plugs were used, state the character of to feet for each plug set.	same and depth placed, from	feet
Dumped 5 sacks of cement on Halliburton at 2450', pipe would not come, shot at 2	354', could not pull, shot at 2250	pe •
	354', could not pull, shot at 2250	pe ',
at 2450', pipe would not come, shot at 2 pulled 57 joints of 5½" casing. 04-25-85 Halliburton dumped 4 sacks of	hulls, 25 sacks of cement, 12 sack	s of
at 2450', pipe would not come, shot at 2pulled 57 joints of 5½" casing04-25-85 Halliburton dumped 4 sacks ofgel, 40 sacks cement, 3 sacks gel, 1 sac	hulls, 25 sacks of cement, 12 sack	s of
at 2450', pipe would not come, shot at 2 pulled 57 joints of 5½" casing. 04-25-85 Halliburton dumped 4 sacks of gel, 40 sacks cement, 3 sacks gel, 1 sac 100 sacks of cement, maximum pressure 1	hulls, 25 sacks of cement, 12 sack hulls. Pull in wiper plug 8 5/8 700, shut in pressure 1250.	s of
at 2450', pipe would not come, shot at 2 pulled 57 joints of 5½" casing. 04-25-85 Halliburton dumped 4 sacks of gel, 40 sacks cement, 3 sacks gel, 1 sac 100 sacks of cement, maximum pressure 1	hulls, 25 sacks of cement, 12 sack hulls. Pull in wiper plug 8 5/8 700,4 shut in pressure 1250.	s of
at 2450', pipe would not come, shot at 2pulled 57 joints of 5½" casing. 04-25-85 Halliburton dumped 4 sacks ofgel, 40 sacks cement, 3 sacks gel, 1 sac100 sacks of cement, maximum pressure 1	hulls, 25 sacks of cement, 12 sack hulls. Pull in wiper plug 8 5/8 700, shut in pressure 1250.	s of
at 2450', pipe would not come, shot at 2pulled 57 joints of 5½" casing. 04-25-85 Halliburton dumped 4 sacks ofgel, 40 sacks cement, 3 sacks gel, 1 sac100 sacks of cement, maximum pressure 1	hulls, 25 sacks of cement, 12 sack hulls. Pull in wiper plug 8 5/8 700, shut in pressure 1250.	s of
at 2450', pipe would not come, shot at 2 pulled 57 joints of 5½" casing. O4-25-85 Halliburton dumped 4 sacks of gel, 40 sacks cement, 3 sacks gel, 1 sacks of cement, maximum pressure 1 (If additional description is necessary Name of Plugging Contractor D. S. & W. Well S	hulls, 25 sacks of cement, 12 sack k hulls. Pull in wiper plug 8 5/8 700, hishut in pressure 1250.	s of
at 2450', pipe would not come, shot at 2 pulled 57 joints of 5½" casing. 04-25-85 Halliburton dumped 4 sacks of gel, 40 sacks cement, 3 sacks gel, 1 sac 100 sacks of cement, maximum pressure 1 (If additional description is necessary Name of Plugging Contractor D. S. & W. Well S STATE OFKansas. COUNTY OF Barton	hulls, 25 sacks of cement, 12 sack k hulls. Pull in wiper plug 8 5/8 700, shut in pressure 1250. y, use RACK of this sheet) servicing, Inc. operator No. 6901	s of
at 2450', pipe would not come, shot at 2 pulled 57 joints of 5½" casing. O4-25-85 Halliburton dumped 4 sacks of gel, 40 sacks cement, 3 sacks gel, 1 sacks of cement, maximum pressure 1 100 sacks of cement, maximum pressure 1 (If additional description is necessary Name of Plugging Contractor D. S. & W. Well S STATE OFKansas COUNTY OF Barton (XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	hulls, 25 sacks of cement, 12 sack k hulls. Pull in wiper plug 8 5/8 700, hishut in pressure 1250. y. use BACK of this sheet) servicing, Inc. operator No. 6901	s of
at 2450', pipe would not come, shot at 2 pulled 57 joints of 5½" casing. O4-25-85 Halliburton dumped 4 sacks of gel, 40 sacks cement, 3 sacks gel, 1 sacks of cement, maximum pressure 1 100 sacks of cement, maximum pressure 1 (If additional description is necessary Name of Plugging Contractor D. S. & W. Well S STATE OFKansas COUNTY OF Barton COUNTY OF	hulls, 25 sacks of cement, 12 sack k hulls. Pull in wiper plug 8 5/8 700, hishut in pressure 1250. y, use BACK of this sheet) servicing, Inc. operator No. 6901 XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	s of
at 2450', pipe would not come, shot at 2 pulled 57 joints of 5½" casing. O4-25-85 Halliburton dumped 4 sacks of gel, 40 sacks cement, 3 sacks gel, 1 sacks of cement, maximum pressure 1 100 sacks of cement, maximum pressure 1 (If additional description is necessary Name of Plugging Contractor D. S. & W. Well S STATE OFKansas COUNTY OF Barton (XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	hulls, 25 sacks of cement, 12 sack k hulls. Pull in wiper plug 8 5/8 700, hishut in pressure 1250. y, use BACK of this sheet) ervicing, Inc. operator No. 6901 ss. ath, says: That I have knowledge of the log of the above-described we help me God.	s of
at 2450', pipe would not come, shot at 2 pulled 57 joints of 5½" casing. O4-25-85 Halliburton dumped 4 sacks of gel, 40 sacks cement, 3 sacks gel, 1 sacks of cement, maximum pressure 1 100 sacks of cement, maximum pressure 1 Name of Plugging Contractor D. S. & W. Well S. STATE OF Kansas. COUNTY OF Barton (ANNXAYAX) above-described well, being first duly sworm on or facts, statements, and matters herein contained ar filed and that the same are true and correct. So	hulls, 25 sacks of cement, 12 sack k hulls. Pull in wiper plug 8 5/8 700, hishut in pressure 1250. y, use RACK of this sheet) servicing, Inc. operator No. 6901 sth, says: That I have knowledge of the log of the above-described we help me God. Signature)	s of
at 2450', pipe would not come, shot at 2 pulled 57 joints of 5½" casing. O4-25-85 Halliburton dumped 4 sacks of gel, 40 sacks cement, 3 sacks gel, 1 sacks of cement, maximum pressure 1 100 sacks of cement, maximum pressure 1 Name of Plugging Contractor D. S. & W. Well S. STATE OF Kansas. COUNTY OF Barton (ANNXAYAX) above-described well, being first duly sworm on or facts, statements, and matters herein contained ar filed and that the same are true and correct. So	hulls, 25 sacks of cement, 12 sack k hulls. Pull in wiper plug 8 5/8 700, hishut in pressure 1250. y. use BACK of this sheet) servicing, Inc. operator No. 6901 XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	s of
at 2450', pipe would not come, shot at 2 pulled 57 joints of 5½" casing. O4-25-85 Halliburton dumped 4 sacks of gel, 40 sacks cement, 3 sacks gel, 1 sacks of cement, maximum pressure 1 (If additional description is necessary Name of Plugging Contractor D. S. & W. Well S STATE OFKansas COUNTY OF Barton (ANXIVEX above-described well, being first duly sworn on or facts, statements, and matters herein contained ar filed and that the same are true and correct. So	hulls, 25 sacks of cement, 12 sack k hulls. Pull in wiper plug 8 5/8 700, hishut in pressure 1250. y. use BACK of this sheet) servicing, Inc. operator No. 6901 ath, says: That I have knowledge of the above-described with help me God. Signature) Great Bend, Kansas (Address)	s of
at 2450', pipe would not come, shot at 2 pulled 57 joints of 5½" casing. 04-25-85 Halliburton dumped 4 sacks of gel, 40 sacks cement, 3 sacks gel, 1 sacks of cement, maximum pressure 1 100 sacks of cement 1 100 sacks of cement 1 100 sacks of cem	hulls, 25 sacks of cement, 12 sack k hulls. Pull in wiper plug 8 5/8 700, hishut in pressure 1250. y. use BACK of this sheet) servicing, Inc. operator No. 6901 ath, says: That I have knowledge of the above-described with help me God. Signature) Great Bend, Kansas (Address)	s of
at 2450', pipe would not come, shot at 2 pulled 57 joints of 5½" casing. 04-25-85 Halliburton dumped 4 sacks of gel, 40 sacks cement, 3 sacks gel, 1 sacks of cement, maximum pressure 1 pressure 1 (If additional description is necessary Name of Plugging Contractor D. S. & W. Well Section 1 pressure 1 pressure 1 pressure 2 pressure 2 pressure 2 pressure 3 pressure 3 pressure 4 pressure 4 pressure 4 pressure 4 pressure 5 pressure 5 pressure 6 pressure 6 pressure 6 pressure 6 pressure 6 pressure 6 pressure 7 press	hulls, 25 sacks of cement, 12 sack k hulls. Pull in wiper plug 8 5/8 700, hishut in pressure 1250. y. use BACK of this sheet) servicing, Inc. operator No. 6901 ath, says: That I have knowledge of the above-described with help me God. Signature) Great Bend, Kansas (Address)	the f the all as,

HOTARY PUBLIC - State of Kansas BESSIE M. DeWERFF My Appt. Exp. May 20, 1985 STATE CORPORATION COMMISSION

MAY OF 10051

MAY 06 1985

CONSERVATION DIVISION