To:	AP! NUMBER 15- Comp. 4-17-53
STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING SECTION	SW NW SE , SEC. 22 , T 21 S, R 12 W/X
200 COLORADO DERBY BUILDING WICHITA, KANSAS 67202	1650 N SE Corner of feet from XXX section line W SE Corner of
TECHNICIAN'S PLUGGING REPORT	
Operator License # 5354	Lease Name <u>Rose</u> Well / 5
Operator: Southern States Oil Co.	CountyStafford
Address Box 1365	Well Total Depth 3583 116. 45
Great Bend, KS 67530	Conductor Pipe: Sizefeet
<u> </u>	Surface Casing: \$1ze 8 5/8 feet 282
Abandoned Oll Well X Gas Well	Input Well D&A
Other well as hereinafter indicated	
Plugging Contractor Kelso Casing Pullin	ngLicense Number6050
Address Box 347, Chase, KS 67524	
Company to plug at: Hour: 10:00 am Day:	17 Month: September Year:19 84
Plugging proposal received from	Bob Brenneman
	(phone) 316-938-2457
(company name) Kelso	(phone) 316-938-2457
(company name) Kelso were: 5 1/2" set at 3581 Perfs 3422-	-28'
(company name) Kelso were: 5 1/2" set at 3581 Perfs 3422- 1st plug sand back to 3370' and dump 5 s	ex cement on top of sand through bailer
(company name) Kelso were: 5 1/2" set at 3581 Perfs 3422- 1st plug sand back to 3370' and dump 5 s	ex cement on top of sand through bailer O sx gel, 50 sx cement, 10 sx gel, 1 sack hulls,
(company name) Kelso were: 5 1/2" set at 3581 Perfs 3422- 1st plug sand back to 3370' and dump 5 second plug squeeze well with 3 sx hulls, 1	ex cement on top of sand through bailer O sx gel, 50 sx cement, 10 sx gel, 1 sack hulls,
Kelso were: 5 1/2" set at 3581 Perfs 3422- 1st plug sand back to 3370' and dump 5 s 2nd plug squeeze well with 3 sx hulls, 1 release 8 5/8" rubber plug and pump 100	ex cement on top of sand through bailer O sx gel, 50 sx cement, 10 sx gel, 1 sack hulls, sx cement
Kelso were: 5 1/2" set at 3581 Perfs 3422- 1st plug sand back to 3370' and dump 5 s 2nd plug squeeze well with 3 sx hulls, 1 release 8 5/8" rubber plug and pump 100	ex cement on top of sand through bailer O sx gel, 50 sx cement, 10 sx gel, 1 sack hulls,
Kelso vere: 5 1/2" set at 3581 Perfs 3422- 1st plug sand back to 3370' and dump 5 s 2nd plug squeeze well with 3 sx hulls, 1 release 8 5/8" rubber plug and pump 100 Plugging Pro	ex cement on top of sand through bailer O sx gel, 50 sx cement, 10 sx gel, 1 sack hulls, sx cement oposa: Received by J. H. Metz (TECHNICIAN)
Kelso were: 5 1/2" set at 3581 Perfs 3422- 1st plug sand back to 3370' and dump 5 s 2nd plug squeeze well with 3 sx hulls, 1 release 8 5/8" rubber plug and pump 100 Plugging Pro	ex cement on top of sand through bailer O sx gel, 50 sx cement, 10 sx gel, 1 sack hulls, sx cement oposa: Received by J. H. Metz (TECHNICIAN)
Kelso were: 5 1/2" set at 3581, Perfs 3422- 1st plug sand back to 3370' and dump 5 s 2nd plug squeeze well with 3 sx hulls, 1 release 8 5/8" rubber plug and pump 100 Plugging Pro Plugging Operations attended by Agent?: Operations Completed: Hour: 12:30 pmDay:	ex cement on top of sand through bailer O sx gel, 50 sx cement, 10 sx gel, 1 sack hulls, sx cement oposa: Received by J. H. Metz (TECHNICIAN) All X Part None 17 Month: September Year:19 84
Kelso were: 5 1/2" set at 3581, Perfs 3422- 1st plug sand back to 3370' and dump 5 s 2nd plug squeeze well with 3 sx hulls, 1 release 8 5/8" rubber plug and pump 100 Plugging Pro Plugging Operations attended by Agent?: Operations Completed: Hour: 12:30 pmDays ACTUAL PLUGGING REPORT 5 1/2" set at 3	ex cement on top of sand through bailer O sx gel, 50 sx cement, 10 sx gel, 1 sack hulls, sx cement oposa: Received by J. H. Metz (TECHNICIAN) All X Part None 17 Month: September Year:19 84
Kelso were: 5 1/2" set at 3581 Perfs 3422- 1st plug sand back to 3370' and dump 5 s 2nd plug squeeze well with 3 sx hulls, 1 release 8 5/8" rubber plug and pump 100 Plugging Pro Plugging Operations attended by Agent?: Operations Completed: Hour: 12:30 pm Day: ACTUAL PLUGGING REPORT 5 1/2" set at 3 1st plug sanded back to 3370' and dumped	ex cement on top of sand through bailer O sx gel, 50 sx cement, 10 sx gel, 1 sack hulls, sx cement Oposa: Received by J. H. Metz (TECHNICIAN) All X Part None 17 Month: September Year:19 84 3581' Perfs at 3422-28' 15 sx cement on top of sand through bailer 10 sx gel, 50 sx cement, 10 sx gel, 1_sack-hulls
Kelso were: 5 1/2" set at 3581 Perfs 3422- 1st plug sand back to 3370' and dump 5 s 2nd plug squeeze well with 3 sx hulls, 1 release 8 5/8" rubber plug and pump 100 Plugging Pro Plugging Operations attended by Agent?: Operations Completed: Hour: 12:30 pmDay: ACTUAL PLUGGING REPORT 5 1/2" set at 3 1st plug sanded back to 3370' and dumped 2nd plug squeezed well with 3 sx hulls,	ex cement on top of sand through bailer O sx gel, 50 sx cement, 10 sx gel, 1 sack hulls, sx cement Oposa: Received by J. H. Metz (TECHNICIAN) All X Part None 17 Month: September Year:19 84 3581' Perfs at 3422-28' 15 sx cement on top of sand through bailer 10 sx gel, 50 sx cement, 10 sx gel, 1 sack-hulls
Kelso vere: 5 1/2" set at 3581, Perfs 3422- 1st plug sand back to 3370' and dump 5 s 2nd plug squeeze well with 3 sx hulls, 1 release 8 5/8" rubber plug and pump 100 Plugging Pro Plugging Operations attended by Agent?: Operations Completed: Hour: 12:30 pmDay: ACTUAL PLUGGING REPORT 5 1/2" set at 3 1st plug sanded back to 3370' and dumped	ex cement on top of sand through bailer O sx gel, 50 sx cement, 10 sx gel, 1 sack hulls, sx cement Oposa: Received by J. H. Metz (TECHNICIAN) All X Part None 17 Month: September Year:19 84 S581' Perfs at 3422-28' S sx cement on top of sand through bailer 10 sx gel, 50 sx cement, 10 sx gel, 1 sack hulls helder 10 sx gel, 50 sx cement, 10 sx gel, 1 sack hulls helder 10 sx gel, 50 sx cement, 10 sx gel, 1 sack hulls helder STATE CORPORATION COMMISSION
Kelso were: 5 1/2" set at 3581 Perfs 3422- 1st plug sand back to 3370' and dump 5 s 2nd plug squeeze well with 3 sx hulls, 1 release 8 5/8" rubber plug and pump 100 Plugging Pro Plugging Operations attended by Agent?: Operations Completed: Hour: 12:30 pm Day: ACTUAL PLUGGING REPORT 5 1/2" set at 3 1st plug sanded back to 3370' and dumped 2nd plug squeezed well with 3 sx hulls, released 8 5/8" rubber plug and pumped 1 Maximum pressure 500 psi and shut in pre Remarks: They recovered 1800' 5 1/2" cas	ex cement on top of sand through bailer 10 sx gel, 50 sx cement, 10 sx gel, 1 sack hulls, sx cement 10 sx gel, 50 sx cement, 10 sx gel, 1 sack hulls, sx cement 10 sx cement 11
Kelso Were: 5 1/2" set at 3581 Perfs 3422- 1st plug sand back to 3370' and dump 5 s 2nd plug squeeze well with 3 sx hulls, 1 release 8 5/8" rubber plug and pump 100 Plugging Pro Plugging Operations attended by Agent?: Operations Completed: Hour: 12:30 pmDay: ACTUAL PLUGGING REPORT 5 1/2" set at 3 1st plug sanded back to 3370' and dumped 2nd plug squeezed well with 3 sx hulls, released 8 5/8" rubber plug and pumped 1 Maximum pressure 500 psi and shut in pre Remarks: They recovered 1800' 5 1/2" cas (If additional description	ex cement on top of sand through bailer 10 sx gel, 50 sx cement, 10 sx gel, 1 sack hulls, sx cement 10 posa; Received by J. H. Metz (TECHNICIAN) All X Part None 17 Month: September Year: 19 84 15 sx cement on top of sand through bailer 10 sx gel, 50 sx cement, 10 sx gel, 1 sack hulls higher to sack through bailer 10 sx gel, 50 sx cement, 10 sx gel, 1 sack hulls higher to sack through bailer 10 sx gel, 50 sx cement, 10 sx gel, 1 sack hulls higher to sack through bailer 10 sx gel, 50 sx cement, 10 sx gel, 1 sack hulls higher to sack through bailer 10 sx gel, 50 sx cement, 10 sx gel, 1 sack hulls higher to sack through bailer 10 sx gel, 50 sx cement, 10 sx gel, 1 sack hulls higher to sack through bailer 10 sx gel, 50 sx cement, 10 sx gel, 1 sack hulls higher to sack through bailer
Kelso were: 5 1/2" set at 3581 Perfs 3422- 1st plug sand back to 3370' and dump 5 s 2nd plug squeeze well with 3 sx hulls, 1 release 8 5/8" rubber plug and pump 100 Plugging Pro Plugging Operations attended by Agent?: Operations Completed: Hour: 12:30 pm Day: ACTUAL PLUGGING REPORT 5 1/2" set at 3 1st plug sanded back to 3370' and dumped 2nd plug squeezed well with 3 sx hulls, released 8 5/8" rubber plug and pumped 1 Maximum pressure 500 psi and shut in pre Remarks: They recovered 1800' 5 1/2" cas	ex cement on top of sand through bailer O sx gel, 50 sx cement, 10 sx gel, 1 sack hulls, sx cement Oposa: Received by J. H. Metz (TECHNICIAN) All X Part None 17 Month: September Year: 19 84 1581' Perfs at 3422-28' 15 sx cement on top of sand through bailer 10 sx gel, 50 sx cement, 10 sx gel, 1 sack hulls RECEIVED STATE CORPORATION COMMISSION Used 60/40 Pozmix 2% gel 3% ccWichita, Kansas Is necessary, use BACK of this form.)
Kelso Were: 5 1/2" set at 3581 Perfs 3422- 1st plug sand back to 3370' and dump 5 s 2nd plug squeeze well with 3 sx hulls, 1 release 8 5/8" rubber plug and pump 100 Plugging Pro Plugging Operations attended by Agent?: Operations Completed: Hour: 12:30 pmDay: ACTUAL PLUGGING REPORT 5 1/2" set at 3 1st plug sanded back to 3370' and dumped 2nd plug squeezed well with 3 sx hulls, released 8 5/8" rubber plug and pumped 1 Maximum pressure 500 psi and shut in pre Remarks: They recovered 1800' 5 1/2" cas (If additional description	ex cement on top of sand through bailer 10 sx gel, 50 sx cement, 10 sx gel, 1 sack hulls, sx cement 10 sx gel, 50 sx cement, 10 sx gel, 1 sack hulls, sx cement 10 posa: Received by J. H. Metz (TECHNICIAN) 11