1090164

200 COLOR	STATE CORPORATION COMMISSION CONSERVATION DIVISION - PLUGGING SECTION 200 COLORADO DERBY BUILDING		C NW NE , SEC.		
WICHITA,	KANSAS 67202				from N/S section
TECHNICIA	N'S PLUGGING RE	PORT .			from W/E section
		5123			Well # A-1
•	Pickrell Drill		County		
Name&					4357 141.60
AQQF855		g, Suite 205			·
•	Wichita, KS 67				feet
					3 5/8 feet 274
Abandoned	Oll Well X	Gas Well	lnput Well	SWD W	VellD&A
Other we!	t as hereinafte	r Indicated			
Plugging	Contractor Roc	khold Engineering		Licens	se Number5111
		Bend, KS 67530	·		
Company †	o plug at: Hour	.9:00 am Day:	17 Month:	May	Year:19 84
		ed from Deacon			
					(nhone) 316_602_25
,		356 PBTD 4200 P			
2nd plug			cement on top of s		
2nd plug	squeeze well wi		sx gel, 50 sx cem		
2nd plug	squeeze well wi	th 2 sx hulls, 10	sx gel, 50 sx cem	ent, 10 s	
2nd plug cement Maximum p	squeeze well wi	th 2 sx hulls, 10 nd shut in pressu Prugging Pro	sx gel, 50 sx cem	10 s	and 150 sx Muttan (TECHNICIAN)
2nd plug cement. Maximum p	squeeze well wi ressure 700# a	th 2 sx hulls, 10 nd shut in pressu Prugging Pro nded by Agent?:	sx gel, 50 sx cem re 400# posal Received by	ent, 10 s	and 150 sx Muttan (TECHNICIAN)
2nd plug cement. Maximum p Plugging Operation	squeeze well wi ressure 700# a Operations atte s Completed: H	nd shut in pressu Plugging Pro nded by Agent?: our: 11:40 ampay:	sx gel, 50 sx cem re 400# posal Received by AllPar	t X	Official Section (Technicial) None Year: 19 84
2nd plug cement. Maximum p Plugging Operation ACTUAL PL	squeeze well wi ressure 700# a Operations atte s Completed: H	nd shut in pressured by Agent?: our: 11:40 ampay: 5 1/2 set at 4356	sx gel, 50 sx cem re 400# posal Received by All Par 17 Month:	t X May s 4136-38	Official Service (Technicial) None Year: 19 84
2nd plug cement. Maximum p Plugging Operation ACTUAL PL lst plug	squeeze well wing ressure 700# a completed: Hugging REPORT sand back to 40	nd shut in pressu Plugging Pro nded by Agent?: our: 11:40 ampay: 5 1/2 set at 4356 75 and dump 5 sx	sx gel, 50 sx cem re 400# posal Received by All Par 17 Month: PBTD 4200' Perf	t X May s 4136-38	(TECHNICIAN) None Year: 19 84
2nd plug cement. Maximum p Plugging Operation ACTUAL PL lst plug	squeeze well wing ressure 700# a completed: Hugging REPORT sand back to 40	nd shut in pressu Plugging Pro nded by Agent?: our: 11:40 ampay: 5 1/2 set at 4356 75 and dump 5 sx	re 400# posal Received by All Par 17 Month: ' PBTD 4200' Perf cement on top of s	t X May s 4136-38	(TECHNICIAN) None Year: 19 84
2nd plug cement. Maximum p Plugging Operation ACTUAL PL 1st plug 2nd plug cement	squeeze well wing ressure 700# a completed: Hugging REPORT sand back to 40 squeeze well wi	nd shut in pressu Plugging Pro nded by Agent?: our: 11:40 ampay: 5 1/2 set at 4356 75 and dump 5 sx th 2 sx hulls, 10	sx gel, 50 sx cem re 400# posal Received by All Par 17 Month: ' PBTD 4200' Perf cement on top of s sx gel, 50 sx cem	t X May s 4136-38	(TECHNICIAN) None Year: 19 84
2nd plug cement. Maximum p Plugging Operation ACTUAL PL 1st plug 2nd plug cement	squeeze well wing ressure 700# a completed: Hugging REPORT sand back to 40 squeeze well wi	nd shut in pressu Plugging Pro nded by Agent?: our: 11:40 ampay: 5 1/2 set at 4356 75 and dump 5 sx	sx gel, 50 sx cem re 400# posal Received by All Par 17 Month: ' PBTD 4200' Perf cement on top of s sx gel, 50 sx cem	t X May s 4136-38	None Year:19 Sx gel and 150 sx STATE CORPORATION ED MAL
2nd plug cement. Maximum p Plugging Operation ACTUAL PL 1st plug 2nd plug cement Maximum p	squeeze well wi ressure 700# a Operations atte s Completed: H UGGING REPORT_ sand back to 40 squeeze well wi ressure 700# an	nd shut in pressu Plugging Pro nded by Agent?: our: 11:40 ampay: 5 1/2 set at 4356 75 and dump 5 sx th 2 sx hulls, 10 d shut in pressur	sx gel, 50 sx cem re 400# posal Received by Al! Par 17 Month: ' PBTD 4200' Perf cement on top of s sx gel, 50 sx cem e 400#	t X May s 4136-38 and throughout, 10 s	None Year:19 Sx gel and 150 sx STATE CORPORATION ED MAL
2nd plug cement. Maximum p Plugging Operation ACTUAL PL 1st plug 2nd plug cement Maximum p	squeeze well wi ressure 700# a Operations atte s Completed: H UGGING REPORT_ sand back to 40 squeeze well wi ressure 700# an	nd shut in pressu Plugging Pro nded by Agent?: our: 11:40 ampay: 5 1/2 set at 4356 75 and dump 5 sx th 2 sx hulls, 10 d shut in pressur	sx gel, 50 sx cem re 400# posal Received by Al! Par 17 Month: ' PBTD 4200' Perf cement on top of s sx gel, 50 sx cem e 400#	t X May s 4136-38 and throughout, 10 s	None Year:19 Sx gel and 150 sx STATE CORPORATION ED MAL
2nd plug cement. Maximum p Plugging Operation ACTUAL PL 1st plug 2nd plug cement. Maximum p Remarks:	operations atte s Completed: H UGGING REPORT sand back to 40 squeeze well wi ressure 700# an Use 60/40 Pozmi	nd shut in pressu Plugging Pro nded by Agent?: our: 11:40 ampay: 5 1/2 set at 4356 75 and dump 5 sx th 2 sx hulls, 10 d shut in pressur	sx gel, 50 sx cem re 400# posal Received by Al! Par 17 Month: ' PBTD 4200' Perf cement on top of s sx gel, 50 sx cem e 400#	t X May s 4136-38 and throughout, 10 s	TATE CORPORATION COM SERV.
2nd plug cement. Maximum p Plugging Operation ACTUAL PL 1st plug 2nd plug cement. Maximum p Remarks:	operations atte s Completed: H UGGING REPORT sand back to 40 squeeze well wi ressure 700# an Use 60/40 Pozmi	nd shut in pressu Plugging Pro nded by Agent?: our: 11:40 ampay: 5 1/2 set at 4356 75 and dump 5 sx th 2 sx hulls, 10 d shut in pressur x 2% gel 3% cc by nal description i	sx gel, 50 sx cem re 400# posal Received by Al! Par 17 Month: ' PBTD 4200' Perf cement on top of s sx gel, 50 sx cem e 400#	t X May s 4136-38 and throughout, 10 s	Sx gel, and 150 sx (TECHNICIAN) None Year: 19 84 3 1gh bailer Sx gel and 150 sx STATE CORPORATION COM CONSERVATION ON USING WICHIE TO WINDOW SION LIST FOR MANAGEN SION LIST FOR MANAGEN SION LUCLUM SX LUCLUM
2nd plug cement. Maximum p Plugging Operation ACTUAL PL 1st plug 2nd plug cement. Maximum p	operations atte s Completed: H UGGING REPORT sand back to 40 squeeze well wi ressure 700# an Use 60/40 Pozmi	nd shut in pressu Plugging Pro nded by Agent?: our: 11:40 ampay: 5 1/2 set at 4356 75 and dump 5 sx th 2 sx hulls, 10 d shut in pressur x 2% gel 3% cc by nal description i	sx gel, 50 sx cem re 400# posal Received by All Par 17 Month: ' PBTD 4200' Perf cement on top of s sx gel, 50 sx cem e 400# Allied s necessary, use B	t X May s 4136-38 and throughout, 10 s	None Year:19 Sx gel and 150 sx STATE CORPORATION ED MAL