## CORRECTION

15-113.20073.0000

STATE CORPORATION COMMISSION CONSERVATION DIVISION - Plugging Section 200 Colorado Derby Building Wichita, Kansas 67202 SENWNE

SE-SW-NE API NUMBER: $15-113-13-13-13-13-13-13-13-13-13-13-13-13$
OPERATOR LICENSE # 30280 2970 FEET FROM S SECTION LINE
TOO ILLE TROPE ESTA
OPERATOR <u>Sunflower Well Service</u>
NAME & P. O. Box 341  ADDRESS Canton, KS 67428
LEASE NAME:
COUNTY: McPherson
WELL TOTAL DEPTH:
CONDUCTOR PIPE:
surface casing: $8-5/8$ $^{"}$ $8$
ABANDONED OIL WELL X GAS WELL INPUT WELL SWD D&A
OTHER WELL AS HEREINAFTER INDICATED:
PLUGGING CONTRACTOR: Sunflower Well Service
ADDRESS: P. O. Box 341, Canton, KS 67428 LICENSE: 30280
COMPANY TO PLUG AT: HOUR: 12:00 DAY: 25 MONTH: 9 YR: 1992
PLUGGING PROPOSAL RECEIVED FROM: Bud Davis  COMPANY NAME: Sunflower Well Service PHONE: 316-628-4723
Sand to 3310' & top w/4 sx cmt - perfs 3360' - 3370' - shoot pipe off & circ cmt from 350 to surface.
PLUGGING PROPOSAL RECEIVED BY: Dave Wertz
PLUGGING OPERATIONS ATTENDED BY AGENT? ALL ( $X$ ) PART ( ) NONE ( )
COMPLETED: HOUR: 12:00 DAY: 25 MONTH: 9 YEAR: 1992
ACTUAL PLUGGING REPORT:  Shot pipe off @ 888' - built bridge at 330' & filled
csq w/slurry mix - used 99 sx cmt & 396 gallons water -
retrieved 888' of 4-1/2" csq Sanded to 3310' & topped w/4 sx.
REMARKS: Plenert Concrete #4204
I DID OBSERVE THIS PLUGGING.
Michael R. Wilson (AGENT)

## KCC OIL/GAS REGULATORY OFFICE

<u> DATE: 01/05/01</u>

[ X ] New Situation
[ ] Response to Request
[ ] Follow-Up

OPERATOR: Sunflower Well Service

**LICENSE #:** 30280

LOCATION: SE-SW-NE, SEC: 24, T: 21S, R: 2W

ADDRESS: P.O. Box 341

LEASE: Duerksen NO.: 1

ADDRESS: Canton, KS 67428

COUNTY: McPherson

**PHONE #:** 316-628-4723

LEASE INSPECTION:

COMPLAINT:

FIELD REPORT: X

**REASON FOR INVESTIGATION:** Clarify if the Duerksen #1 or Duerksen #2 was plugged.

**PROBLEM:** Confusing on well number and location concerning plugging of 09/25/92.

PERSONS CONTACTED: None.

FINDINGS: The Duerksen #1 well located in the SE-SW-NE of the section was plugged on 09/25/92. There is no well at this location. The plugging contractor supplied incorrect information on the CP-1 calling the plugged the Duerksen #2. The spot location given on the CP-1, filed with the K.C.C., was the SE-NW-NE of the section. The Duerksen #2 well is an oil well, on the location, with rods and tubing in place at the time of the inspection. The Duerksen #2 well is to be converted to an U.I.C. well in the near future.

PHOTOS TAKEN: None.

<u>ACTION/RECOMMENDATIONS</u>: Correct CP-2/3 on file with central office and District #2 office.

Michael R. Wilson P.I.R.T. II 01/16/01

CC: Mike Engelbrecht

B. E. SHEL	TON		#1 DUERKSEN SE SW NE
WICHITA, K			FI DULKKSEN SE STINE
ContrASPEN	DRLG. COM	PANY	Cty. MC PHERSON
Geol. WALTE	R_MARTZ		Pool WINSINGER
		Cp10	/9/69 IPPMP 79 BOPD + 48% WTR/HUNT 3368-72
API 15-113			
LOGTops	Depth	Datum	Csg. 8-5/8" 268/160 sx: $4\frac{1}{2}$ " 3438/100 sx
MISS	2976	-1479	DST 3364-3375/11, 1740' GIP, 60'
KIND	3296	-1799	CL 01L, 60' MDY GSY 01L, 30'
HUNT	3364	<b>-</b> 1867	O&GCM, 30' SO&GCMW, BHP
MAQ	3380	<u>-1883</u>	707#/30"-707#/45", FP 31-94#
LTD	3439		
	<del> </del>	- <del></del>	CO TO 3407, PF 16/3368-72, SWB
	<del> </del>	<del></del>	DN, NO FU, 250 MA, SWB LD & SWB
<del></del>	<u> </u>		5 BFPH, 10% W/1', 1000 REG ACID SWB LD, FU 600' OIL, 960' M&W/
			12 HRS, SWB 10 BFPH/4 HRS, 50%W
			POP, PMP 48 BOPD + 22% WTR.
			tory the local ELW wing
	<del> </del>		NO CORES
<del></del>	.		,
	The same of the sa	And the particular of the particular transport and the particular transport and the particular part	

WICHITA, KANSAS

## RECEIVED KANSAS CORPORATION COMMISSION:

OCT 8 1992

STATE CORPORATION COMMISSION
CONSERVATION DIVISION - Plugging Section
200 Colorado Derby Building
CONSERVATION DIVISION
WICHITA, KS

INV. NO.

			API NUMBER	: <u>15-</u>	<b>20 e</b> 113- <del>20 ,</del> (	975.00	00
		SE NW NE	E_, SECTION	24_	TOWNSHIP _	21_ RAP	NGE <u>2W</u>
	R LICENSE # 30280		<del>-</del>		FEET FROM S		
	R <u>Sunflower V</u>						
NAME & ADDRESS	P. O. Box Canton, KS						
AUDKE22	cancon, kb	07420		EASE NAME: .	Duerks	sen #2-	1
			C		McPherso	on	
			មា	ELL TOTAL DE	EPTH:34	429 <b>'</b>	11).4
			CONDUCTOR	PIPE:		<del></del>	
			SURFACE CA	sing:8	3-5 <u>/8"</u> (	210'	
ABANDON	ED OIL WELL X	GAS WELL	INPUT WEL	L	SWD	D&A	
OTHER W	ELL AS HEREINAFTER INDIC	CATED:					
PLUGGIN	TO PLUG AT: HOUR:  G PROPOSAL RECEIVED FROM NAME:Sunflowe	ı: <u>Bud Da</u>	vis				
WERE:	Sand to 3310 shoot pipe o					•	
PLUGGIN	G PROPOSAL RECEIVED BY:	Dave_We	rt <u>z</u>				
PLUGGIN	G OPERATIONS ATTENDED BY	AGENT? ALL {	<u>X</u> 3	PART {	э мо	NE {	}
COMPLETA	ED: HOUR: 12:00	<u>)</u> DAY:	25	HTHOM	9	YEAR	: <u>19</u>
ACTUAL I	PLUGGING REPORT:  Shot pipe of csg w/slurry retrieved 888	mix - used B' of 4-1/	l 99 sx c '2" csq	mt & 39	96 gallo	ns wate	er -
DEMADYC	sand Plenert Con	ded to 3310'		-			
		<u>-1200</u> π420	<u>, , ,                                 </u>				
1 Y U	BSERVE THIS PLUGGING.	/<	$\checkmark$				
	36622	7	Michael R.	Wilson	(#	GENT)	— FORM (