NE/4

STATE OF KANSAS STATE CORPORATION COMMISSION

Give All Information Completely
Make Required Affidavit
Mail or Deliver Report to:
Conservation Division
State Corporation Commission
800 Bitting Building

WELL PLUGGING RECORD

Wichita, Kansas		Location as "NE/CNWXSWX" or footage from line NE NE NE; 330 FNL & 990 FEL of						
NORTH		Location as "N	NE/CNW#SW#"	or footage fro	om line NE NE	NE; 330 FN	L & 990 F	EL of
	+ #3	Lease Owner	Made	LLA PETIC GATES	oleum Compa	any		Chitta
· .	د# .	Lease Name _	Da 0/		as, Texas		Well No. 3	MUM
		Office Address				SWDW		
		Character of Well (completed as Oil, Gas or Dry Hole) SWDW Date well completed 10-7-38; DD for SWDW 4-20 19 46						
i	j [Application for plugging filed 12–19 19 55						
	<u> </u>	Application for plugging approved 12-20 19 55						
		Plugging commenced 1-10 19 56						
	!	Plugging completed						
		Reason for abandonment of well or producing formation Junk hole						
! !]	If a producing well is abandoned, date of last production None 19						
		_			_			.9
Locate well correctly on al Section Plat	oove		on obtained from es	the Conserv	vation Division	or its agents bero	re plugging wa	ıs com-
Name of Conservation Agent N	vho supervi			M. Brund	lege	44		
Producing formation Non	e Î		Depth to top	Botton	m	Total Depth of	Well 4100	Feet
Show depth and thickness of a	ll water, o					_		
OIL, GAS OR WATER F	ECORDS					(CASING RECO	רואנ
				 	 	 	1	
FORMATION		CONTENT	FROM	TD	SIZE	PUT IN	PULLED OU	
None					13"	240 3660	None	
			 		5] :11	163	None	
							210220	
								
		· · · ·		<u> </u>	<u> </u>	<u> </u>	<u> </u>	
	0 2 c ((c	565', fill D csg; fill " tub, pump mnt (no fil 5' fill up 18' fill to mnt at btm o 25', set o btm of ce	hole w/mudin 50 sx of up); dump to 250°), dum of surface 5° rock bri	to 260; ennt, pul 20 sm c tump 20 sm p 10 sx 100 sx);	, set 5° 1 1 2° tub 8 munt at 25° ex cunt & c cunt fill fill surf	check top theck top heck fill up to 2121 ace pipe w	; run of fill up up (total ith mud	
						MEL		112010V
						TATE CORE	माप्तारा	
						211	VII 5 1 12:01	-
<u> </u>	-				-	J		
						COMOE	<u> </u>	<i></i>
		(If addition	al description is nece	ssarv. use BAC	C of this sheet)	<u> </u>	ar le	5 4
Name of Plugging Contractor		<u> Pipe Pulli</u>	ng Co.				1-29	
Address	Gre	<u>at Bend, Kar</u>	nsas					
STATE OF KANSAS R. C. B well, being first duly sworn o above-described well as filed	n oath, say	rs: That I have k	nowledge of the and correct. So i	facts, statem	ents, and matte	-, ss. 267 or operator) rs herein contain and, Kansas Address)	of the above-de	escribed; of the
Subscribed and Sworn		me this <u>21;t1</u>	day of_	Janu	uett L	Kais	56 Notary Pu	uhlia
My commission expires 1-	LL-57						wotary Pu	www.
	PLI	GGING	24.7368.5 3	59-20M				

MON MON 25 UHE 20

このでは 神経の はられ

Mattie GATES #3 SWDW P&A NE'NE NE; Sec 34-21S-13W Stafford County, Kansas (Gates Field)

ID 4100

1878 DF Elevation

Well Completed 10-7-38 Converted to SWDW 4-20-46

Casing Points:

13" OD 40# lapweld 7" OD 24# Seamless Put In: 240 Pulled: None Left In: 240' Put In: 3660' Pulled: 1778' 7" Left In: 1881' 5" 5월 Seamless Liner Left In: 163' Put In: 1631 Pulled: None

FORMATION RECORD: Formation From σ r 9 0 Cellar 9 30 Clay 30 135 Sand & gravel Shale & Shells 135 240 13" OD csg set 240 Red rock & shells 2h0 714 Anhydrite 714 738 930 Shale 738 Shale & line 1215 930 1215 1510 Salt & shale Lime 1510 1735 2055 Lime & shale 1735 Lime 2055 2110 2944 Lime & shale 2110 2944 Lime 3215 3215 3264 Shale 326L Shale & lime 3310 3545 **3310** 3545 Top Viola lime 3571 3613 Top Simpson 3659 3613 Shale Sand & Pyrite 3659 3660 Top Arbuckle 3660 Arbuckle Lime 3660 3662 Cored - 12' recovery 3649 3662 3661 Show oil 7" OD casing set 3660

DD for Salt Water Disposal

Drlg comm 3/2/46 --- Drlg compl 4/20/46 Old TD 3664. 3664 4100 Drilled Arbuckle Lime Set bridge of tree limbs at 3755
Filled up from 3755 to 3728 with crushed rock.
Ran 163' of 52" OD Welded Liner w/HOWCo liner Setting tool on 2" tubing. Bottom of liner 3728 Top of liner 3565. Cemented by HOWCo w/40 sax cement - 600# pressure
Emput test 100 bbl water per hour for 3 hrs on Ran 3500 - 3" plastic lined tubing without packer - open end - filled annular space with crude oil

TD - SLM 4100.

WORK-OVER 11-16-55 to 12-18-55 PURPOSE: Clean out & fish for 3" cmnt lined tub,

clean out hole, run csg & tub & put back in service

Recover all but 8' of tub, lost 2 strings HISTORY: Cable Tools in hole, recover all but 1 set Cable Tools w/Cherry Picker; well temp abandaned - study for abandonment.

Standardized:

Drilled plug

Swabbed 24 bb1 oil per hr for 6 hrs

to bottom.

Arbuckle lime 3662 3664 - cored Swabbed 368 bbl oil in 7 hrs - 34 bbl

last hour 600' off bottom.

3664

Estimated good for 50 BOPH before acid

Pumped 1283 bbl oil - no water on

potential in 24 hrs after acid 1000 gal.

JA1124 1956 CONSERVATION DIVISION Wichita, Konsas

PLUGGING AND ABANDONMENT RECORD:

PLUGGING COMMENCED: 1-10-56 Ace Pipe Pulling Co.,

PLUGGING COMPLETED: 1-19-56 Great Bend, Kansas

HISTORY OF PLUGGING: Plugging: Plug back w/sand to 3645'. Dump 5 sx cmnt, set bridge at 3565',

fill back w/sand to 3540', dump 5 sx cmnt; pull 7" OD csg; fill

hole w/mud to 260', set 5' rock bridge, run 2" tub, pump in 50 sx

cmnt, pull 2" tub & check top of cmnt (no fill up); dump 20 sx cmnt

at 255' & check fill up (5' fill up to 250'); dump 20 sx cmnt &

check fill up (18' fill to 228'); dump 10 sx cmnt fill up to 212'

(total cmnt at bottom of surface 100 sx); fill surface pipe with

mud to 25', set 5' rock bridge, mix & put in 15 sx cmnt, fill to

btm of cellar. Plugging supervised by R. M. Brundege, State Corp

Comm District Plugging Supervisor. Comm District Plugging Supervisor.

PLUGGING erc 34 721 7 13W PAGE 25 LINE 20