₹ ¿, STATE OF KANSAS STATE CORPORATION COMMISSION

Give All Information Completely
Make Required Affidavit
Mail or Deliver Report to;
Conservation Division
State Corporation Commission
212 No. Maybet

WELL PLUGGING RECORD

Wichita, Kansas		777 / AND TERROLOGIC TO 1/18		a linna Ni	W NE SE SW	
NORTH	Location as "N	_	or footage from cial Oil		<u></u>	
	Lease Owner_ Lease Name _			Company		_ Well No. 1
	Office Address		. Broadwa	y, Wic	hita, Kansa	
<u> </u>		Well (completed	as Oil, Gas or	Dry Hole) _	011	
	Date well con		7-1	7		19
		r plugging filed_		ary 7	 	19
		r plugging approv		ary 16		19 19
	Plugging comp			ary 19		19
	Reason for aba	andonment of wel	l or producing	formation	Dry	
		well is abandon		_		19 fore plugging was
Locate well correctly on above Section Plat	menced?			HOICE DIVISION	Of its agents bei	ore plugging was
Name of Conservation Agent who su	pervised plugging of t	his well G11	<u>bert Toma</u>	n		
Producing formation			Bottom		Total Depth of	F Well 3416
Show depth and thickness of all wat	ter, oil and gas formation	ons.				
OIL, CAS OR WATER RECO	RD\$					CASING RECO
FORMATION	BONTENT	FROM	TD	SIZE	PUT IN	PULLED OUT
				7"		431'
· · · · · · · · · · · · · · · · · · ·						-
	- -	 			 	-
			†	<u> </u>	<u> </u>	
	·					
<u> </u>	_1					<u> </u>
bridge 215 f	t 3080 ft. Roc t. to 200 ft. rds of Ready M	<u>Dumped 6 sa</u>	cks of ce	ment. Ba	iled water	
Set bridge a bridge 215 f Dumped 10 ya	t 3080 ft. Roc t. to 200 ft.	<u>Dumped 6 sa</u>	cks of ce	ment. Ba	iled water	
Set bridge a bridge 215 f Dumped 10 ya	t 3080 ft. Roc t. to 200 ft.	<u>Dumped 6 sa</u>	cks of ce	ment. Ba	iled water	
Set bridge a bridge 215 f Dumped 10 ya	t 3080 ft. Roc t. to 200 ft.	<u>Dumped 6 sa</u>	cks of ce	ment. Ba	iled water	
Set bridge a bridge 215 f Dumped 10 ya	t 3080 ft. Roc t. to 200 ft.	<u>Dumped 6 sa</u>	cks of ce	ment. Ba	iled water	down.
Set bridge a bridge 215 f Dumped 10 ya	t 3080 ft. Roc t. to 200 ft.	<u>Dumped 6 sa</u>	cks of ce	ment. Ba	Iled water RE(DEIVED
Set bridge a bridge 215 f Dumped 10 ya	t 3080 ft. Roc t. to 200 ft.	<u>Dumped 6 sa</u>	cks of ce	ment. Ba	iled water	DEIVED
Set bridge a bridge 215 f Dumped 10 ya	t 3080 ft. Roc t. to 200 ft.	<u>Dumped 6 sa</u>	cks of ce	ment. Ba	RE(STATE CORPORATE CONSERV	CEIVED RATION COMMISS R 2 1970 ATION DIVISION
Set bridge a bridge 215 f Dumped 10 ya	t 3080 ft. Roc t. to 200 ft.	<u>Dumped 6 sa</u>	cks of ce	ment. Ba	RE(STATE CORPORATE CONSERV	CEIVED RATION COMMISS R2 1970
Set bridge a bridge 215 f Dumped 10 ya	t 3080 ft. Roc t. to 200 ft.	<u>Dumped 6 sa</u>	cks of ce	ment. Ba	RE(STATE CORPORATE CONSERV	CEIVED RATION COMMISS R 2 1970 ATION DIVISION
Set bridge a bridge 215 f Dumped 10 ya	t 3080 ft. Roc t. to 200 ft. rds of Ready M	Dumped 6 saix cement.	cks of ce	ment. Ba	RE(STATE CORPORATE CONSERV	CEIVED RATION COMMISS R 2 1970 ATION DIVISION
Set bridge a bridge 215 f Dumped 10 ya Name of Plugging Contractor	t 3080 ft. Roc t. to 200 ft. rds of Ready M	Dumped 6 sa ix cement. al description is nece 1 Servicing	cks of ce	ment. Ba	RE(STATE CORPORATE CONSERV	CEIVED RATION COMMISS R 2 1970 ATION DIVISION
Set bridge a bridge 215 f Dumped 10 ya Name of Plugging Contractor Address P.	(If addition Flowers Well O. Box 122,	Dumped 6 sa ix cement. al description is nece 1 Servicing Peabody, K	cks of ce	of this sheet)	RE(STATE CORPORATE CONSERV	CEIVED RATION COMMISS R 2 1970 ATION DIVISION
Set bridge a bridge 215 f Dumped 10 ya Name of Plugging Contractor Address P. STATE OF Kansas	(If addition Flowers Well O. Box 122, CO Douglas G. Po	Dumped 6 sa ix cement. al description is nece 1 Servicing Peabody, K UNTY OF	ssary, use BACK , Inc. ansas Marion	of this sheet) 66866	RE(STATE CORPORATE CONSERV. Wich , ss. vner or operator)	CEIVED RATION COMMISS R 2 1970 ATION DIVISIONITA, Kansas
Set bridge a bridge 215 f Dumped 10 ya Name of Plugging Contractor Address P. STATE OF Kansas well, being first duly sworn on oath	(If addition Flowers Well O. Box 122, CO Douglas G. Poth, says: That I have kere to 200 ft.	Dumped 6 sa ix cement. al description is nece 1 Servicing Peabody, K UNTY OF	ssary, use BACK Inc. ansas Marion angleyexeks facts, stateme	of this sheet) 66866	RE(STATE CORPORATE CONSERV. Wich , ss. vner or operator)	CEIVED RATION COMMISS R 2 1970 ATION DIVISIONITA, Kansas
Set bridge a bridge 215 f Dumped 10 ya Name of Plugging Contractor Address P. STATE OF Kansas well, being first duly sworn on oath	(If addition Flowers Well O. Box 122, CO Douglas G. Poth, says: That I have kere to 200 ft.	Dumped 6 sa ix cement. al description is nece 1 Servicing Peabody, K UNTY OF	ssary, use BACK Inc. ansas Marion angleyexeks facts, stateme	of this sheet) 66866	RE(STATE CORPORATE CONSERV. Wich , ss. vner or operator)	CEIVED RATION COMMISS R 2 1970 ATION DIVISIONITA, Kansas
Set bridge a bridge 215 f Dumped 10 ya Name of Plugging Contractor Address P. STATE OF Kansas	(If addition Flowers Well O. Box 122, CO Douglas G. Poth, says: That I have kere to 200 ft.	Dumped 6 sa ix cement. al description is nece 1 Servicing Peabody, K UNTY OF	ssary, use BACK Inc. ansas Marion angleyexeks facts, stateme	of this sheet) 66866	RE(STATE CORPORATE CONSERV. Wich , ss. vner or operator)	CEIVED RATION COMMISS R 2 1970 ATION DIVISIONITA, Kansas
Set bridge a bridge 215 f Dumped 10 ya Name of Plugging Contractor Address P. STATE OF Kansas well, being first duly sworn on oath	(If addition Flowers Well O. Box 122, CO Douglas G. Poth, says: That I have kere to 200 ft.	Dumped 6 sa ix cement. al description is nece 1 Servicing Peabody, K UNTY OF rter (mowledge of the and correct. So (Signature)	ssary, use BACK Inc. ansas Marion angleyexeks facts, stateme	of this sheet) 66866	RE(STATE CORPORATE CONSERV. Wich , ss. vner or operator)	CEIVED RATION COMMISS R 2 1970 ATION DIVISIONITA, Kansas
Name of Plugging Contractor Address P. STATE OF Kansas well, being first duly sworn on oath above-described well as filed and the state of the st	(If addition Flowers Well O. Box 122, CO Douglas G. Poth, says: That I have khat the same are true a	Dumped 6 saix cement. al description is necell Servicing Peabody, K UNTY OF	ssary, use BACK, Inc. an sas Marion Exployeexes facts, stateme help me God.	of this sheet) 66866 WKSt) or (overts, and matter.) Kansas	RE(STATE CORPORATION MAI CONSERV. Wich where or operator) ers herein contact 66866 (Address)	CEIVED RATION COMMISS R 2 1970 ATION DIVISION hita, Kansas of the above-desired and the log
Set bridge a bridge 215 f Dumped 10 ya Name of Plugging Contractor Address P. STATE OF Kansas well, being first duly sworn on oath	(If addition Flowers Well O. Box 122, CO Douglas G. Poth, says: That I have khat the same are true a	Dumped 6 sa ix cement. al description is nece 1 Servicing Peabody, K UNTY OF rter (mowledge of the and correct. So (Signature)	ssary, use BACK , Inc. ansas Marion Exployesx&s facts, statementally me God;	of this sheet) 66866 WKSt) or (overts, and matter.) Kansas	RE(STATE CORPORATION MAI CONSERV. Wich where or operator) ers herein contact 66866 (Address)	CEIVED RATION COMMISS R 2 1970 ATION DIVISIONITA, Kansas
Name of Plugging Contractor Address P. STATE OF Kansas well, being first duly sworn on oath above-described well as filed and the state of the st	(If addition Flowers Well O. Box 122, CO Douglas G. Poth, says: That I have khat the same are true a	Dumped 6 saix cement. al description is necell Servicing Peabody, K UNTY OF	ssary, use BACK , Inc. an sas Marion supplements facts, statements help me God. Peabody,	of this sheet) 66866 WKM or (overthe and matter) Kansas	RE(STATE CORPORATION MAI CONSERV. Wich where or operator) ers herein contact 66866 (Address)	down. CEIVED RATION COMMISS R 2 1970 ATION DIVISION hita, Kansas of the above-desimed and the log
Set bridge a bridge 215 f Dumped 10 ya Name of Plugging Contractor Address P. STATE OF Kansas well, being first duly sworn on oath above-described well as filed and the specific plant of the second plant.	(If addition Flowers Well O. Box 122, CO Douglas G. Poth, says: That I have khat the same are true a	Dumped 6 sa ix cement. al description is nece 1 Servicing Peabody, K UNTY OF rter (mowledge of the and correct. So (Signature) th day of.	ssary, use BACK , Inc. an sas Marion supplements facts, statements help me God. Peabody,	of this sheet) 66866 Kansas ary	RE(STATE CORPORATION MAI CONSERV. Wich where or operator) ers herein contact 66866 (Address)	CEIVED RATION COMMISS R 2 1970 ATION DIVISION hita, Kansas of the above-desired and the log
Set bridge a bridge 215 f Dumped 10 ya Name of Plugging Contractor Address P. STATE OF Kansas well, being first duly sworn on oath above-described well as filed and the specific plant of the second plant.	(If addition Flowers Well O. Box 122, CO Douglas G. Poth, says: That I have khat the same are true at the same at the same are true at the same at the same are true at the same	Dumped 6 sa ix cement. al description is nece 1 Servicing Peabody, K UNTY OF rter (mowledge of the and correct. So (Signature) th day of.	ssary, use BACK Inc. ansas Marion suppleyexxxx facts, stateme help me God. Peabody, Febru	of this sheet) 66866 Kansas ary	RE(STATE CORPORATION MAI CONSERV. Wich where or operator) ers herein contact 66866 (Address)	down. CEIVED RATION COMMISS R 2 1970 ATION DIVISION hita, Kansas of the above-desimed and the log
Set bridge a bridge 215 f Dumped 10 ya Name of Plugging Contractor AddressP STATE OF Kansas well, being first duly sworn on oath above-described well as filed and the state of the sta	(If addition Flowers Well O. Box 122, CO Douglas G. Poth, says: That I have khat the same are true at the same at the same are true at the same at the same are true at the same	Dumped 6 sa ix cement. al description is nece 1 Servicing Peabody, K UNTY OF rter (mowledge of the and correct. So (Signature) th day of.	ssary, use BACK Inc. ansas Marion suppleyexxxx facts, stateme help me God. Peabody, Febru	of this sheet) 66866 Kansas ary	RE(STATE CORPORATION MAI CONSERV. Wich where or operator) ers herein contact 66866 (Address)	down. CEIVED RATION COMMISS R 2 1970 ATION DIVISION hita, Kansas of the above-desimed and the log
Set bridge a bridge 215 f Dumped 10 ya Name of Plugging Contractor AddressP STATE OF Kansas well, being first duly sworn on oath above-described well as filed and the state of the sta	(If addition Flowers Well O. Box 122, CO Douglas G. Poth, says: That I have khat the same are true at the same at the same are true at the same at the same are true at the same	Dumped 6 sa ix cement. al description is nece 1 Servicing Peabody, K UNTY OF rter (mowledge of the and correct. So (Signature) th day of.	ssary, use BACK Inc. ansas Marion suppleyexxxx facts, stateme help me God. Peabody, Febru	of this sheet) 66866 Kansas ary	RE(STATE CORPORATION MAI CONSERV. Wich where or operator) ers herein contact 66866 (Address)	down. CEIVED RATION COMMISS R 2 1970 ATION DIVISION hita, Kansas of the above-desimed and the log

WELL LOG BUREAU - KANSAS GEOLOGICAL SOCIETY &

UNION NATIONAL BANK BLDG, WICHITA, KANSAS

nw ne se sw Location.

430' EL 990' SL of ST

Sec. 3 T. 21

County. Rice

Casing Record.

Farm. Rainey

No. 1

10" Farm. Rainey
20" 43 81" 2668 Company. Rogers and Wilhelm.
154"82 65/6"3122 Contr.
124"535 53/16"3383 Comm. 8-3-32 Comp.:
Total Depth. 3416 Shot Quarts Between.
Correspondence Regarding This Well Should Be Referred Tc.

Comp. 11-23-32

Elevation.

Pigures Indicate Bottom of Formations. Date Issued. 12-24-32

Initial Production. Pump 150 B.

Formation	Pepth Formation	Depth
sand water@60	'90 lime	3060
shale	110 lime ex	3125
red rock 2 EW 110	305 shale STATE OF E	3128
shale	110 lime state correctly shale lime correctly shale correctly shale lime shale wichita from one lime lime lime shale lime lime lime lime lime lime lime li	3155
	115 shale Wichita NON DIVISION. 126 shale conservation of 1970 to 197	3175
salt	840 lime CONSEST COM	3185
salt	115 shale Willy Olo Million	3195
shale	1125 lime Vichita ON 500 STON	3198
red rock	1175 no log 19/0/1/8/2	3215
lime	1260 shale	3235
shale	1295 red rock	3265 ·
sand	1300 shale blue	3285
shale	1340' shale	3295
lime	•	3300
lime	1395 lime 1445 shale	3350 ·
lime and shale	1450. 3350 squals 3335 SIM.	0000
red rock	1455 red rock 3335-	3385
shale	1515 chat	3412
shale and lime shells	1575 pay 3408-12	OTIL
shale	1625 3000 fluit	
shale	1645 chat	3414
lime	184C chat	3416
shale red ro <i>c</i> k	185 Swab 15 #il and 15 wtr per hr	
•	1875 Swab 15 611 and 15 well per in	TOT TO HITE
lime shale	1925	
lime	1955 pump 40 bbls oil and 210 wtr	•
shale	2016 Plugged back to 3410	,
lime	2025 150 oil and 300 wtr pump.	
shale	2035.	•
	2053	1 1
lime shale	2100 8 UR 2795 UR 2800	•
lime	2115 6 CR \$195	
shale	2165	
lime	281	•
lime	2250	
shale	2310	1.
lime 15 BW 2365	260 £	. •
lime	2640	***
sand	2650	
lime	2673	
sand	2725	`.
HFW 2695		•
lime	2740	
shale	2785	
lime	2860	
lime	3025	
shale	3040	
ar agreege ▼	, , , , , , , , , , , , , , , , , , , ,	•