the state of STATE OF KANSAS STATE CORPORATION COMMISSION -200 Colorado Derby Bullding Wichita, Kansas 67202


WELL PLUGGING RECORD K.A.R.-82-3-117

PI	NUMBER_	15-149-01388-0000
		•

WELL NUMBER	_

Michila Vanzaz o	11202	_							
est of		TYPE OR PRINT TICE:Fill out completely d return to Cons. Div.				SPOT LOCATION NE SW NW SEC.32 TWP.23srge.15w(E)or(A)			
	NO1 and								
	• 01	c c							
LEASE OPERATOR Kel	so Casing bought f	/ Cities	s Serv	vice Oil	& Gas			_	
ADDRESS Box					CO	UNTY	Pawnee		
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	<u> </u>				Da	te Well Co	ompleted		
PHONE # (316 938-	2457 OPERATO	ORS LICE	NSE N	060.	<u>50</u> PI	ugging Cor	mmenced <u>1/</u>	15/86	
Character of Well_ (Oll, Gas, D&A, SW	/D, Input, Water So	upply We	11)		. P1	ugging Cor	mplèted <u>1/2</u>	1/86	
Did you notify the	KCC/KDHE Joint D	istrict	Offic	e prior t	o plugging	this well	Yes		
Which KCC/KDHE Jol	nt Office did you	notify?			<u> </u>	Dodge	City		
Is ACO-1 filed?	lf not,	is well	log	attached?					
Producing formatio	n	Dept	h to	top	bot	tom	T.D. <u>_392</u> ?	<u>, , , , , , , , , , , , , , , , , , , </u>	
Show depth and thi	ckness of all wate	er, oll	and g	as format	ions.			;	
OIL, GAS OR WATER	RECORDS				CASING R	ECORD			
Formation	Content	From	To	Size	Put In	Pulled	dout		
				8 5/8	392'	none			
				<u>5½''</u>	39031	2490			
Pull 60/4 Plug	placed and the met t or other plugs of feet to feet of ged bottom with si ed 79 joints of p 0 poz 6% gel. gging complete.	thod or overe use each set and to 3 ipe. Pl	method star	ds used 1 te, the c & 5 sacks well wit	n introducharacter of cement.	Ing it inf f same and Shot pipe 20 gel, s form.)	at 2490'. & 200 sacks		
Name of Plugging C Address Box	ontractor Kel 347, Chase, Ks.	so Casin 67524	<u>g. Pul</u>	ling		_License N		6050	
STATE OF Kans	sas Co	DUNTY OF	R	ice		,ss.			
	arrell Kelso				oyee of op				
(operator) of above the log of the above correct, so help m	f the facts, state ve-described well	ements,	and ma	atters he t the sam	rein conta	Ined and	it .	_	
				(Addr	, , .		e, Ks. 67	 524_	
	SUBSCRIB	ED AND S	WORN				February ,		

My Commission expires:



FEB 1 8 1986 2-18-86

D Form CP-4. Revised 01-84

CONSERVATION DIVISION

PLUGGING PROCEDURE FOR BENSON UNIT WELLS

15-145-01388-0006

- Dump sand of sufficient, quantity to cover perforations fifty (50) feet.
- Place five (5) sacks cement on sand using dump bailer prior to pulling pipe.
- 3. Run freepoint. Shoot off 5-1/2" casing and pull same.
- 4. Pump down 8-5/8" surface pipe as follows:
 - A. 3 sacks hulls
 - B. 50 sacks cement
 - C. 10 sacks gel
 - D. 30-50 sacks cement
 - E. 8 sacks gel
 - F. l sack hulls
 - G. 8-5/8" wiper plug
 - H. Appropriate volume of cement to fill surface pipe above plug (± 120 sacks)
- 5. Cut off 8-5/8" three (3) feet below ground level and verify surface casing is filled with cement.

The above procedure recommended by Paul Luthi of the Dodge City, Kansas Corporation Commission Office.

RECEIVED STATE CORPORATION COMMISSION

NOV 1 4 1535

CONSERVATION DIVISION Wichita, Kansas